

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate  
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

**INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD****PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1812/011
Policy No:	5094821249-01	Date of Loss:	24/12/2018
Vehicle Reg. No.:	<b>GBE3543E</b>	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHD7121Y
Any Injuries?	no	Contact No:	
Insured/Claimant:	HOPE TECHNIK PTE LTD	Driver:	MUHAMMAD NURAZLI BIN JUMA EN

Make/Model:	Nissan, NV200 - VSKYBAM20U	Vehicle Reg. Date:	02 Nov 2015
Vehicle Colour:	BLACK	Engine Number:	HR16039239D
Chassis No:	VM20082765	Odometer:	
Total Loss?	<b>NO</b>	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR  
Remarks:  
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

**COST OF CLAIMS**

	Amount
Parts	3,677.15
Miscellaneous Items	60.00
Labour	610.00
Paintwork Labour	840.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>5,187.15</b>
<b>GST 7.00%(S\$):</b>	<b>363.10</b>
<b>Nett Amount(S\$):</b>	<b>5,550.25</b>

This claim is handled by: Sky Toh T C

**REPAIR DETAILS****Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	0.00	650.40	-30.00	455.28
2	1	REAR TAILLAMP RH	0.00	258.70	-10.00	232.83
3	1	REAR FENDER RH	0.00	2,997.20	-30.00	2,098.04
4	1	REAR WHEEL HUB RH	0.00	380.00	-10.00	342.00
5	1	REAR WHEEL HUB BEARING RH	0.00	240.00	-10.00	216.00
6	1	REAR SHOCK ABSORBER RH	0.00	370.00	-10.00	333.00

Total Parts (\$\$) 3,677.15

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR WHEEL HUB COVER RH	0.00	60.00	0.00	60.00
Sub Total (\$\$)						<u>60.00</u>

**Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	80.00
3	1	To Dismantle and Refit Rear Undercarriage.	220.00	220.00	0.00	220.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	280.00	280.00	0.00	280.00

Gross Labour Cost (\$\$) 610.00

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	0.00	800.00

Gross Labour Cost (\$\$) 840.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

< END OF ESTIMATES >

Not Affected  
 taken photo. After repair  
 2/12/19 3/27