

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

LKK

67418434

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 02/01/2019
TP Vehicle No. : SKD-2112-X
To : EQ INSURANCE COMPANY LTD
Attn : Motor Claim Department

@ 1200Hrs
02/01/19

Owner : RUI SHAN ENGINEERING & TRADING PTE. LTD.
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5070219710-03
Vehicle No. : GBD-3975-Y
Make & Model : NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T

not Adm
Lkb

Accident Date: 22/12/2018

1/58
3/1/19

Take photo of the reg-

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Nett Item

1	TAILGATE	scr/p/k \$1,699.70	X
1	TAILGATE HINGE RH	11 \$95.70	X
1	TAILGATE HINGE LH	11 \$95.70	X
1	TAILGATE LOCK CATCH RH	11 \$210.40	X
1	TAILGATE LOCK CATCH LH	11 \$210.40	X
2	TAILGATE STOPPER RH	11 \$30.00	—
2	TAILGATE STOPPER LH	11 \$30.00	X
1	RH TAILLAMP	11 \$280.60	X
1	RH TAILLAMP PANEL	11 \$95.60	X
1	RH TAILLAMP BRACKET	11 \$102.60	X
1	RH TAIL DOOR	11 \$3,600.60	X
2	RH TAIL DOOR HINGE BOTTOM	11 \$190.60	X
1	RH REAR FENDER	11 \$185.80	✓
Sub Total		\$6,827.70	
Discount 10% on Parts		(\$682.77)	
		\$6,144.93	

Special Nett

1	RH REAR FENDER MUFLAP	11 \$150.00	✓
1	EXHAUST MUFFLER	11 \$855.60	X
1	RH REAR TYRE	11 \$350.00	X
1	RH REAR WHEEL RIM	11 \$450.00	X
Sub Total		\$1,805.60	

Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$2,500.00	500
TO SPRAY PAINT ON AFFECTED AREAS	\$2,500.00	400
TO CHECK LIGHTING AND FOCUS TAILLAMP	\$150.00	20
TO TRANSFER & REFIX LH SLIDING DOOR FIXTURE & FITTING	11 \$250.00	X

Date : 02/01/2019
TP Vehicle No. : SKD-2112-X
To : **EQ INSURANCE COMPANY LTD**
Attn : **Motor Claim Department**

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : RUI SHAN ENGINEERING & TRADING PTE. LTD.
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5070219710-03
Vehicle No. : GBD-3975-Y
Make & Model : NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T

Accident Date: 22/12/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO TRANSFER & INSTALL TAILGATE COMPOENTS	11 \$250.00	X
	TO TRANSFER REAR WINDSCREEN FITTING	11 \$150.00	X
	TO REFIX RH SLIDING DOOR GLASS	11 \$150.00	X
	TO APPLY TUFF KOTE.	\$150.00	30
	TO WHEEL ALIGNMENT AND TYRE BALANCING	11 \$200.00	X
	Sub Total	\$6,300.00	

Sub Total \$14,250.53
GST 7% \$997.54
Total \$15,248.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: