

INSURANCE CASE OWNER:

CC 6/LPC1900 0026, K h2bhz

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

V11/19

Date / Time:

21/11/19

Registered in Merimen:

Pre-assign / CCU / FTE

GY 9097Y



Insured Vehicle No.:

Claim No.:

Name of Insured:

KOH BROTHERS BUILDING & CONSTRUCTION

Policy No.:

2116/20010233

Insured Tel No.:

HP:

Make / Model:

MSSKIN

Excess Sec II :\$5

D.O.A.:

Place of Accident:

PTE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SHANKU UMIN

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L) YES / NO

Insured Liability:

%

Final ? Yes / No

SLV 4041A

INSRS:
WSP:
Tel:
Liability:
RMKS:

MBM

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

8/1/19

21/11/19

21/11/19

21/11/19

21/12/19

12/12/19

20/12/19

4041A-Y

4041A-Y

EMAIL LIABILITY CLERK
 PTE REMOVED. OLD RATE-ENDED TP.
 PINAUGED
 TP LOG IN BY EMAIL

TYPE REPORT FOR WARRANT APPROVAL
 REPORT DONE

BOOK WARRANT TO LPC.

LPC APPROVED WARRANT
 SEND ACCEPTANCE EMAIL TO TP
 RECEIVED BY. ALL BOOK IF ORPTE.
 TO CLOSE.

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 02/01/19

Sent By: b3

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L9

\$5 4,480.00

(6 days) Reduction:

57

%

Email:

Call:

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email:

Call:

Final Liability:

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/loss)

\$5 4,761.50

Loss of Rental (LOR) (w/loss)

\$5 1,505.00 (10 days) X \$150

Loss of Use (LOU):

\$5 - (\$ x days)

Loss of Income (LOI):

\$5 - (\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GLA/TA Search

\$5 2.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

Total:

\$5 6,308.50

Global Sum \$5:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format

3) Survey fee

\$4480.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

\$5 6,308.50

Name 1:

MBM WHEELPOWER PTE LTD

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

-

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

-

REF: **HPC**condition re
calculation
slip sheet

ASSIGNMENT

From Date: **02/01/2019**Veh No: **SLV 4941A** Tr Regn: **12 17**

Estimated Cost:

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /OD ☒ TP ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To inspect Vehicle No:

SLV 4941A

Make:

Toy**C11R**

C.C.

1797

at Workshop m/s

MBM Wheelpower

Colour:

M. Red

A/C:

Insured / Std / NI / NA

at

1608n Ming Drive # 06-03

Sp Reading:

77856

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

8YX10**2025920**

Policy No:

C/No:

Claims No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Danny @ 93288668Modi: ☐ Nil / ☐ S/Rim / ☒ STD / ☐ Right or


Tyre Size:

F:

225/50R18

R:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

/ Hankook

IDAC Accident Rpt:

Consistent? Yes or No

Front

9

mm

Rear

R/Bal.

9

mm

GIA / PR. Seen:

Consistent? Yes or No

L/Bal.

9

mm

L/Bal.

9

mm

Est. Repairs:

6 days

Res: Yes or No

D.O.A. **28/12/18**

D.O.I.

2/1/19

Lump Sum:

1-R1 %

3 Val: Yes or No

Survey held at

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/1 File pass to Corbin**Lo \$4,450.00**
(Net: \$5,901.25/57%)

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

If

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) \$ + RD \$

) Photos

) Others

) TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19000036/Kjb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 02-01-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 9097Y	Veh. Inspected	SLV 4941A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/12/2018	Inspection Date	02/01/2019	
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19000036/Kjb3

Date: 03.01.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLV4941A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.01.2019 at the premises of M/s MBM Wheelpower Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	10,351.25
Revised Estimate Amount	: S\$	4,389.50
"Check" Items Amount	: S\$	4,416.75
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5-6 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SLV4941A		
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	TOYOTA		
Vehicle Model:	C-HR HYBRID 1.8G CVT		
Chassis No.:	ZYX102025920		
Propellant:	Petrol-Electric		
Engine No.:	2ZR8070597		
Motor No.:	20A317221971		
Engine Capacity:	1797 cc		
Power Rating:	53.0 kW		
Maximum Power Output:	90.0 kW (120 bhp)		
Maximum Laden Weight:	1715 kg		
Unladen Weight:	1440 kg		
Year Of Manufacture:	2017		
Original Registration Date:	29 Dec 2017		
Lifespan Expiry Date:	-		
COE Category:	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium:	\$53,711.00		
COE Expiry Date:	28 Dec 2027		
Road Tax Expiry Date:	28 Dec 2019		
PARF Eligibility Expiry Date:	28 Dec 2027		
Inspection Due Date:	28 Dec 2020		
Intended Transfer Date:	29 Dec 2018		
CO2 Emission:	88.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$30,000.00		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Kj

MBM WHEELPOWER PTE LTD

Your Ref: GY9097Y
Our Ref: SLV4941A

To: LONPAC

CC

Fax

Not withhows
1.B.1
Assembly 04 paint
5-6 days

Date: 31/12/2018
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: TOYOTA C-HR HYBRID 1.8 G
Chassis No.: ZYX102025920
Engine No.: 2ZR8070597
Year of Make: 2017
Accident Date: 1-October 2018
26 Dec

ESTIMATE FOR VEHICLE NO.: SLV4941A

DESCRIPTION

REAR WINDSCREEN MOULDING
TAIL GATE
TAIL GATE WEATHERSTRIP
TAIL GATE OUTER TOP GARNISH
TAIL GATE "TOYOTA" LOGO
TAIL GATE "C-HR" EMBLEM
TAIL GATE "HYBRID" LOGO
TAIL GATE LAMP RH
TAIL GATE LAMP LH
REAR BUMPER
REAR BUMPER CLIPS
REAR BUMPER LOWER COVER
REAR BUMPER RH TOW COVER
REAR BUMPER RH REFLECTOR
REAR BUMPER LH REFLECTOR
REVERSE SENSOR @ \$ 480 EACH
END PANEL
END PANEL TOP GARNISH
END PANEL TOP GARNISH CLIPS
TEMPERATURE SENSOR BRACKET
REAR REINFORCEMENT

QTY

List Price

1	\$	<i>Na</i>	155.00	<i>✓</i>
1	\$	<i>B</i>	1,549.00	<i>✓</i>
1	\$	<i>Sn</i>	393.00	<i>X</i>
1	\$	<i>Sn</i>	1,034.00	<i>X</i>
1	\$	<i>na</i>	76.00	<i>X</i>
1	\$	<i>na</i>	58.00	<i>X</i>
1	\$	<i>na</i>	89.00	<i>X</i>
1	\$	<i>Sn</i>	595.00	<i>X</i>
1	\$	<i>Sn</i>	595.00	<i>X</i>
1	\$	<i>B</i>	1,030.00	<i>✓</i>
10	\$	<i>na</i>	60.00	<i>✓</i>
1	\$	<i>B</i>	475.00	<i>✓</i>
1	\$	<i>na</i>	75.00	<i>✓</i>
1	\$	<i>Sn</i>	85.00	<i>X</i>
1	\$	<i>Sn</i>	85.00	<i>X</i>
21	\$	<i>480 Sn</i>	960.00	<i>4</i>
1	\$	<i>B</i>	802.00	<i>2</i>
1	\$	<i>Sn</i>	295.00	<i>X</i>
10	\$	<i>na</i>	60.00	<i>X</i>
1	\$	<i>na</i>	162.00	<i>X</i>
1	\$	<i>B</i>	502.00	<i>✓</i>

Total: \$ 9,135.00

LESS 25% \$ (2,283.75)

Parts Total: \$ 6,851.25



SPECIAL NETT

BODY SEALANT	1	\$	nn 80.00 X
WINDSCREEN SEALANT	1	\$	40sn 80.00
ANTI-RUST COATING	1	\$	nn 250.00 X
NUMBER PLATE & HOLDER	1	\$	95sn 50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	800 1,200.00 600
TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW TAIL GATE / FACILITATE REPAIR	\$	601 80.00
TO DISMANTLE AND RE-FIT REAR WINDSCREEN	\$	1201 150.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	601 100.00
TO RE-ALIGN EXHAUST PIPE	\$	150.00 X
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	nn 80.00 X
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	201 80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	800 1,200.00

Total:	\$	10,351.25
7% GST:	\$	724.59
Grand Total:	\$	11,075.84

3546
88
1260
5791
44501
L/S - 44501-

MBM WHEELPOWER PTE LTD

mbm wheelpower

Your Ref: GY9097Y
Our Ref: SLV4941A

To: LONPAC

CC

Fax

Not with him
1.B.1
Permy B4 paint
5-6 days

Date: 31/12/2018
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: TOYOTA C-HR HYBRID 1.8 G
Chassis No.: ZYX102025920
Engine No.: 2ZR8070597
Year of Make: 2017
Accident Date: 1 October 2018

ESTIMATE FOR VEHICLE NO. : SLV4941A

DESCRIPTION

REAR WINDSCREEN MOULDING
TAIL GATE
TAIL GATE WEATHERSTRIP
TAIL GATE OUTER TOP GARNISH
TAIL GATE "TOYOTA" LOGO
TAIL GATE "C-HR" EMBLEM
TAIL GATE "HYBRID" LOGO
TAIL GATE LAMP RH
TAIL GATE LAMP LH
REAR BUMPER
REAR BUMPER CLIPS
REAR BUMPER LOWER COVER
REAR BUMPER RH TOW COVER
REAR BUMPER RH REFLECTOR
REAR BUMPER LH REFLECTOR
REVERSE SENSOR @ \$ 480 EACH
END PANEL
END PANEL TOP GARNISH
END PANEL TOP GARNISH CLIPS
TEMPERATURE SENSOR BRACKET
REAR REINFORCEMENT

QTY

1
1
1
1
1
1
1
1
1
1
1
10
1
1
1
1
2 / 1
1
1
10
1
1

List Price

M 155.00
B 1,549.00
393.00
1,034.00
76.00
58.00
89.00
595.00
595.00
B 1,030.00
M 60.00
B 475.00
M 75.00
85.00
85.00
S 960.00
802.00
295.00
60.00
162.00
B 502.00

Total: \$ 9,135.00

LESS 25% \$ (2,283.75)

Parts Total: \$ 6,851.25

SPECIAL NETT

BODY SEALANT	1	\$		80.00
WINDSCREEN SEALANT	1	\$	405n	80.00
ANTI-RUST COATING	1	\$		250.00
NUMBER PLATE & HOLDER	1	\$	201 455n	50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$		1,200.00
TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW TAIL GATE / FACILITATE REPAIR	\$	601	80.00
TO DISMANTLE AND RE-FIT REAR WINDSCREEN	\$	1201	150.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	601	100.00
TO RE-ALIGN EXHAUST PIPE	\$		150.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	201	80.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	201	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	8001	1,200.00

Total: \$ 10,351.25

7% GST: \$ 724.59

Grand Total: \$ 11,075.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

(62628888 / 64525333

Company Registration Number : 200204110W

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 31 December 2018 12:21 PM
To: Danny Ong ; MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: stephanie.lin@mbmwheelpower.com.sg
Subject: Our Ref: 18/18/19/VC/021272 RE: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018
Attachments: 20181231110029290.pdf

12:25pm @ 31/12/18
vehicle in
person @ Danny
agreed arrange on
21/01/2019

Without Prejudice

Dear Danny

Please liaise with LKK Auto Consultants Pte Ltd for survey and liability.

Dear Nivitha/Catherine

Please follow up.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Danny Ong [mailto:danny.ong@mbmwheelpower.com.sg]
Sent: Monday, 31 December, 2018 12:03 PM
To: MT_Claim_SG
Cc: stephanie.lin@mbmwheelpower.com.sg
Subject: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018

Dear All

Appreciate if you can advise us on the liability status first for the below loss and arrange a pre-survey.

Kindly refer to the attached GIA report & estimate.

Our Client's Vehicle Number:	SLV4941A
LONPAC Vehicle Number:	GY9097Y
Date/Time of Loss:	28/12/2018 1730hrs

Kindly arrange your surveyor to survey the vehicle at **160 Sin Ming Drive #06-03 Sin Ming**

Autocity
Singapore 575722

Please contact Danny 93288668 for the survey arrangement


Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 2 January 2019 5:03 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; assignments; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Our Ref: 18/18/19/VC/021272 RE: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018
Attachments: GY9097Y 281218.PDF

Hi Shu Pei

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 2 January, 2019 2:52 PM
To: ONG LI LI
Cc: MT_Claim_SG; assignments; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Our Ref: 18/18/19/VC/021272 RE: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 2 January 2019 11:51 AM
To: 'ONG LI LI' <llong@lonpac.com>; 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: Our Ref: 18/18/19/VC/021272 RE: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018

Dear Li Li,

Thank you for your email.

Dear Shu Pei,

Kindly assist.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Wednesday, 2 January, 2019 11:48 AM
To: Danny Ong <danny.ong@mbmwheelpower.com.sg>; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: stephanie.lin@mbmwheelpower.com.sg
Subject: RE: Our Ref: 18/18/19/VC/021272 RE: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018

Without Prejudice

Dear Danny

Please liaise with LKK Auto Consultants Pte Ltd.

Dear Catherine/Nivitha

Please handle urgently.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Danny Ong [<mailto:danny.ong@mbmwheelpower.com.sg>]
Sent: Wednesday, 2 January, 2019 11:35 AM

To: ONG LI LI; MT_Claim_SG; assignments@lkkauto.com; 'Admin-D (LKKAuto)'

Cc: stephanie.lin@mbmwheelpower.com.sg

Subject: RE: Our Ref: 18/18/19/VC/021272 RE: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018

Importance: High

Dear Ms Ong

Noted with thanks.

Kindly advise on the liability status urgently

Best regards,

Danny Ong | Claims Advisor



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: danny.ong@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

From: ONG LI LI <long@lonpac.com>

Sent: Monday, 31 December 2018 12:21 PM

To: Danny Ong <danny.ong@mbmwheelpower.com.sg>; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: stephanie.lin@mbmwheelpower.com.sg

Subject: Our Ref: 18/18/19/VC/021272 RE: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018

Without Prejudice

Dear Danny

Please liaise with LKK Auto Consultants Pte Ltd for survey and liability.

Dear Nivitha/Catherine

Please follow up.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Danny Ong [<mailto:danny.ong@mbmwheelpower.com.sg>]
Sent: Monday, 31 December, 2018 12:03 PM
To: MT_Claim_SG
Cc: stephanie.lin@mbmwheelpower.com.sg
Subject: Liability Status - Accident involving SLV4941A & GY9097Y (LONPAC) on 28/12/2018

Dear All

Appreciate if you can advise us on the liability status first for the below loss and arrange a pre-survey.

Kindly refer to the attached GIA report & estimate.

Our Client's Vehicle Number:	SLV4941A
LONPAC Vehicle Number:	GY9097Y
Date/Time of Loss:	28/12/2018 1730hrs

Kindly arrange your surveyor to survey the vehicle at **160 Sin Ming Drive #06-03 Sin Ming Autocity Singapore 575722**

Please contact Danny 93288668 for the survey arrangement

Best regards,

Danny Ong | Claims Advisor



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: danny.ong@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

This message has been scanned for viruses and dangerous content by
QUAPE SPAM Protection, and is believed to be clean.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19000036/Khb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 24-12-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 9097Y	Veh. Inspected	SLV 4941A	
Policy No.	Z/18/VC00/102233	Coverage (\$)	0.00	
Claim No.	18/18/19/VC/021272	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	31/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CHR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102025920	Colour	METALLIC RED	
Odometer	77856	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	HANKOOK	9 mm	
L/H Front Tyre	225/50 R18	HANKOOK	9 mm	
R/H Rear Tyre	225/50 R18	HANKOOK	9 mm	
L/H Rear Tyre	225/50 R18	HANKOOK	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2018	Inspection Date	02/01/2019	
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4941A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NECESSARY	155.00	155.00
1	TAIL GATE	BENT	1,549.00	1,549.00
1	TAIL GATE WEATHERSTRIP	SERVICEABLE	393.00	-
1	TAIL GATE OUTER TOP GARNISH	SERVICEABLE	1,034.00	-
1	TAIL GATE "TOYOTA" LOGO	NOT NECESSARY	76.00	-
1	TAIL GATE "C-HR" EMBLEM	NOT NECESSARY	58.00	-
1	TAIL GATE "HYBRID" LOGO	NOT NECESSARY	89.00	-
1	TAIL GATE LAMP RH	SERVICEABLE	595.00	-
1	TAIL GATE LAMP LH	SERVICEABLE	595.00	-
1	REAR BUMPER	BENT	1,030.00	1,030.00
10	REAR BUMPER CLIPS	NECESSARY	60.00	60.00
1	REAR BUMPER LOWER COVER	BENT	475.00	475.00
1	REAR BUMPER RH TOW COVER	MISSING	75.00	75.00
1	REAR BUMPER RH REFLECTOR	SERVICEABLE	85.00	-
1	REAR BUMPER LH REFLECTOR	SERVICEABLE	85.00	-
2	REVERSE SENSOR @\$480.00	SCRATCHED (1PC ONLY)	960.00	480.00
1	END PANEL	BENT	802.00	802.00
1	END PANEL TOP GARNISH	SERVICEABLE	295.00	-
10	END PANEL TOP GARNISH CLIPS	NOT NECESSARY	60.00	-
1	TEMPERATURE SENSOR BRACKET	TO REPAIR SEE LABOUR	162.00	-
1	REAR REINFORCEMENT	BENT	502.00	502.00
	LESS 25% DISCOUNT		-2,283.75	-1,282.00
			6,851.25	3,846.00
SPECIAL NETT ITEMS				
1	BODY SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	ANTI-RUST COATING (SN)	NOT NECESSARY	250.00	-
1	NUMBER PLATE & HOLDER (SN)	DENTED	50.00	45.00
			460.00	85.00

Report Ref No. CC4/LPC19000036/Khb3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF TEMPERATURE SENSOR BRACKET.		1,200.00	600.00
	TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW TAIL GATE / FACILITATE REPAIR.		80.00	60.00
	TO DISMANTLE AND RE-FIT REAR WINDSCREEN.		150.00	120.00
	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS.		100.00	60.00
	TO RE-ALIGN EXHAUST PIPE.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIRS.	NOT NECESSARY	80.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	20.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,200.00	800.00
			3,040.00	1,660.00
	GRAND TOTAL		10,351.25	5,591.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,450.00

Report Ref No. CC4/LPC19000036/Khb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.