

INSR2011
 INS CASE OWNER: Org 1/11 | CC/LPC1900 01/29, R1 263⁵² | LKK:
 IDAC:

Surveyor: Rasel | DOI: 3/1/2019 | Date/Time: 7/1/18
 Registered in Merimen:

Pre-assign / CCU / FTE
 Insured Vehicle No.: SLA 9772M | Claim No.: 18/18/19/1905/01/253
 Name of Insured: TAY STAN TUNE | Policy No.: 218VPU50A820
 Insured Tel No.: | HP: 94779977 | Make / Model: MITSUBISHI
 Excess Sec II :SS | D.O.A: 8/1/18 | Place of Accident: PUNJAGU V WNY
 Is driver the owner? (YES / NO) | Nature of Accident:
 If NO, Driver Name / Age: | OI GIA REPORT: YES / NO: | TP GIA REPORT: YES / NO:
 Driver Tel No.: | (V/L) YES / NO: | Insured Liability: % | Final ? Yes / No:

SLA 9772M → SLN 5470C → SLV 4487M
 INSR: | WSP: | Tel: | Liability: | RMKS: 01
 INSR: trans | WSP: | Tel: | Liability: | RMKS: TP
 INSR: | WSP: | Tel: | Liability: | RMKS:

Date/Time	STAGE	DATE / PIC
<u>7/1/19</u>	Non-Reporting ltr (1st):	
<u> </u>	Non-Reporting ltr (2nd):	
<u> </u>	Non-Reporting ltr (final):	
<u> </u>	Notification ltr (if non-pickup):	
<u> </u>	Call OI:	
<u> </u>	After call ltr to OI:	
<u> </u>	Documentation Check List:	Handler Typist
<u> </u>	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
<u> </u>	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
<u> </u>	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u> </u>	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u> </u>	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u> </u>	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u> </u>	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u> </u>	LTA / GIA:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u> </u>	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
<u> </u>	PIR:	<input type="checkbox"/> <input type="checkbox"/>
<u> </u>	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u> </u>	LOD:	<input type="checkbox"/> <input type="checkbox"/>
<u> </u>	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
<u> </u>	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
<u> </u>	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 7/1/2019 Sent By: LSP

FINALIZATION Date/Time: Confirm with: Confirm by:
 Repair Cost: SS (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 22/9/19 Confirm with: Jen
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28
 Repair Cost: (w/hy) SS 9557.55
 Loss of Rental (LOR): (w/hy) SS 856.00 (8 days) x \$100
 Loss of Use (LOU): SS - (5 x days)
 Loss of Income (LOI): SS - (5 x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: SS 2.00
 Medical: SS -
 Disbursement: SS - (e.g. Tow/Independent)
 Legal Cost: SS -
 Total: SS 10415.55 Global Sum SS: Email Call

FINAL PAYMENT Date/Time: Confirm with: Email Call
 Payee 1: SS 10415.55 Name 1: Trans Eurokars Pte Ltd
 Payee 2: (Strike if N.A.) SS Name 2:
 Payee 3: (Strike if N.A.) SS Name 3:

SLA 9772M - CS/LPC1900/01/29/01/253/01/18/18
SLN 5470C - X
3 car chain collision and OI is last vehicle
28 BOLA, 100%
LOD in vlm email
17/7/19 - ALC PASS TO TYPE MANDATE
2/10/19 - ALC PASS TO LSP TO CLOSE

If NO or B 28, Ass. Lia: 100%
3 car chain collision, TP is 2nd vehicle
OI is last vehicle
7/10/19
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: \$450

Janan

ASSIGNMENT

From: _____ Date: *03 01 2019*

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLN 5470C*

at Workshop m/s: *Trans Eureka*

of: *27A Tanjung Perindu*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: *Samuel*

(Policy Condition) *2:30 pm owner waiting*

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *8* days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: *SLN 5470C* Yr Regn: *2017 / MY*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: *MAZDA 3 I-SLCA* C.C: *1496*

Colour: *WHITE* A/C: Insured / Std / NI / NA

Sp. Reading: *42886* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *SM 6BN22A8H 0149003*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: order / Jammed / Leaked / Burnt or

Brake: order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/60R16*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. <i>6</i> mm	R/Bal. <i>6</i> mm
L/Bal. <i>6</i> mm	L/Bal. <i>6</i> mm
D.O.A. <i>23/12/18</i>	D.O.I. <i>03/01/19</i>

Survey held at: *Trans Eureka*

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>P/P - \$8932.29 (Red \$10276.95 (54%))</i>	

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech Invs (\$ _____)

Weekend (\$ _____)

Other: _____

TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19000039/fb3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 02-01-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 9372U	Veh. Inspected	SLN 5470C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/01/2019

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	23/12/2018	Inspection Date	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19000039/R1fb3

Date: 07.01.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLN5470C


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 03.01.2019 at the premises of M/s Trans Eurokars Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	<u>19,209.24</u>
Revised Estimate Amount	: S\$	<u>6,780.63</u>
"Check" Items Amount	: S\$	<u>2,520.16</u>
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 8 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



<p><i>Lonpac</i></p> <p>ATTN.: MOTOR CLAIMS</p> <p>FAX:</p>	<p>NAME: Mr Lau Aik Cheng</p> <p>ADDRESS: Blk 306b Punggol Place #09-25 Singapore 822306</p> <p>TEL: 97927303</p>	<p>WIP: 38885</p> <p>EXCESS:</p> <p>DATE: 28-Dec-18</p>
---	---	---

VEH NO:	SLN5470C	DATE IN:		CONTACT PERSON:	TOMMY/JESS
CHASSIS NO:	JM6BN22A8H0149003	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA3	DATE REG.:	8-May-17	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	Parts Description	QTY	REVISED	PRICES
1	FRONT BUMPER ? <i>FSU</i>	1		\$ 825.50
2	FRONT REINFORCEMENT ? <i>FSU</i>	1		\$ 478.80
3	CLIP, FRONT BUMPER <i>nn</i>	12		\$ 42.00
4	FASTENER, FRONT BUMPER <i>nn</i>	2		\$ 5.60
5	GROMMET, FRONT BUMPER <i>nn</i>	2		\$ 5.40
6	SEAL RUBBER, FRONT BUMPER <i>X nn</i>	2		\$ 4.40
7	GRILLE TOP <i>DC</i>	1		\$ 338.50
8	RIVET, GRILLE TOP <i>nn</i>	4		\$ 34.80
9	RIVET, GRILLE TOP <i>nn</i>	4		\$ 15.20
10	MASCOT, FRONT <i>X old damage nn</i>	1		\$ 58.50
11	BRACKET, MASCOT <i>X</i>	1		\$ 20.60
12	CHROME LHS <i>X</i>	1		\$ 182.30
13	CHROME RHS <i>X</i>	1		\$ 182.50
14	PROTECTOR LHS, CHROME <i>X</i>	1		\$ 19.50
15	PROTECTOR RHS, CHROME <i>X</i>	1		\$ 19.50
16	PROTECTOR LHS, NO.1 <i>X</i>	1		\$ 36.80
17	PROTECTOR RHS, NO.1 <i>X</i>	1		\$ 37.20
18	PROTECTOR LHS, NO.2 <i>X</i>	1		\$ 37.10
19	PROTECTOR RHS, NO.2 <i>X</i>	1		\$ 37.10
20	PROTECTOR LHS, NO.3 <i>X</i>	1		\$ 37.20
21	PROTECTOR RHS, NO.3 <i>X nn</i>	1		\$ 37.10
22	PROTECTOR CENTER, NO.1 <i>X</i>	1		\$ 67.60
23	PROTECTOR CENTER, NO.2 <i>X</i>	1		\$ 67.60
24	PROTECTOR CENTER, NO.3 <i>X</i>	1		\$ 66.30
25	FRONT GRILLE ? <i>X</i>	1		\$ 129.00
26	BRACKET LHS, FRONT GRILLE <i>X</i>	1		\$ 26.00
27	BRACKET RHS, FRONT GRILLE <i>X</i>	1		\$ 26.00
28	CLIP, FRONT GRILLE <i>X</i>	2		\$ 8.80
29	CLIP, FRONT GRILLE <i>X</i>	1		\$ 3.20
30	PIN LOCATOR, FRONT GRILLE <i>X</i>	2		\$ 5.40

31	GROMMET, FRONT GRILLE	X	2	MKD45-50-ES1	\$ 5.40
32	RIVET, FRONT GRILLE	X	4	MEA01-50-037	\$ 30.40
33	SEAL RUBBER, FRONT GRILLE	X	2	MB63C-50-2G2	\$ 5.20
34	BRACKET TOP, GRILLE	X	1	MB63B-50-717	\$ 90.80
35	HEADLAMP RHS	X	1	MBAAR-51-031H	\$ 3,598.60
36	RIVET, HEADLAMP	X	1	MB092-51-833	\$ 3.30
37	CLIP, HEADLAMP	X	2	MDR61-50-133	\$ 12.20
38	PLATE SET, FRONT REINFORCEMENT	?	1	MB63E-50-1C0A	\$ 67.00
39	FASTENER, PLATE SET	?	4	MGD7A-50-EA1	\$ 12.00
40	REAR BUMPER	DE-	1	MBPD8-50-221ABB	\$ 1,074.80
41	BRACKET CENTER	? X SU	1	MKD53-50-251	\$ 5.10
42	TOWING COVER LHS	* MIS-	1	MBHN1-50-EL1 BB	\$ 15.70
43	TOWING COVER RHS	cut-	1	MBHN1-50-EK1 BB	\$ 16.20
44	REFLECTOR RHS	?	1	MD350-51-5M0E	\$ 50.40
45	RETAINER, SENSOR	?	3	MKD47-67-UC5A64	\$ 51.90
46	SENSOR CENTER, ULTRASONIC	X	2	MGMK6-67-UC1 64	\$ 344.40
47	SENSOR SIDE, ULTRASONIC	X	1	MKD47-67-UC1 64	\$ 193.90
48	TAPE PROTECTOR, SENSOR	NE-	3	MGS1D-50-EM1A	\$ 24.30
49	REAR REINFORCEMENT	? X AN	1	MB45A-50-260	\$ 537.30
50	GROMMET, REAR BUMPER	NE-	4	MBHN1-50-0Z1A	\$ 10.00
51	RIVET, REAR BUMPER	NE-	4	MBBM4-50-355	\$ 16.80
52	GROMMET, REAR BUMPER	NE-	21	M9991-00-501	\$ 58.80
53	FASTENER, REAR BUMPER	NE-	4	MB45A-56-146A	\$ 11.20
54	CLIP, REAR BUMPER	NE-	2	MGJ21-50-049	\$ 6.40
55	GASKET LHS, BOOTLID	NE-	1	MB45A-51-318	\$ 20.90
56	GASKET RHS, BOOTLID	NE-	1	MB45A-51-3H8	\$ 20.90
57	GASKET LHS, TAILLAMP	NE-	1	MBHN1-51-163	\$ 20.90
58	GASKET RHS, TAILLAMP	NE-	1	MBHN1-51-153	\$ 20.90
59	ORNAMENT, MAZDA	NE-	1	MBHN1-51-721	\$ 53.40
60	MASCOT, REAR	NE-	1	MBHN1-51-730	\$ 74.40
61	ORNAMENT, SKYACTIVE	NE-	1	MBHN1-51-771	\$ 63.60
62	HOLDER, LICENSE PLATE	X SU	1	MBABD-50-170	\$ 71.00
63					
TOTAL PARTS					\$ 9,443.60
LESS 10%					\$ 944.36
TOTAL PARTS COST					\$ 8,499.24

Labour Description

1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 1,980.00
2	MZ-SP-SFRTO3	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP.	945	\$ 1,890.00
3	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 1,980.00

1650

1890

4	MZ-SP-SREARS	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	1260	\$ 2,520.00
5	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	12X	\$ 660.00
7	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. 24	NETT	\$ 70.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 30 100.00

TOTAL LABOUR	\$ -	\$ 10,710.00
TOTAL PARTS	\$ -	\$ 8,499.24
TOTAL	\$ -	\$ 19,209.24
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD 20070-90

Authorized Signature

Rasul
 Hp 90010068
 8 days
 P/P
 03/01/19 @ 1450
 Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



LONPAC INSURANCE BERHAD		NAME : Mr Lau Aik Cheng	WIP : 38885
ATTN. : MOTOR CLAIMS		ADDRESS : Blk 306b Punggol Place #09-25 Singapore 822306	EXCESS :
FAX :		TEL : 97927303	DATE: 28-Dec-18
VEH NO :	SLN5470C	DATE IN :	CONTACT PERSON : TOMMY/JESS
CHASSIS NO :	JM6BN22A8H0149003	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.: 8-May-17	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	FRONT BUMPER MB63B-50-031BBB		\$ 825.50
2	1	FRONT REINFORCEMENT MB61K-50-070A		\$ 478.80
3	12	CLIP, FRONT BUMPER MC274-50-133	\$ 42.00	\$ 42.00
4	2	FASTENER, FRONT BUMPER MB45A-56-146A	\$ 5.60	\$ 5.60
5	2	GROMMET, FRONT BUMPER MGHP9-50-025	\$ 5.40	\$ 5.40
6	2	SEAL RUBBER, FRONT BUMPER MB63B-50-2G2		\$ 4.40
7	1	GRILLE TOP MB63B-50-033A64	\$ 338.50	\$ 338.50
8	4	RIVET, GRILLE TOP MTK21-50-355	\$ 34.80	\$ 34.80
9	4	RIVET, GRILLE TOP MS51S-51-833	\$ 15.20	\$ 15.20
10	1	MASCOT, FRONT MD10J-51-730		\$ 58.50
11	1	BRACKET, MASCOT MB63B-50-716		\$ 20.60
12	1	CHROME LHS MB63B-50-7K1A		\$ 182.30
13	1	CHROME RHS MB63B-50-7J1A		\$ 182.50
14	1	PROTECTOR LHS, CHROME MB63E-50-B51B		\$ 19.50
15	1	PROTECTOR RHS, CHROME MB63E-50-B41B		\$ 19.50
16	1	PROTECTOR LHS, NO.1 MB63B-50-B51		\$ 36.80
17	1	PROTECTOR RHS, NO.1 MB63B-50-B41		\$ 37.20
18	1	PROTECTOR LHS, NO.2 MB63C-50-B51		\$ 37.10
19	1	PROTECTOR RHS, NO.2 MB63C-50-B41		\$ 37.10
20	1	PROTECTOR LHS, NO.3 MB63D-50-B51		\$ 37.20
21	1	PROTECTOR RHS, NO.3 MB63D-50-B41		\$ 37.10
22	1	PROTECTOR CENTER, NO.1 MB63B-50-B31		\$ 67.60
23	1	PROTECTOR CENTER, NO.2 MB63C-50-B31		\$ 67.60
24	1	PROTECTOR CENTER, NO.3 MB63D-50-B31		\$ 66.30
25	1	FRONT GRILLE MB63C-50-712B		\$ 129.00
26	1	BRACKET LHS, FRONT GRILLE MB63B-50-163		\$ 26.00
27	1	BRACKET RHS, FRONT GRILLE MB63B-50-153		\$ 26.00
28	2	CLIP, FRONT GRILLE MG46L-50-EB1		\$ 8.80
29	1	CLIP, FRONT GRILLE MGHP9-50-EB1A		\$ 3.20
30	2	PIN LOCATOR, FRONT GRILLE MKD45-50-1K5A		\$ 5.40
31	2	GROMMET, FRONT GRILLE MKD45-50-E51		\$ 5.40

4	MZ-SP-SREARS	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOTLID.	\$ 1,890.00	\$ 2,520.00
5	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		\$ 660.00
7	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 6,315.00 \$ 10,710.00
			TOTAL PARTS	\$ 2,617.29 \$ 9,360.90
			TOTAL	\$ 8,932.29 \$ 20,070.90
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 8,932.29
			GST 7%	\$ 625.26 \$ -
			GRAND TOTAL	\$ 9,557.55 \$ -

REMARKS:

10 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 31 December 2018 8:48 AM
To: ronald.yap@eurokars.com.sg; tommywoon@eurokars.com.sg;
assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg;
catherinechua@eurokars.com.sg
Subject: Our Ref: 18/18/19/VP05/021253 RE: ARRANGE FOR SURVEY / YOUR REF:
SLA9372U / OUR REF: SLN5470C
Attachments: 1169_181229144456_001.pdf

9.22am @ 31/12/18
person @ Ronald
UNI

Without Prejudice


Dear Ronald

Please liaise with LKK Auto Consultants Pte Ltd for survey and liability.

Dear Catherine/Nivitha

Please arrange.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]
Sent: Saturday, 29 December, 2018 2:37 PM
To: ONG LI LI; tommywoon@eurokars.com.sg
Cc: jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg; catherinechua@eurokars.com.sg
Subject: ARRANGE FOR SURVEY / YOUR REF: SLA9372U / OUR REF: SLN5470C

Dear Li Li,

As per subject / attached, let us have your appointed surveyor for arrangements.

Thank You,

Ronald Yap
Insurance Claims

Trans Eurokars Pte Ltd
5 Ubi Close, Singapore 408605
T: 6395 8899 H: 9127 7928
ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <transeurokars@eurokars.com.sg>

Sent: 29 December 2018 14:45

To: Ronald Yap <ronald.yap@eurokars.com.sg>

Subject: Attached Image

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Wednesday, 9 January 2019 3:29 PM
To: 'jess.francis@eurokars.com.sg'
Cc: 'ronald.yap@eurokars.com.sg'; samuel.ng@eurokars.com.sg;
'catherinechua@eurokars.com.sg'
Subject: RE: ARRANGE FOR SURVEY / YOUR REF: SLA9372U / OUR REF: SLN5470C
Importance: High

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC4/LPC19000039/R1fb3
Your Ref: SLN 5470C

Dear Sir/Madam,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

LAU Aik CHENG (Owner's Name)
BLK 306B Punggol Place (Address)
09-25
S(822306)

Longpac Insurance Bhd (Ins Co)
300 Beach Road (Address)
#17-04/07 The Concourse
S(199555)

Attn : Motor Claims Dept
Your ref : SLA93724
Our ref : SLW5470C
Date : 28/12/2018

Dear Sirs,

RE : Accident involving vehicle nos. SLW 5470C and SLA93724 on 23/12/18.

I refer to the above accident.

My car been repaired by Trans Eurokars Pte Ltd. As they are submitting a 3rd Party claim against Longpac Insurance Bhd on behalf, please pay to **Trans Eurokars Pte Ltd** for the whole claim due to them.


Yours faithfully,



(LAU Aik CHENG)

I/C No : 57933255J

Cc. Trans Eurokars Pte Ltd
Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648



Without Prejudice
to Injury Claim

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
repairers my/our vehicle No: SLN5470C which has been
repaired to my satisfaction and I/we admit that the payment for such
repairs by Trans Eurokars Pte Ltd is in full and final discharge of my claim
under policy number: _____ in respect of damage
caused to the said vehicle as a result of an accident that occurred on
23/12/2018 at near cross junction @ Punggol way & Punggol field



Witnessed by Repairers



1/02/19

Date



Signature by Insured

1/02/19

Date



Corporate Head Office

Trans Eurokars Pte Ltd, Eurokars Centre, 12 Sengol Kadut Ave Singapore 729848
Tel: 6303 3003 Fax: 6309 3003 BBN 199103859N

Showroom & Service Centre

23 Leng Kee Road Singapore 160006
Sales Hotline : 6603 6118 Service Hotline : 6603 6128
Sales Fax : 6476 7079 Service Fax : 6476 7417

5 Ubi Close Singapore 408605
Sales Hotline : 6395 8888 Service Hotline : 6395 8899
Sales Fax : 6646 1700 Service Fax : 6744 9402

Handwritten notes and stamps:
2018-2019
2017-2018

LETTER OF AUTHORIZATION

To: Name: Trans Eurokars Pte Ltd.
From: Name: LAW AIK CHENG
Address: _____

In the matter of an accident involving motor vehicles SLN5470C & SLA372W
ON 23/12/18

I/We LAW AIK CHENG the owner of vehicle registration no: SLN 5470C
hereby authorize you to commence repairs to my above-mentioned vehicle.

I/We confirm that you are hereby authorized to handle the repair and /or to negotiate and settle any claims relating to the above accident which I /we may have against other third party /parties or insurers and /or to instruct lawyer on my /our behalf to facilitate the third party claim for me /us.

You are hereby authorized as my attorney to execute and /or sign any documents /discharge vouchers /discharge agreement regarding my /our claim for my convenience.

I confirm that in the event of an unsuccessful claim against the negligent party and /or my own insurer for the damages caused to my vehicle, I agree to pay for all repair cost and /or any incidental expenses incurred by you.

Dated the _____ day of _____ 20_____

LAW AIK CHENG



Owner (name /signature)

NRIC No. 57933255J



Witness (name /signature)

NRIC No. _____



Sia Le

Date: 25th September 2019

**c/o LKK AUTO CONSULTANTS PTE LTD
LONPAC INSURANCE BHD**

300 Beach Road

#17-04/07

The Concourse

Singapore 199555

Attn : Motor Claims Department

Claim No : **18/18/19/VP05/021253**

Our Ref : **SLN5470C**

RE: Accident involving SLN5470C & SLA9372U on 23/12/2018

Enclosed is the duly signed Discharge voucher for your perusal.

Please pay **Trans Eurokars Pte Ltd** the sum of **\$10,415.55**
as soon as possible and mail your cheque to
12 Sungei Kadut Avenue Singapore 729648.

Yours faithfully,

Stephanie Loke
Manager-Service & Development
DID: 63310686
FAX: 63310690
email: stephanie.loke@eurokars.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19000039/R1db3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 03-10-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLA 9372U	Veh. Inspected	SLN 5470C
Policy No.	Z18VP05017830	Coverage (\$)	0.00
Claim No.	18/18/19/VP05/021253	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	31/12/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 1.5 L (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0149003	Colour	WHITE
Odometer	42886	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60R16	TOYO	6 mm
L/H Front Tyre	205/60R16	TOYO	6 mm
R/H Rear Tyre	205/60R16	TOYO	6 mm
L/H Rear Tyre	205/60R16	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/12/2018	Inspection Date	03/01/2019
Survey held at	27A TANJONG PENJURU		
Repairer	TRANS EUROKARS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5470C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	SERVICEABLE	825.50	-
1	FRONT REINFORCEMENT	SERVICEABLE	478.80	-
12	CLIP, FRONT BUMPER	NECESSARY	42.00	42.00
2	FASTENER, FRONT BUMPER	NECESSARY	5.60	5.60
2	GROMMET, FRONT BUMPER	NECESSARY	5.40	5.40
2	SEAL RUBBER, FRONT BUMPER	NOT NECESSARY	4.40	-
1	GRILLE TOP	DEFORMED	338.50	338.50
4	RIVET, GRILLE TOP	NECESSARY	34.80	34.80
4	RIVET, GRILLE TOP	NECESSARY	15.20	15.20
1	MASCOT, FRONT (OLD DAMAGE)	NOT NECESSARY	58.50	-
1	BRACKET, MASCOT	NOT NECESSARY	20.60	-
1	CHROME LHS	NOT NECESSARY	182.30	-
1	CHROME RHS	NOT NECESSARY	182.50	-
1	PROTECTOR LHS, CHROME	NOT NECESSARY	19.50	-
1	PROTECTOR RHS, CHROME	NOT NECESSARY	19.50	-
1	PROTECTOR LHS, NO.1	NOT NECESSARY	36.80	-
1	PROTECTOR RHS, NO.1	NOT NECESSARY	37.20	-
1	PROTECTOR LHS, NO.2	NOT NECESSARY	37.10	-
1	PROTECTOR RHS, NO.2	NOT NECESSARY	37.10	-
1	PROTECTOR LHS, NO.3	NOT NECESSARY	37.20	-
1	PROTECTOR RHS, NO.3	NOT NECESSARY	37.10	-
1	PROTECTOR CENTER, NO.1	NOT NECESSARY	67.60	-
1	PROTECTOR CENTER, NO.2	NOT NECESSARY	67.60	-
1	PROTECTOR CENTER, NO.3	NOT NECESSARY	66.30	-
1	FRONT GRILLE	NOT NECESSARY	129.00	-
1	BRACKET LHS, FRONT GRILLE	NOT NECESSARY	26.00	-
1	BRACKET RHS, FRONT GRILLE	NOT NECESSARY	26.00	-
2	CLIP, FRONT GRILLE	NOT NECESSARY	8.80	-
1	CLIP, FRONT GRILLE	NOT NECESSARY	3.20	-
2	PIN LOCATOR, FRONT GRILLE	NOT NECESSARY	5.40	-
2	GROMMET, FRONT GRILLE	NOT NECESSARY	5.40	-

Report Ref No. CC4/LPC19000039/R1db3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	RIVET, FRONT GRILLE	NOT NECESSARY	30.40	-
2	SEAL RUBBER, FRONT GRILLE	NOT NECESSARY	5.20	-
1	BRACKET TOP, GRILLE	NOT NECESSARY	90.80	-
1	HEADLAMP RHS	NOT NECESSARY	3,598.60	-
1	RIVET, HEADLAMP	NOT NECESSARY	3.30	-
2	CLIP, HEADLAMP	NOT NECESSARY	12.20	-
1	PLATE SET, FRONT REINFORCEMENT	NOT NECESSARY	67.00	-
4	FASTENER, PLATE SET	NOT NECESSARY	12.00	-
1	REAR BUMPER	DEFORMED	1,074.80	1,074.80
1	BRACKET CENTER	SERVICEABLE	5.10	-
1	TOWING COVER LHS	MISSING	15.70	15.70
1	TOWING COVER RHS	CUT	16.20	16.20
1	REFLECTOR RHS	NOT NECESSARY	50.40	-
3	RETAINER, SENSOR	NOT NECESSARY	51.90	-
2	SENSOR CENTER, ULTRASONIC	NOT NECESSARY	344.40	-
1	SENSOR SIDE, ULTRASONIC	NOT NECESSARY	193.90	-
3	TAPE PROTECTOR, SENSOR	NECESSARY	24.30	24.30
1	REAR REINFORCEMENT	NOT NECESSARY	537.30	-
4	GROMMET, REAR BUMPER	NECESSARY	10.00	10.00
4	RIVET, REAR BUMPER	NECESSARY	16.80	16.80
21	GROMMET, REAR BUMPER	NECESSARY	58.80	58.80
4	FASTENER, REAR BUMPER	NECESSARY	11.20	11.20
2	CLIP, REAR BUMPER	NECESSARY	6.40	6.40
1	GASKET LHS, BOOTLID	NECESSARY	20.90	20.90
1	GASKET RHS, BOOTLID	NECESSARY	20.90	20.90
1	GASKET LHS, TAILLAMP	NECESSARY	20.90	20.90
1	GASKET RHS, TAILLAMP	NECESSARY	20.90	20.90
1	ORNAMENT, MAZDA	NECESSARY	53.40	53.40
1	MASCOT, REAR	NECESSARY	74.40	74.40
1	ORNAMENT, SKYACTIVE	NECESSARY	63.60	63.60
1	HOLDER, LICENCE PLATE	SERVICEABLE	71.00	-
1	BOOTLID	BENT	957.40	957.40

Report Ref No. CC4/LPC19000039/R1db3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,040.10	-290.81
			9,360.90	2,617.29
	SPECIAL NETT ITEMS			
1	NUMBER PLATE (SN)	NOT NECESSARY	70.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			170.00	30.00
	LABOUR			
	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,980.00	990.00
	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP.		1,890.00	945.00
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO BOOTLID REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.		1,980.00	1,650.00
	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOTLID.		2,520.00	1,890.00
	TO TRANSFER REVERSE SENSORS.		660.00	330.00
	TO TRANSFER REVERSE CAMERA.	NOT NECESSARY	660.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			10,540.00	6,285.00
	GRAND TOTAL		20,070.90	8,932.29
RECOMMENDED COST OF REPAIRS				8,932.29

Report Ref No. CC4/LPC19000039/R1db3s2

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.