



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



LKK

<i>Lampac</i>		NAME : Mr Lau Aik Cheng	WIP : 38885
ATTN. : MOTOR CLAIMS		ADDRESS : Blk 306b Punggol Place	EXCESS :
FAX :		#09-25	DATE: 28-Dec-18
		Singapore 822306	
		TEL : 97927303	

VEH NO :	SLN5470C	DATE IN :		CONTACT PERSON :	TOMMY/JESS
CHASSIS NO :	JM6BN22A8H0149003	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	8-May-17	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	FRONT BUMPER ? 1 MB63B-50-031BBB		\$ 825.50
2	FRONT REINFORCEMENT ? 1 MB61K-50-070A		\$ 478.80
3	CLIP, FRONT BUMPER m- 12 MC274-50-133		\$ 42.00
4	FASTENER, FRONT BUMPER m- 2 MB45A-56-146A		\$ 5.60
5	GROMMET, FRONT BUMPER m- 2 MGHP9-50-025		\$ 5.40
6	SEAL RUBBER, FRONT BUMPER X 2 MB63B-50-2G2		\$ 4.40
7	GRILLE TOP DC- 1 MB63B-50-033A64		\$ 338.50
8	RIVET, GRILLE TOP m- 4 MTK21-50-355		\$ 34.80
9	RIVET, GRILLE TOP m- 4 MS51S-51-833		\$ 15.20
10	MASCOT, FRONT X old damage 1 MD10J-51-730		\$ 58.50
11	BRACKET, MASCOT X 1 MB63B-50-716		\$ 20.60
12	CHROME LHS X 1 MB63B-50-7K1A		\$ 182.30
13	CHROME RHS X 1 MB63B-50-7J1A		\$ 182.50
14	PROTECTOR LHS, CHROME X 1 MB63E-50-B51B		\$ 19.50
15	PROTECTOR RHS, CHROME X 1 MB63E-50-B41B		\$ 19.50
16	PROTECTOR LHS, NO.1 X 1 MB63B-50-B51		\$ 36.80
17	PROTECTOR RHS, NO.1 X 1 MB63B-50-B41		\$ 37.20
18	PROTECTOR LHS, NO.2 X 1 MB63C-50-B51		\$ 37.10
19	PROTECTOR RHS, NO.2 X 1 MB63C-50-B41		\$ 37.10
20	PROTECTOR LHS, NO.3 X 1 MB63D-50-B51		\$ 37.20
21	PROTECTOR RHS, NO.3 X 1 MB63D-50-B41		\$ 37.10
22	PROTECTOR CENTER, NO.1 X 1 MB63B-50-B31		\$ 67.60
23	PROTECTOR CENTER, NO.2 X 1 MB63C-50-B31		\$ 67.60
24	PROTECTOR CENTER, NO.3 X 1 MB63D-50-B31		\$ 66.30
25	FRONT GRILLE ? 1 MB63C-50-712B		\$ 129.00
26	BRACKET LHS, FRONT GRILLE X 1 MB63B-50-163		\$ 26.00
27	BRACKET RHS, FRONT GRILLE X 1 MB63B-50-153		\$ 26.00
28	CLIP, FRONT GRILLE X 2 MG46L-50-EB1		\$ 8.80
29	CLIP, FRONT GRILLE X 1 MGHP9-50-EB1A		\$ 3.20
30	PIN LOCATOR, FRONT GRILLE X 2 MKD45-50-1K5A		\$ 5.40

31	GROMMET, FRONT GRILLE	X	2	MKD45-50-ES1	\$ 5.40
32	RIVET, FRONT GRILLE	X	4	MEA01-50-037	\$ 30.40
33	SEAL RUBBER, FRONT GRILLE	X	2	MB63C-50-2G2	\$ 5.20
34	BRACKET TOP, GRILLE	X	1	MB63B-50-717	\$ 90.80
35	HEADLAMP RHS	X	1	MBAAR-51-031H	\$ 3,598.60
36	RIVET, HEADLAMP	X	1	MB092-51-833	\$ 3.30
37	CLIP, HEADLAMP	X	2	MDR61-50-133	\$ 12.20
38	PLATE SET, FRONT REINFORCEMENT	?	1	MB63E-50-1C0A	\$ 67.00
39	FASTENER, PLATE SET	?	4	MGD7A-50-EA1	\$ 12.00
40	REAR BUMPER	DC-	1	MBPD8-50-221ABB	\$ 1,074.80
41	BRACKET CENTER	?	1	MKD53-50-251	\$ 5.10
42	TOWING COVER LHS	* MIS	1	MBHN1-50-EL1 BB	\$ 15.70
43	TOWING COVER RHS	cut	1	MBHN1-50-EK1 BB	\$ 16.20
44	REFLECTOR RHS	?	1	MD350-51-5M0E	\$ 50.40
45	RETAINER, SENSOR	?	3	MKD47-67-UC5A64	\$ 51.90
46	SENSOR CENTER, ULTRASONIC	X	2	MGMK6-67-UC1 64	\$ 344.40
47	SENSOR SIDE, ULTRASONIC	X	1	MKD47-67-UC1 64	\$ 193.90
48	TAPE PROTECTOR, SENSOR	ne	3	MGS1D-50-EM1A	\$ 24.30
49	REAR REINFORCEMENT	?	1	MB45A-50-260	\$ 537.30
50	GROMMET, REAR BUMPER	ne	4	MBHN1-50-0Z1A	\$ 10.00
51	RIVET, REAR BUMPER	ne	4	MBBM4-50-355	\$ 16.80
52	GROMMET, REAR BUMPER	ne	21	M9991-00-501	\$ 58.80
53	FASTENER, REAR BUMPER	ne	4	MB45A-56-146A	\$ 11.20
54	CLIP, REAR BUMPER	ne	2	MGJ21-50-049	\$ 6.40
55	GASKET LHS, BOOTLID	ne	1	MB45A-51-3J8	\$ 20.90
56	GASKET RHS, BOOTLID	ne	1	MB45A-51-3H8	\$ 20.90
57	GASKET LHS, TAILLAMP	ne	1	MBHN1-51-163	\$ 20.90
58	GASKET RHS, TAILLAMP	ne	1	MBHN1-51-153	\$ 20.90
59	ORNAMENT, MAZDA	ne	1	MBHN1-51-721	\$ 53.40
60	MASCOT, REAR	ne	1	MBHN1-51-730	\$ 74.40
61	ORNAMENT, SKYACTIVE	ne	1	MBHN1-51-771	\$ 63.60
62	HOLDER, LICENSE PLATE	X	1	MBABD-50-170	\$ 71.00
63					
TOTAL PARTS					\$ 9,443.60
LESS 10%					\$ 944.36
TOTAL PARTS COST					\$ 8,499.24

Labour Description				
1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 1,980.00
2	MZ-SP-SFRTO3	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP.	945	\$ 1,890.00
3	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 1,980.00

4	MZ-SP-SREARS	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	1260	\$ 2,520.00
5	MZ-BR-REVEN	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X	\$ 660.00
7	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT	\$ X 70.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 30 100.00

TOTAL LABOUR	\$ -	\$ 10,710.00
TOTAL PARTS	\$ -	\$ 8,499.24
TOTAL	\$ -	\$ 19,209.24
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature

Rasul

Hp 90010068

8 days

P/P

03/01/19 @ 1450

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: