

INS. CASE OWNER

PKLW

CC 4 AXA 1900

0043, T19 a3

LKK: IDAC:

ASSIGNMENT

Surveyor:

Tanish

DOE:

4/1/2019

Date / Time:

21/1/19

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLV 6596A

Claim No.:

S8MU182H / 00175

Name of Insured:

MUKUND SATHAR ISMAIL

Policy No.:

60747661

Insured Tel No.:

HP:

Make / Model:

HONDA

Excess Sec II SS

D.O.A.:

26/1/19

Place of Accident:

PRIME EDWARDS RD

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MOHAMMAD ABU BAKR BIN MOHAMMAD

OI GIA REPORT (YES / NO):

TP GIA REPORT (YES / NO)

Driver Tel No.:

(V/L: YES / NO) SHARIF ISMAIL

Insured Liability: %

Final ? Yes / No

SLW 50576



INSRS: WSP: Tel: Liability: RMKS:

performance



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date / Time	STAGE	DATE / PIC
21/1/19	Non-Reporting (1st):	
	Non-Reporting (2nd):	
	Non-Reporting (Final):	
	Notification (1st) (non-pickup):	
	Call OI	
	After call (1st) to OI	
26/1/19	Documentation Check List: Handler	Typist
	Notification (1st) (non-pickup)	<input checked="" type="checkbox"/>
	After call (1st) to OI	<input checked="" type="checkbox"/>
	Authorization To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
 Repair Cost: SS (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 9
 Repair Cost: SS
 Loss of Rental (LOR): SS (days)
 Loss of Use (LOU): SS (5 x days)
 Loss of Income (LOI): SS (5 x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: SS
 Medical: SS
 Disbursement: SS (e.g. Tow/Independent)
 Legal Cost: SS

Total: SS **Global Sum SS:** _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call
 Payee 1: SS Name 1: _____
 Payee 2: (Strike if N.A.) SS Name 2: _____
 Payee 3: (Strike if N.A.) SS Name 3: _____

COPY SENT 4/1/2020

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: WP
- 3) Survey fee: \$250

Tanpin

REF: ASM(AXA)

J

ASSIGNMENT

From: Date: 04/01/2019

Veh No: SLW59526 In Regn: 2018 Feb

Estimated Cost: OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

To inspect Vehicle No: SLW 59526
at Workshop no: Performance
of: 303 Alexandra Road

Make: BMW 318 c.c. 1499
Colour: Black A/C: Insured / Std / NI / NA
Sp Reading: 13423 T/Radio: Insured / Std / NI / NA

Insured: Policy No: Claims No: Sum Insured: Excess:

Eng/No: C/N: WBSA 8E36040N4 82307
Gen Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record) Make of Veh: 3-30 Kalvin

Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or Tyre Size: F: 225/50R17
R: 225/50R17

(Policy Condition) Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: \$138K
IDAC Accident Rpt: Consistent? Yes or No
GIA / PR Seen: Consistent? Yes or No

Front R/Bal: C mm Rear R/Bal: C mm
L/Bal: C mm L/Bal: C mm

Est Repairs: 5 days Res: Yes or No
Lum Sum: 1-9-1 % 3 Val: Yes or No
CA / REV / REP. / 24 HRS (cap)

D.O.A. D.O.I: 4/1/19
Survey held at: PML
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Fnt o/s

Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
29/12/19	TP claim revert to OD claim, inform by Tony from PML. PIP # 9575.75 (Red- 44689.95 / 331.) ? Item # 1659

Date/Time, File Pass to? : Prell. Report : Final Report

Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: \$ + RS. \$
Photos: Others: TOTAL

Date/Time, File Return to? Add Fee: : Site Insp. (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Report Format: Lump Sum / I.B.I. (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19000043/jb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 02-01-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLV 6596A	Veh. Inspected	SLW 5952G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/01/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/12/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401859M GST Reg. No M2-0020081-X



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

281, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64756601 (AfterSales)
64756624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

27 DEC 2018

ESTIMATE

Estimate No. : **b1 49558** Page No. : **1 of 5**
Date Estimated : **27/12/2018**
Prepared By : **Kevin Leong Wai Kit**

- ESTIMATE REPAIR FOR -

J Anton Ravindran
69 Bedok Ria Crescent

Singapore 489885

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLW5952G	NU82307	23/02/2018	318iA/4Dr	0

DESCRIPTION

VALUE

To replace frt bumper, frt RH headlamp bracket, frt RH side panel & all attachments cause by accident.	1700	3,400.00
Painting on frt bumper & frt RH side panel	✓	1,634.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	451	531.00
To replace tyre and wheel rim including balancing. (1x)	80	94.00
To check electrical wiring systems at the front section for proper function.	150	177.00
To replace right headlight.	408	481.00
To carry out body cavity preservation, (Per panel) Frt RH side panel	100	118.00
Sundries.	?	150.00

Total Labour 1: **6,585.00**

DESCRIPTION

QTY PRIC

VALUE

ALLOY RIM 7.5JX17 MULTISPOKE 414	1	819.55	Rx 819.55
FRT RH SIDE PANEL	1	699.55	bt 699.55
FRT RH 2 SIDE PANEL BRACKET	1	32.95	? 32.95
FRT RH 1 SIDE PANEL BRACKET	1	32.95	? 32.95
FRT RH 3 SIDE PANEL BRACKET	1	32.95	? 32.95
FRT BUMPER TOP MOUNT	1	370.70	? 370.70
FRT RH DEFORMATION ELEMENT	1	99.80	? 99.80
INSERT AIR INLET MIDDLE	1	121.95	? 121.95
INSERT AIR INLET MIDDLE	1	121.95	? 121.95
RH FOG LAMP SUPPORT	1	41.85	? 41.85
RH AIR INLET FINISHER (LUXURY)	1	53.20	ans 53.20
RH PARTIALLY OPEN GRID (BASIS)	1	85.90	? 85.90

305, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770280, Kembangan Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796604 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49558
Date Estimated : 27/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLW5952G	NU82307	23/02/2018	318iA/4Dr	0

DESCRIPTION	QTY	PRIC	VALUE
FRT SHOCK ABSORBER ECE	1	53.45	? 53.45
FRT BUMPER PANEL PRIMED (LINES)	1	959.35	de 959.35
RH SPRAY NOZZLE COVER PRIMED	1	43.25	de X43.25
SET MOUNTING PDC/PMA SENSOR FRT	1	84.10	rel 84.10
FRT RH GRILLE (LUXURY)	1	118.55	rel 118.55
RIVET	2	0.45	rel 0.90
RH SUPPORT	1	55.30	? 55.30
FRT BUMPER LOWER MOUNT	1	131.20	rel 131.20
LH COVER FOR BULB REPLACEMENT	1	10.10	de 10.10
FRT RH WHEEL HOUSING COVER	1	116.55	? 116.55
COVER BOTTOM RH	1	116.55	de 116.55
DEFLECTOR LIP RH	1	52.80	? 52.80
RH HEADLIGHT LED TECHNOLOGY	1	3,068.40	rel 3,068.40
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	rel 20.20
ULTRASONIC SENSOR BLACK	1	236.85	? 236.85
(DG/SL) ADHESIVE SET K6	1	53.05	? 53.05
Total Parts :			7,633.90

Client GST Ref Party / Address / Contact / Date / Time / Signature / Stamp / Remarks

4/1/17 @ 340
Tanjoh
97175749
WP
Tanjoh @ Pinter.com
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recognized and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour 1	:	6,585.00
Parts	:	7,633.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	995.32
Grand Total	:	15,214.22

◀ Service Request Details

Claim

S8M0183H

Reference

None ✎

Loss Date

26 December 2018

Request Date

28 December 2018

Due Date

4 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*31/12/2018 @ 9:18am
Online verification*

Actions

Next Step

Agree to perform service

Decline Work	Accept Work
--------------	-------------

Vehicle Information

Incident Vehicle Registration #

SLW5952G

Make

TPVD BMW

Service Address

...

Primary Contact/Insured

ISMAIL MOHAMD SAHAR
769 CHOA CHU KANG STREET 54, #06-19, 680769, Singapore
82234134

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 27 December, 2018 5:25 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: REQUEST FOR DIRECT SETTLEMENT - SLW5952G & SLV6596A ON 26/12/2018
Attachments: SKM_558e18122717210.pdf; 117ddd15-5256-4c3a-b4d1-d0dc1ebc1061.jpg; c306a53e-53e1-45e4-9c83-76aae79fcaec.jpg; IMG_8100.JPG; IMG_8102.JPG; IMG_8104.JPG

Categories: Shekhar

Dear Sirs,
We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 26 June 2019 11:58 AM
To: md.aflaque@gmail.com
Subject: <Standard Notification Letter> Our ref: CC4/ASM19000043/T1gb3 *** ACCIDENT INVOLVING SLV 6596A & SLW 5952G ON 26/12/2018 ***

MOHAMD SAHAR ISMAIL /
MOHAMAD AFLAQUE BIN MOHAMD SAHAR ISMAIL

Dear Sir/ Mdm

OUR REF : CC4/ASM19000043/T1gb3
YOUR REF : SLV 6596A
ACCIDENT INVOLVING SLV 6596A AND SLW 5952G ALONG/AT PRINCE EDWARD ROAD ON 26/12/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **PERFORMANCE MOTORS LIMITED** acting on behalf of the owner of SLV 5952G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ceciliachong@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Driver's Work Permit
- Employment Letter/ Authorisation letter from your company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6749 4274 or email us at ceciliachong@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK

Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19000043/T1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 16-01-2020



ATTN:PETER

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 6596A	Veh. Inspected	SLW 5952G
Policy No.	GA342966/1	Coverage (\$)	0.00
Claim No.	S8M0183H	Excess (\$)	0.00
Assign From		Assign Date	02/01/2019

2. Vehicle Particulars & Condition

Make & Model	BMW 318	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBA8E36040NU82307	Colour	BLACK
Odometer	13423	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/12/2018	Inspection Date	04/01/2019
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 5952G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	* CHECK	✓ 150.00	-
1	ALLOY RIM 7.5JX17 MULTISPOKE 414 (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 819.55	-
1	FRT RH SIDE PANEL (SN) (CONSISTENT)	BENT	✓ 699.55	699.55
1	FRT RH 2 SIDE PANEL BRACKET (SN) (CONSISTENT)	* CHECK	✓ 32.95	-
1	FRT RH 1 SIDE PANEL BRACKET (SN) (CONSISTENT)	* CHECK	✓ 32.95	-
1	FRT RH 3 SIDE PANEL BRACKET (SN) (CONSISTENT)	* CHECK	✓ 32.95	-
1	FRT BUMPER TOP MOUNT (SN) (CONSISTENT)	* CHECK	✓ 370.70	-
1	FRT RH DEFORMATION ELEMENT (SN) (CONSISTENT)	* CHECK	✓ 99.80	-
1	INSERT AIR INLET MIDDLE (SN) (CONSISTENT)	* CHECK	✓ 121.95	-
1	INSERT AIR INLET MIDDLE (SN) (CONSISTENT)	* CHECK	✓ 121.95	-
1	RH FOG LAMP SUPPORT (SN) (CONSISTENT)	* CHECK	✓ 41.85	-
1	RH AIR INLET FINISHER (LUXURY) (SN) (CONSISTENT)	CRACKED	✓ 53.20	53.20
1	RH PARTIALLY OPEN GRID (BASIS) (SN) (CONSISTENT)	* CHECK	✓ 85.90	-
1	FRT SHOCK ABSORBER ECE (SN) (CONSISTENT)	* CHECK	✓ 53.45	-
1	FRT BUMPER PANEL PRIMED (LINES) (SN) (CONSISTENT)	DEFORMED	✓ 959.35	959.35
1	RH SPRAY NOZZLE COVER PRIMED (SN) (CONSISTENT)	NOT NECESSARY	✓ 43.25	-
1	SET MOUNTING PDC/PMA SENSOR FRT (SN) (CONSISTENT)	NECESSARY	✓ 84.10	84.10
1	FRT RH GRILLE (LUXURY) (SN) (CONSISTENT)	NOT NECESSARY	✓ 118.55	-
2	RIVET (SN) (CONSISTENT)	NECESSARY	✓ 0.90	0.90
1	RH SUPPORT (SN) (CONSISTENT)	* CHECK	✓ 55.30	-
1	FRT BUMPER LOWER MOUNT (SN) (CONSISTENT)	NOT NECESSARY	✓ 131.20	-
1	LH COVER FOR BULB REPLACEMENT (SN) (CONSISTENT)	DEFORMED	✓ 10.10	10.10
1	FRT RH WHEEL HOUSING COVER (SN) (CONSISTENT)	* CHECK	✓ 116.55	-
1	COVER BOTTOM RH (SN) (CONSISTENT)	DEFORMED	✓ 116.55	116.55
1	DEFLECTOR LIP RH (SN) (CONSISTENT)	* CHECK	✓ 52.80	-
1	RH HEADLIGHT LED TECHNOLOGY (SN) (CONSISTENT)	CRACKED	✓ 3,068.40	3,068.40
4	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT)	NECESSARY	✓ 20.20	20.20

Report Ref No. CC4/ASM19000043/T1ga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ULTRASONIC SENSOR BLACK (SN) (CONSISTENT)	* CHECK	236.85	-
1	(DG/SL) ADHESIVE SET K6 (SN) (CONSISTENT)	* CHECK	53.05	-
			7,783.90	5,012.35
	LABOUR			
	TO REPLACE FRT BUMPER ,FRT RH HEADLAMP BRACKET ,FRT RH SIDE PANEL & ALL ATTACHMENTS CAUSE BY ACCIDENT.INCLUSIVE OF THE REPAIR OF ALLOY RIM 7.5JX17 MULTISPOKE 414.		3,400.00	1,700.00
	PAINTING ON FRT BUMPER & FRT RH SIDE PANEL.		1,634.00	1,634.00
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION .		531.00	451.00
	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING.		94.00	80.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION .		177.00	150.00
	TO REPLACE RIGHT HEADLIGHT.		481.00	408.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) FRT RH SIDE PANEL.		118.00	100.00
			6,435.00	4,523.00
GRAND TOTAL			14,218.90	9,535.35
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1659.00 NETT)				9,535.35

Report Ref No. CC4/ASM19000043/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim SRM01B3H

Reference CC4UASM19000043/TTg3iqz

Loss Date 26 December 2018

Report Date 28 Dec 2018 9:14:00 AM

Request Date 30 May 2019

Due Date

Vendor Name LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss Third Party Vehicle Damage

Services Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration # SLW5952G

Make TPVD BMW

Model 318i-1.5

Service Address

...

Primary Contact/Insured

ISMAIL MOHAMAD SAHAR
749 CHOA CHU KANG STREET 54, #06-19,
680769, Singapore
82234134

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Actions

Next Step: Wait for Approve Invoice

[Add Invoice](#)

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type:

[Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKXInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	17 January 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInspection11.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 LKK PHOTO.jpg	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 TP VIDEO - SLW5952.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 EMAIL TP Prelimng	Letters and Correspondence	Workshop	VISHNU BATHNAM Shekhar	28 December 2018
 GIA SLW5952G TP.PDF	Letters and Correspondence	Government Authorities / Police / Association / Regulator	VISHNU BATHNAM Shekhar	28 December 2018
 GIA SLW596A INSD.PDF	Reports & Statement	GIA Report	VISHNU BATHNAM Shekhar	28 December 2018