

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

27 DEC 2018

E S T I M A T E

Page No. : 1 of 5

Estimate No. : **b1 49558**
Date Estimated : **27/12/2018**
Prepared By : **Kevin Leong Wai Kit**

- ESTIMATE REPAIR FOR -
J Anton Ravindran
69 Bedok Ria Crescent

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 489885

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLW5952G	NU82307	23/02/2018	318iA/4Dr	0

DESCRIPTION

VALUE

To replace frt bumper, frt RH headlamp bracket, frt RH side panel & all attachments cause by accident.	1700	3,400.00
Painting on frt bumper & frt RH side panel	✓	1,634.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	451	531.00
To replace tyre and wheel rim including balancing. (1x).	80	94.00
To check electrical wiring systems at the front section for proper function.	150	177.00
To replace right headlight.	408	481.00
To carry out body cavity preservation. (Per panel) Frt RH side panel	100	118.00
Sundries.	?	150.00

Total Labour 1: **6,585.00**

DESCRIPTION

QTY

PRIC

VALUE

ALLOY RIM 7.5JX17 MULTISPOKE 414	1	819.55	Rx 819.55
FRT RH SIDE PANEL	1	699.55	bt 699.55
FRT RH 2 SIDE PANEL BRACKET	1	32.95	? 32.95
FRT RH 1 SIDE PANEL BRACKET	1	32.95	? 32.95
FRT RH 3 SIDE PANEL BRACKET	1	32.95	? 32.95
FRT BUMPER TOP MOUNT	1	370.70	? 370.70
FRT RH DEFORMATION ELEMENT	1	99.80	? 99.80
INSERT AIR INLET MIDDLE	1	121.95	? 121.95
INSERT AIR INLET MIDDLE	1	121.95	? 121.95
RH FOG LAMP SUPPORT	1	41.85	? 41.85
RH AIR INLET FINISHER (LUXURY)	1	53.20	can 53.20
RH PARTIALLY OPEN GRID (BASIS)	1	85.90	? 85.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : **b1 49558**
Date Estimated : **27/12/2018**
Prepared By : **Kevin Leong Wai Kit**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLW5952G	NU82307	23/02/2018	318iA/4Dr	0

DESCRIPTION	QTY	PRIC	VALUE
FRT SHOCK ABSORBER ECE	1	53.45	? 53.45
FRT BUMPER PANEL PRIMED (LINES)	1	959.35	de 959.35
RH SPRAY NOZZLE COVER PRIMED	1	43.25	X 43.25
SET MOUNTING PDC/PMA SENSOR FRT	1	84.10	rel 84.10
FRT RH GRILLE (LUXURY)	1	118.55	X 118.55
RIVET	2	0.45	rel 0.90
RH SUPPORT	1	55.30	? 55.30
FRT BUMPER LOWER MOUNT	1	131.20	X 131.20
LH COVER FOR BULB REPLACEMENT	1	10.10	de 10.10
FRT RH WHEEL HOUSING COVER	1	116.55	? 116.55
COVER BOTTOM RH	1	116.55	de 116.55
DEFLECTOR LIP RH	1	52.80	? 52.80
RH HEADLIGHT LED TECHNOLOGY	1	3,068.40	can 3,068.40
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	rel 20.20
ULTRASONIC SENSOR BLACK	1	236.85	? 236.85
(DG/SL) ADHESIVE SET K6	1	53.05	? 53.05

Total Parts : **7,633.90**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time 4/1/19 @ 340 Excess S\$ _____
 Surveyor's Name Tanjim Sign [Signature]
 Surveyor's Tel 97415749 Authorised Yes / No _____
 Authorised Date WP Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes No PML Yes / No _____
 Surveyor's E-mail tanjim@lhkart.com
 No. of Working Days Recommendation 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour 1	:	6,585.00
Parts	:	7,633.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	995.32
Grand Total	:	15,214.22

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **