

PERSON

INSURANCE OWNERS

CC4 / III1900 0060

LKK

IDAC

Surveyor:

MARINS

DOI:

ASSIGNMENT

2/1/19

Date / Time:

2/1/19

Registered in Meriton:

2/1/15

Pre-assign / CCU / FTE

SLD 3682X



Insured Vehicle No.:

Claim No.:

Name of Insured:

LTC

Policy No.:

MUM0015

Insured Tel No.:

HP:

Make / Model:

HONDA

Excess Sec II :SS

D.O.A.:

20/1/18

Place of Accident:

MPP (HONG KONG)

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

RAYMOND LEE KONG LENO

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SLN 4666L

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:200m  
mtoINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time

8/1/19

SLN 4666L / MPP (HONG KONG) / 2/1/19

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

15/1/19

FILE RECORDED. OLD CHANGED CAR.

BASIC LIABILITY MANDATE.

16/1/19

IN AGREED PS

17/1/19

BASIC LIABILITY CLERK

PICKUP

TP LOP IN BY BULK

13/2/19

File pass to type mandae

6/1/19

File -&gt; SW to send in

13/12/19

File pass to LSP to close.

## PRELIMINARY ADVICE

Date/Time:

Sent By:

## FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

45

SS

P1,000.00

14

days) Reduction:

57

%

Confirm by:

Email

Call

## FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

SS

19000.00

Loss of Rental (LOR):

SS

1700.00

17

days)

YB100

Loss of Use (LOU):

SS

-

(5

x

days)

Loss of Income (LOI):

SS

-

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

745

Medical:

SS

Disbursement:

SS

(e.g. Tows/ Independent)

Legal Cost

SS

Total:

SS

20707.45

Global Sum SS:

20700.00

## FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

20700.00

Name 1:

Zam Automotives Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: TH

Surveyor

## ASSIGNMENT

From: \_\_\_\_\_ Date: 02/12/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLN 4666Lat Workshop m/s: Zoom Autoof: 15 Kaki Bukit Rd 4 # 01-53

Insured:

Policy No:

Claims No:

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 75

IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No

Est. Repairs: 14 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLN 4666L Yr Regn: S 17Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Horde verel cc 1496Colour: Green A/C Insured / Std / NI / NASp Reading: 23186 T/Radio: Insured / Std / NI / NA

Eng/No:

ChNo: Ru / 1208976Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mmR/Bal: 7 mmL/Bal: 7 mmL/Bal: 7 mmD.O.A. 30/12/18D.O.I. 2/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21A 540fr net 20918  
Sym. 4666L Rep 814 x 19,000.00  
(200 x 20,349.00/57%)14 + 1PH + 1PR + 2Sun = 18

Date/Time: File Pass to?

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ : Site Insp (\$

) S + RE: SI

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Other

☐ Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III19000060/Uhb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 02-01-2019	
			Code : III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 3682X	Veh. Inspected	SLN 4666L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/01/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	30/12/2018	Inspection Date	02/01/2019	
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

*Not Authorised*

*4/5 @ 19.000  
2/1/19 14 day.  
Teh J. H. Heng*

03 JANUARY 2019

REG NO.: SLN 4666 L  
MAKE/MODEL: HONDA VEZEL

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet <i>892.30</i>	\$ <i>Sub</i> 1,151.70
2	Front bonnet hinges	\$ <i>Sub</i> 143.40
1	Front bonnet insulator	\$ <i>Torn</i> 168.00
1	Front bonnet insulator clip (1 set)	\$ <i>Sub</i> 50.00
1	Front bonnet lock	\$ <i>Sub</i> 145.00
1	Front bonnet rubber	\$ <i>Sub</i> 78.30
2	Front headlamps <i>1759 x 2 = 3518</i>	\$ <i>Core</i> 3,569.00
2	Front headlamp lower brackets	\$ <i>Core</i> 150.60
1	Front grille	\$ <i>Core</i> 285.00
1	Front grille top outer garnish	\$ <i>Core/Car</i> 195.30
1	Front grille logo	\$ <i>Sub</i> 45.70
1	Front bumper <i>801.70</i>	\$ <i>Sub</i> 1,085.40
1	Front bumper centre grille	\$ <i>Sub</i> 167.00
1	Front bumper fog lamp	\$ <i>Core</i> 327.70
1	Front bumper fog lamp cover	\$ <i>Torn</i> 45.20
1	Front bumper reinforcement	\$ <i>Sub</i> 321.40
2	Front bumper side retainers	\$ <i>Sub</i> 120.60
1	Front bumper tow hook cover	\$ <i>Sub</i> 48.00
1	Front bumper undercover	\$ <i>Sub</i> 225.00
2	Front fenders <i>180</i>	\$ <i>Sub/Dis</i> 1,160.80 <i>180</i>
1	Front fender inner panel <i>180</i>	\$ <i>Sub/Dis</i> 485.00
2	Front fender inner shields	\$ <i>Sub/Dis</i> 100.00 <i>180</i>
1	Front fender wheel house	\$ <i>Sub</i> 675.00
2	Front fender wheel arch garnishes <i>210 x 2 = 420</i>	\$ <i>Torn/Sub</i> 976.60
1	Front support panel	\$ <i>Sub</i> 576.00
1	Front support panel top garnish	\$ <i>Sub</i> 190.30
1	Front support panel side garnish	\$ <i>Sub</i> 70.50
1	Horn	\$ <i>Dis</i> 95.00
1	Air con condenser	\$ <i>Sub</i> 748.00
1	Radiator	\$ <i>Sub</i> 1,150.00
1	Wire harness (1 set)	\$ <i>Sub</i> 1,855.20
1	Front wiper tank	\$ <i>Sub</i> 185.00
1	Front wiper garnish (1 set)	\$ <i>Sub</i> 255.00
1	Front wiper motor	\$ <i>Sub</i> 135.00
1	Front wheel rim -R/H	\$ <i>Sub</i> 1,350.40 <i>4805</i>
1	Front wheel hub	\$ <i>Sub</i> 299.70
		\$ 18,629.80

LIST ITEMS

1	Front wheel bearing		\$	all	181.50 ✓
1	Front shock absorber	366.20	\$	best	501.20 ✓
1	Front knuckle arm	388.50	\$	best	600.70 ✓
1	Front tie rod		\$	all	120.50 X
1	Front lower arm	392.30	\$	all	426.00 ✓
1	Power steering rack		\$	all	1,750.60 X
1	Steering rack cross member		\$	all	795.20 X
1	Front stabilizer bar		\$	11	175.90 X
1	Front drive shaft -R/H		\$	11	985.00 X
1	Engine mounting -R/H		\$	2012	240.00 ✓
1	Engine mounting bracket		\$	all	160.00 X
1	Front door	966.20	\$	best	1,085.70 ✓
1	Front door checker		\$	11	95.00 X
1	Front door glass outer moulding		\$	11	199.00 X
2	Front door hinges		\$	11	179.40 X
1	Front door inner board		\$	11	588.90 X
1	Front door lock		\$	11	213.80 X
1	Front door regulator		\$	11	488.80 X
1	Front door regulator motor		\$	11	350.70 X
1	Front door rubber		\$	all	122.70 ✓
1	Front door side mirror assy		\$	all	745.50 X
1	Front door pillar		\$	11	950.70 X
1	Front door pillar inner garnish		\$	11	155.80 X
1	Front dashboard	892.50	\$	all	1,280.50 ✓
1	Side air bag -LH	1488.10	\$	all	2,600.90 ✓
1	Roof lining	1488.50	\$	all	2,888.80 ✓
1	Front passenger air bag	2436.80	\$	all	2,667.30 ✓
2	Front safety belts		\$	all	1,400.60 ✓
1	Front steering air bag	2110.10	\$	all	2,650.00 ✓
1	Air bag control unit	980.00	\$	all	1,564.40 ✓
1	Steering wheel clock spring	268.90	\$	all	297.60 ✓
			\$		45,092.50
Less 20%			\$		9,018.50
			\$		36,074.00

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)		\$	all	45.00 ✓
1	Front bumper lower spoiler		\$	11	750.00 400
1	Front number plate with holder		\$	11	50.00 X
2	Front fender inner shield clips (2 set)		\$	all	100.00 50
1	Front tyre -R/H		\$	all	350.00 X
1	Rocker panel side skirt		\$	11	650.00 400
			\$		1,945.00

1375

S/N	LABOUR CHARGES		
1	To check wiring and reset headlamps focusing.	\$	80.00 30
2	To remove and refit inner garnishes.	\$	11 180.00 X
3	To remove and refit front undercarriage.	\$	450.00 150
4	To conduct wheel alignment.	\$	180.00 80
5	To remove, refit and reset Air bag systems.	\$	280.00 ✓
6	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00 100
7	To remove and refit dashboard to assist repair.	\$	250.00 ✓
8	To remove and refit front windscreen glass.	\$	11 180.00 X
9	To remove, replace doors and damaged parts, transfer all fittings to new door.	\$	150.00 60
10	To apply undercoating.	\$	250.00 120
11	Panel beating.	\$	2,000.00 1200
12	To re-spray painting on the affected areas.	\$	1,800.00 1400
13	To diagnose erase fault memory after repair.	\$	350.00 100
		\$	6,330.00

3770

GRAND TOTAL :

\$ 44,349.00

LEADER'S COMPANY will handle notify the Repairer of the following:

- To receive better after sales service
- To ensure correct parts being replaced
- Parts must be subject to confirmation
- To ensure there is no "without prejudice" term
- The Repairer's work is allowed
- Supplementary work must be re-employed and is subject to full approval from insurance Company

Acknowledged by Repairer:

Signature \_\_\_\_\_

Date: \_\_\_\_\_

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 0920D

### Vehicle Details

Vehicle No.: SLN4666L  
Vehicle to be Exported: No  
Intended Deregistration Date: 03 Jan 2019  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X CVT  
Primary Colour: Green  
Manufacturing Year: 2016  
Engine No.: L15B4408976  
Chassis No.: RU11208976  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$23,412.00  
Original Registration Date: 04 May 2017  
First Registration Date: 04 May 2017  
Transfer Count: 0  
Actual ARF Paid: \$14,777.00 7388

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 03 May 2027  
PARF Rebate Amount: \$11,082.00

### Intended COE Rebate Details

COE Expiry Date: 03 May 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$51,600.00  
COE Rebate Amount: \$43,000.00  
**Total Rebate Amount: \$54,082.00**

The information contained herein is correct as at 03 Jan 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

- 2019 Mercedes A class (W177) and Sedan (V177) - A3
- What Did You Make Today PT 5
- Apple Event '18: iPhones XS, XS Max, XR, Apple Wat...

vezel

Price Range

Depreciation

2017

Vehicle Type

Home » Used Cars » AL Autocart Pte Ltd » Honda Vezel 1.5A X Honda Sensing

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Honda Vezel 1.5A X Honda Sensing

Overview

Financial

Accessories

Similar

Research

Photos

Map



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

**Price** \$75,800**Depreciation** \$8,220 /yr

View models with similar depreciation

**Reg Date** 18-Jul-2017

(8yrs 6mths 14days COE left)

**Manufactured** 2016**Mileage** 25,000 km (17.1k /yr)**Transmission** Auto**Engine Cap** 1,496 cc**Road Tax** \$682 /yr**Power** 96.0 kW (128 bhp)

View specs of the Honda Vezel (2014)

**Curb Weight** 1,190 kg

**Features** Honda Sensing Technology With Navi Package/ LDW - Lane Departure Warning/ FCW- Forward Collision Warning/Engine Start Stop Feature/Intelligent Keyless.

**Accessories** Reverse Sensors, Auto Headlights/LED DRL, Auto Fold Mirrors, Multi Function Steering Etc.

**Description** Hottest SUV Sought After In The Market With Honda Sensing. Superbly Well Maintained By Only 1 Owner. Spacious Interior, Excellent Fuel Efficiency, Huge And Comfortable Head Space. Huge Boot Space. Accident Free. Flexible Loan Packages Available With Attractive Interest Rates. Welcome All Trade In. Call Our Friendly Representatives For More Information Or For A Viewing Of The Car.

**COE** \$42,801

## Seller Information

**Company**

AL Au

• dealer

• 45 yr

**Address**

210 Tu

Search

Compare



vezel

Price Range

Depreciation

2017

Vehicle Type



Home » Used Cars » Prime Motor &amp; Leasing » Honda Vezel 1.5A X

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Honda Vezel 1.5A X

Overview

Financial

Accessories

Similar

Research

Photos

Map



PRIME MOTOR &amp; LEASING



(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

• PRIME CAR RENTAL &amp; TAXI SERVICES PTE LTD • SECTION CREDIT &amp; MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD •

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

Price	\$72,900	
Depreciation	\$8,200 /yr View models with similar depreciation	?
Reg Date	31-Mar-2017 (8yrs 2mths 27days COE left)	
Manufactured	2016	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,496 cc	
Road Tax	\$682 /yr	?
Power	96.0 kW (128 bhp) View specs of the Honda Vezel (2014)	
Curb Weight	1,190 kg	?
Features	SRS Airbags, ABS, Reliable 1.5L Inline 4 Cylinder DOHC I-VTEC Engine, CVT Transmission, Keyless Start/Stop.	
Accessories	Leather Seats, Sports Rims, Audio System.	
Description	Elegant White SUV, One Owner Only, Comes With Warranty, Low Maintenance Cost, Very Well Maintained, Flexible In-house Loan Packages Available.	
COE	\$51,765	?
OMV	\$20,501	?
ARF	\$10,702	?
Dereg Value	\$50,687 as of today (change)	?
No. of Owners	1	?
Type of Veh	SUV	



Location Map



Price Ar

## Seller Information

Company	Prime » dealer » 102 v available
Address	61 Ubi Search
Location	Automat
Office No	644401
Contact Person(s)	Mark Connie

Compare

**Catherine Chong (LKK Auto)**

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 2 January, 2019 9:07 AM  
**To:** Zoom Autowerks; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Sherini Pillai; Zuhaidah Samsuri  
**Subject:** RE: Pre-Repair Inspection for SLN 4666 L // Accident on 30/12/2018 @ 10:40HR at along Junction of Xilin Avenue & Upper Changi Road East involving Vehicle Number SLN 4666 L & SHD 3682 X  
**Attachments:** SLN4666L\_30122018.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLN4666L and let us have your report urgently.

This claim will be handled by Ms Sherini.

\*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,  
**Gabriel Wee**

02012019 @ 9:19am  
Elin veh in  
murus.



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** Zoom Autowerks [mailto:zoomautowerks@gmail.com]  
**Sent:** 02 January, 2019 9:02 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Gabriel Wee <Gabriel@iii.com.sg>  
**Subject:** Re: Pre-Repair Inspection for SLN 4666 L // Accident on 30/12/2018 @ 10:40HR at along Junction of Xilin Avenue & Upper Changi Road East involving Vehicle Number SLN 4666 L & SHD 3682 X

Dear all,

Please arrange LKK for the survey.

On Wed, Jan 2, 2019, 09:01 Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

**From:** Zoom Autowerks [mailto:[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)]

**Sent:** 01 January, 2019 12:43 PM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>; Gabriel Wee <[Gabriel@iii.com.sg](mailto:Gabriel@iii.com.sg)>

**Subject:** Pre-Repair Inspection for SLN 4666 L // Accident on 30/12/2018 @ 10:40HR at along Junction of Xilin Avenue & Upper Changi Road East involving Vehicle Number SLN 4666 L & SHD 3682 X

Dear Sir/Madam,

We are instructed by Mahmood Shah Bin Ali Akbar Shah to notify you of a road traffic accident on

30/12/2018

at about 10:40HR at along Junction of Xilin Avenue & Upper Changi Road East involving our client's vehicle registration number

SLN 4666 L

and vehicle registration number SHD 3682 X driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

***Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178***

08.

Warmest Regards,

**Elin Cai**

**Zoom Autowerks Pte Ltd**

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)

***- Please note our change in mailing/registered address with effect from 1st July 2018 -***

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing,

handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	02 Jan 2019 16:52	Cim Veh Model Changed	(204611) HONDA VEZEL 1.5 1.5X CVT (A).		[A] Lau Shu Pei
2	02 Jan 2019 16:52	Cim Created	Reg No: SLN4666L. Acct Date: 2018/12/30. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Zoom Autowerkz Pte Ltd (HQ)		[A] Lau Shu Pei
3	02 Jan 2019 16:52	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] Lau Shu Pei
4	02 Jan 2019 16:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/11		[A] Lau Shu Pei
5	02 Jan 2019 16:52	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] Lau Shu Pei
6	02 Jan 2019 16:52	Label Added	(30653):Direct Settlement.		[A] Lau Shu Pei
7	02 Jan 2019 16:52	Adj Adjuster Assigned	[None] -> MARCUS CHUA		[A] Lau Shu Pei
8	15 Jan 2019 11:35	Adj Mandate Request	Cur.Reg:0.00:PODS LIABILITY: 100% REMARKS: BOLA 15 - OID changed lane		[A] VIC ALPEH
9	16 Jan 2019 09:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/11		[I] Zuhaidah Bte Samsuri
10	16 Jan 2019 09:46	Adj Mandate Set	Approved:0.00.		[I] Zuhaidah Bte Samsuri
11	13 Sep 2019 14:10	Adj Rpt Initiated			[A] JOANNE LEE KHANG MIN
12	13 Sep 2019 14:10	Cim Dtl Modified	Insured Name: -> -. Insured ID: -> -.		[A] JOANNE LEE KHANG MIN
13	13 Sep 2019 14:10	Cim Dtl Modified	JPJ Reg. Date: -> 2017/05/04.		[A] JOANNE LEE KHANG MIN
14	13 Sep 2019 14:10	Cim Details Notified			[A] JOANNE LEE KHANG MIN
15	28 Sep 2019 13:54	Adj Mandate Request	Cur.Reg:20807.45:PODS Liability: 100% Quantum: (a)COR: \$19,000.00 + (b)LOR(18a ys x \$100.00): \$1,800.00 + (c)LTA/GIA search fee: \$7.45 = Total: 20,807.45 Vehicle Model: Honda Vezel (1496cc) 14 recommendation repair days + 1PH + 2Sunday + 1P RS = 18		[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None



Go

### ACTIVITY

[04/03/2019 15:46] VIC ALPEH:

PENDING TP LOD

[04/03/2019 15:46] VIC ALPEH:

FINALIZED COR L/S \$19,000.00 with 14 DAYS

[17/01/2019 11:10] VIC ALPEH:

Alert - Adj Mandate Approved (\$40.00) - SLN4666L - Claim Handler: Sherini Pillai

Approved:0.00.

[15/01/2019 11:35] VIC ALPEH:

Adj Mandate Request Cur.Reg:0.00:PODS LIABILITY: 100% REMARKS: BOLA 15 - OID changed lane

[15/01/2019 11:35] VIC ALPEH:

FILE REVIEWED. OID Mr Raymond Lee Kwong Leng reported that he filtered lane to make a turn at the junction as he missed out the turn earlier based on his GPS when collided by TP vehicle. Seek liability mandate to III by merimen

### Merimen Billing for this case - Transaction History

Bill Paid No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2279341	13 Sep 2019 14:10:09	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLN4666L	SHD3682X	11.77

## Print Received Message

This mail is associated with :

**\*SLN4666L (MCT18120842)**  
**[SHD3682X]**

TP

MAHMOOD SHAH BIN ALI AKBAR SHAH

Dec 30 2018 10:00AM

[-]

Zoom Autowerkz Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 30/10/2019 14:41 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$20807.45) - SLN4666L - Claim Handler: Sherini Pillai

Approved:20807.45.

## Hsiao Tong (LKKAUTO)

---

**From:** Zoom Autowerks <zoomautowerks@gmail.com>  
**Sent:** Monday, 4 November 2019 10:32 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** Admin A  
**Subject:** Re: Letter of Claim for SLN 4666 L // LKK REF CC4/III19000060/Upb3

Dear Hsiao Tong,

We confirm acceptance.

Warmest Regards,

**Elin Cai**

**Zoom Autowerks Pte Ltd**

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)

***- Please note our change in mailing/registered address with effect from 1st July 2018 -***

On Mon, Nov 4, 2019 at 9:46 AM Hsiao Tong (LKKAUTO) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)> wrote:

**Without Prejudice**

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$20,700.00(all-in).**

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>

**Sent:** Thursday, 20 June 2019 10:26 AM

**To:** Zoom Autowerks <[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)>; Poh Kin (LKKAuto) <[pohkin@lkkauto.com](mailto:pohkin@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>

**Subject:** RE: Letter of Claim for SLN 4666 L LKK REF CC4/III19000060/Ufb3

Without Prejudice

Dear Elin,

We refer to your below email.

Please be informed that this matter is now handled by my colleague, Mr Poh Kin and he will get back to you for an update/offer.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**From:** Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

**Sent:** Tuesday, 18 June, 2019 10:50 AM

**To:** Vic (LKKAuto)

**Subject:** Re: Letter of Claim for SLN 4666 L

Dear Vic,

Gentle reminder.

Warmest Regards,

**Elin Cai**

**Zoom Autowerks Pte Ltd**

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)

**- Please note our change in mailing/registered address with effect from 1st July 2018 -**

On Tue, Apr 9, 2019 at 1:21 PM Zoom Autowerks <[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)> wrote:

Dear Vic,

- Without Prejudice -

Enclosed please find Letter of Claim for your kind attention.

Look forward to your favorable reply.

Warmest Regards,

**Elin Cai**

**Zoom Autowerks Pte Ltd**

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)

**- Please note our change in mailing/registered address with effect from 1st July 2018 -**

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2019 <a href="#">Edit Reg</a>		02 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$519,000.00</b> <a href="#">Edit Estimates</a>	<b>\$519,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>












































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	MAHMOOD SHAH BIN ALI AKBAR SHAH, ID: S1100920D								
Vehicle Reg. No.:	SLN4666L	Date of Loss:	30/12/2018 10:00 - :59 [19 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18120842	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD3682X	Policy No. (Claimant):	A29078572QMY						
		Excess:							
Repairer:	Zoom Autowerks Pte Ltd (HQ) 130 Bedok Reservoir Road, Eunos Spring, #08-1339, 470130 Bedok - Tel: 94507920								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/01/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (30/10/2019): Alert - Adj Mandate Approved (\$20807.45) - SLN4666L - Claim Handler: Sherini Pi...</li> <li>III_SG (16/01/2019): Alert - Adj Mandate Approved (\$0.00) - SLN4666L - Claim Handler: Sherini Pillai</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									























































## Claim Documents

\*SLN4666L (MCT18120842)  
[SHD3682X]  
TP  
MAHMOOD SHAH BIN ALI AKBAR SHAH  
Dec 30 2018 10:00AM  
[COMFORT TRANSPORTATION PTE LTD]  
Zoom Autowerks Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 15:47	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 15:47	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
30	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
31	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
32	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
33	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
34	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
56	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
57	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
58	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
59	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
60	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
61	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
62	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
63	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
64	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
65	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
66	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
67	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
68	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
69	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
70	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
71	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
72	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
73	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
74	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
75	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
76	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
77	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
78	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
79	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
80	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
81	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
82	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
83	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
84	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
85	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
86	04/03/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
87	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
88	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
89	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
90	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
91	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
92	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
93	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
94	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
95	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
96	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
97	04/03/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
98	04/03/19 15:48	General View	Load JPG	<input checked="" type="checkbox"/>
99	04/03/19 15:48	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	04/03/19 15:48	General View		<input checked="" type="checkbox"/>
101	04/03/19 15:48	General View		<input checked="" type="checkbox"/>
102	04/03/19 15:48	General View		<input checked="" type="checkbox"/>
103	04/03/19 15:48	General View		<input checked="" type="checkbox"/>
104	04/03/19 15:48	General View		<input checked="" type="checkbox"/>
105	04/03/19 15:48	General View		<input checked="" type="checkbox"/>
106	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
107	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
108	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
109	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
110	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
111	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
112	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
113	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
114	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
115	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
116	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
117	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
118	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
119	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
120	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
121	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
122	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
123	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
124	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
125	04/03/19 15:48	Reinspection Photo		<input checked="" type="checkbox"/>
126	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
127	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
128	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
129	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
130	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
131	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
132	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
133	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
134	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
135	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
136	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
137	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
138	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
139	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
140	04/03/19 15:52	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 16:53	EMAIL FROM III DD 02012019		<input type="checkbox"/>
2	02/01/19 16:53	TP GIA REPORT		<input type="checkbox"/>
3	04/03/19 15:43	TP ESTIMATE - MARKED		<input type="checkbox"/>
4	13/09/19 14:30	RENTAL RECEIPT		<input type="checkbox"/>
5	13/09/19 14:30	LTA SEARCH		<input type="checkbox"/>
6	16/12/19 12:09	WORKSHOP INVOICE		<input type="checkbox"/>
7	16/12/19 12:09	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
8	16/12/19 12:09	DISCHARGE VOUCHER		<input type="checkbox"/>
9	16/12/19 12:09	LOD		<input type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	03/01/19 08:51	Singapore Accident Statement		<input type="checkbox"/>

### Documents Checklist

**DOCUMENTS CHECKLIST**[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

^

v

**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19000060/UPB3Q2

Date: 16/12/2019

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SLN4666L Insured Vehicle No: SHD3682X  
 Date of Loss: 30/12/2018 Nature of Claim: TP Claim No: MCT18120842

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN4666L  
 Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4408976  
 Reg. Date: 04/05/2017 (Man. Year: 2016) Chassis No: RU11208976  
 Colour: Green Odometer: 23186 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm  
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,019.00	20,065.24	17,953.76	47.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,330.00	3,770.00	2,560.00	40.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>44,349.00</b>	<b>23,835.24</b>	<b>20,513.76</b>	<b>46.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>19,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>44,349.00</b>	<b>19,000.00</b>	<b>25,349.00</b>	<b>57.16</b>
<b>+ Car Rental (17.0 x S\$100.00/day) (S\$)</b>		1,700.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>20,707.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>20,700.00</b>		

### INSPECTION

Date of Assignment: 02/01/2019  
 Date Inspected: 02/01/2019 Inspected At: 15 KAKI BUKIT RD 4# 01-53  
 Repairer: Zoom Autowerkz Pte Ltd (HQ)  
 Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**SPECIAL REMARKS**

Market Value: \$75,000.00(est) less LTA Rebate: \$54,082.00(est) = Nett Value :\$20,918.00(est)

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN4666L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,151.70 FL	*892.30 FL
2	2		*FRONT BONNET HINGES	Bent	143.40 FL	*143.40 FL
3	1		*FRONT BONNET INSULATOR	Torn	168.00 FL	*168.00 FL
4	1		*SET FRONT BONNET INSULATOR CLIP	Necessary	50.00 FL	*50.00 FL
5	1		*FRONT BONNET LOCK	Serviceable	145.00 FL	*- FL
6	1		*FRONT BONNET RUBBER	Necessary	78.30 FL	*78.30 FL
7	2		*FRONT HEADLAMPS	Cracked	3,569.00 FL	*3,518.00 FL
8	2		*FRONT HEADLAMP LOWER BRACKETS	Cracked	150.60 FL	*150.60 FL
9	1		*FRONT GRILLE	Cracked	285.00 FL	*285.00 FL
10	1		*FRONT GRILLE TOP OUTER GARNISH	Cut / Cracked	195.30 FL	*195.30 FL
11	1		*FRONT GRILLE LOGO	Necessary	45.70 FL	*45.70 FL
12	1		*FRONT BUMPER	Distorted	1,085.40 FL	*801.70 FL
13	1		*FRONT BUMPER CENTRE GRILLE	Twisted	167.00 FL	*167.00 FL
14	1		*FRONT BUMPER FOG LAMP	Cracked	327.70 FL	*327.70 FL
15	1		*FRONT BUMPER FOG LAMP COVER	Twisted	45.20 FL	*45.20 FL
16	1		*FRONT BUMPER REINFORCEMENT	Bent	321.40 FL	*321.40 FL
17	2		*FRONT BUMPER SIDE RETAINERS	Bent	120.60 FL	*120.60 FL
18	1		*FRONT BUMPER TOW HOOK COVER	Missing	48.00 FL	*48.00 FL
19	1		*FRONT BUMPER UNDERCOVER	Not Necessary	225.00 FL	*- FL
20	1		*FRONT FENDERS	N/S Repair / O/S Distorted	1,160.80 FL	*580.00 FL
21	1		*FRONT FENDER INNER PANEL	Badly Dented	485.00 FL	*485.00 FL
22	1		*FRONT FENDER INNER SHIELDS	O/S Torn	100.00 FL	*50.00 FL
23	1		*FRONT FENDER WHEEL HOUSE	Repair	675.00 FL	*- FL
24	2		*FRONT FENDER WHEEL ARCH GARNISHES	Torn / Broken	976.60 FL	*420.00 FL
25	1		*FRONT SUPPORT PANEL	Repair	576.00 FL	*- FL
26	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	190.30 FL	*- FL
27	1		*FRONT SUPPORT PANEL SIDE GARNISH	Not Necessary	70.50 FL	*- FL
28	1		*HORN	Damaged	95.00 FL	*95.00 FL
29	1		*AIR CON CONDENSER	Not Necessary	748.00 FL	*- FL
30	1		*RADIATOR	Not Necessary	1,150.00 FL	*- FL
31	1		*SET WIRE HARNESS	Repair	1,855.20 FL	*- FL
32	1		*FRONT WIPER TANK	Broken	185.00 FL	*185.00 FL
33	1		*SET FRONT WIPER GARNISH	Cut	255.00 FL	*255.00 FL
34	1		*FRONT WIPER MOTOR	Not Necessary	135.00 FL	*- FL
35	1		*FRONT WHEEL RIM -R/H	Bent	1,080.32 FS	*480.00 FS
36	1		*FRONT WHEEL HUB	Bent	299.70 FL	*299.70 FL
37	1		*FRONT WHEEL BEARING	Necessary	181.50 FL	*181.50 FL
38	1		*FRONT SHOCK ABSORBER	Bent	501.20 FL	*366.20 FL
39	1		*FRONT KNUCKLE ARM	Bent	600.70 FL	*388.50 FL
40	1		*FRONT TIE ROD	Serviceable	120.50 FL	*- FL
41	1		*FRONT LOWER ARM	Buckled	426.00 FL	*392.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*POWER STEERING RACK	Serviceable	1,750.60 FL	*- FL
43	1		*STEERING RACK CROSS MEMBER	Serviceable	795.20 FL	*- FL
44	1		*FRONT STABILIZER BAR	Not Necessary	175.90 FL	*- FL
45	1		*FRONT DRIVE SHAFT -R/H	Not Necessary	985.00 FL	*- FL
46	1		*ENGINE MOUNTING -R/H	Damaged	240.00 FL	*240.00 FL
47	1		*ENGINE MOUNTING BRACKET	Serviceable	160.00 FL	*- FL
48	1		*FRONT DOOR	Dented / Bent	1,085.70 FL	*966.20 FL
49	1		*FRONT DOOR CHECKER	Not Necessary	95.00 FL	*- FL
50	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	199.00 FL	*- FL
51	2		*FRONT DOOR HINGES	Not Necessary	179.40 FL	*- FL
52	1		*FRONT DOOR INNER BOARD	Not Necessary	588.90 FL	*- FL
53	1		*FRONT DOOR LOCK	Not Necessary	213.80 FL	*- FL
54	1		*FRONT DOOR REGULATOR	Not Necessary	488.80 FL	*- FL
55	1		*FRONT DOOR REGULATOR MOTOR	Not Necessary	350.70 FL	*- FL
56	1		*FRONT DOOR RUBBER	Necessary	122.70 FL	*122.70 FL
57	1		*FRONT DOOR SIDE MIRROR ASSY	Serviceable	745.50 FL	*- FL
58	1		*FRONT DOOR PILLAR	Repair	950.70 FL	*- FL
59	1		*FRONT DOOR PILLAR INNER GARNISH	Not Necessary	155.80 FL	*- FL
60	1		*FRONT DASHBOARD	Buckled	1,280.50 FL	*892.50 FL
61	1		*SIDE AIR BAG-LH	Activated	2,600.90 FL	*1,488.10 FL
62	1		*ROOF LINING	Torn	2,888.80 FL	*1,400.50 FL
63	1		*FRONT PASSENGER AIR BAG	Activated	2,667.30 FL	*2,436.80 FL
64	2		*FRONT SAFETY BELTS	Activated	1,400.60 FL	*1,400.60 FL
65	1		*FRONT STEERING AIR BAG	Activated	2,650.00 FL	*2,110.10 FL
66	1		*AIR BAG CONTROL UNIT	Activated	1,564.40 FL	*980.00 FL
67	1		*STEERING WHEEL CLOCK SPRING	Activated	297.60 FL	*268.90 FL
68	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
69	1		*FRONT BUMPER LOWER SPOILER	Distorted	750.00 FS	*400.00 FS
70	1		*FRONT NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
71	2		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	100.00 FS	*50.00 FS
72	1		*FRONT TYRE -R/H	Serviceable	350.00 FS	*- FS
73	1		*ROCKER PANEL SIDE SKIRT	Distorted	650.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **46,767.42**    **24,737.80**  
 - List Item Discount on L Items 20.00/20.00% (S\$) **8,748.42**    **4,672.56**  
 Total Parts (S\$) **38,019.00**    **20,065.24**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	0.00
3	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	450.00	150.00
4	TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
5	TO REMOVE,REFIT AND RESET AIR BAG SYSTEMS	New	280.00	280.00
6	TO REMOVE,REPLACE AIR-CON CONDENSER ,REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	100.00
7	TO REMOVE AND REFIT DASHBOARD TO ASSIST REPAIR	New	250.00	250.00
8	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	180.00	0.00
9	TO REMOVE,REPLACE DOORS AND DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	150.00	60.00
10	TO APPLY UNDERCOATING	New	250.00	120.00
11	PANEL BEATING	New	2,000.00	1,200.00
12	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	1,400.00
13	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	350.00	100.00
Gross Labour Cost (S\$)			<b>6,330.00</b>	<b>3,770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >