

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Dec-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30M REGN NO: SHD 1573 R

1 pc	Front o/s fender	X rpa	\$	434.30
1 pc	Front o/s wheel cover	flaw	\$	114.80
			\$	549.10
		Less 20%	\$	109.82
			\$	439.28
S/NETT				
1 pc	Front o/s fender sticker	✓		\$30.00
1 set	o/s door stickers	✓	\$	100.00
1 pc	Rear o/s fender sticker	✓	\$	60.00
	Sundry		\$	50.00 20
	To check wheel alignment		\$	80.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, rear o/s door, rear o/s fender		\$	900.00 300
	To putty and spray painting on front o/s fender, o/s mirror assy, front o/s door, rear o/s door, rear o/s fender	X	\$	900.00 720
	To apply rustproofing on the repaired and replaced panels.		\$	180.00 X
			\$	<u>2,739.28</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Kalvin LKK
2/1/19 1210L
3 By,
4/5
Attn Repair pte