

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

31-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6183 E

1 pc	Front bumper <i>X repair</i>	\$	531.00
1 pc	Front bumper emblem <i>✓</i>	\$	44.00
1 pc	Front bumper centre grille <i>X</i>	\$	174.00
1 pc	Front bumper tow hook cover <i>X</i>	\$	14.00
1 pc	Front bumper inner sponge <i>X</i>	\$	110.00
1 pc	Front bumper reinforcement <i>X</i>	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>X</i>	\$	32.00
1 pc	Rear bumper <i>✓</i>	\$	696.00
1 pc	Rear bumper lower cover <i>✓</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X</i>	\$	36.00
		\$	3,158.00
Less 10%		\$	315.80
		\$	2,842.20

S/NETT

1 set	Rear bumper clips <i>✓</i>	\$	48.00
1 set	Reverse sensor <i>✓</i>	\$	280.00 <i>200</i>
1 pc	Front no. plate with casing <i>✓</i>	\$	50.00 <i>35</i>
1 pc	Front bumper clips <i>X</i>	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 <i>X</i>	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 <i>X</i>	\$	6.00

31-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6183 E

Sundry	\$ 50.00 ²⁰
To check for wiring and to focus head lamps	\$ 80.00 ^X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 ³⁰
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 ^X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$ 850.00 ⁴⁵⁰
To putty and spray painting on front bumper, rear bumper, end panel	\$ 600.00 ³⁶⁰
^X To apply rustproofing on the repaired and replaced panels.	\$ 120.00 ^X
	<u>\$ 5,286.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin Ukky

2/1/19 1225hrs

3 Pgs

L/S

A/Hr

Repair

LKK Appoint. Suits. hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damages parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: