Malmul From (Person): Flain Nyu	phopes south and	MSU ₁		02012019	4270
Estimated Cost:		Bill to:			
OD / TP WS / TP RES / OD R	FBA 87329		THE CONTRACTOR OF THE PROPERTY	BE 92108	
	a motor	Λ	Tel:	453 9903	
		DFM #01:331			
Policy No: 828736497M	KC J	Claim No: _	579777		VOV.
Sum Insured:		Excess:			
Make of Veh:		50	D.O.A.	13122018	
(Client's Record) CA / REV / REP. / REV 24 Date/Time: Quality 45(3012019 acted: MATUM	H.O.D.	Endorsement:	
Date/Time Action/Instruction	(/) Est	imate	+0-		
LBU 82ROD	- X				
GBE GOILB -	Х				
04/1/19@1.52m rens	ed to the	ine Ngu va	Meirnen.		
7 (20)	24 10 0100	0			
30/1 11 Ly 6	1400 en	201			
12/2 6/Pm P	TOOL EN	former (Red)		1.	-

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est S	ubmitted	Ad) Assigned	Adj Rpt	T. ensemble					
Main	13 Dec 2018			02 Jan 2019	Nuj rept	Adj Submi	itted	Ins Auth'ed	Status		
270011				16:27 Assign						case	
STORES OF THE PARTY OF THE PART	Main		R	eference		Claim Details		Docur			
CLAIM S	UBFOLDER DET	AILS	- Contraction	THE RESERVE OF THE PARTY OF	-	-		Docu	nents		Show All
Insured:		to interest in	KHON	G GUAN RISCUT	FACTORY			[C	reated i	by insure	r1
Main Clain	nant:		MUHA	G GUAN BISCUIT	IN ALI, ID	S) PTE LTD, C	o. Reg. N	lo.: -	Company -	95e90022	
Vehiçle Re	g. No.;		FBA8			2500 28 1		13/	12/2018	11:00 - 11	
			1000			Date of Loss:		[14	13/12/2018 11:00 - :59 [146 Months and 22 Days From		
Claim Type	e:		TD / 5	70077					LTA Reg Date (Man Yr)] B28736497MKC(COMP)		
			TP / 579977			Policy/Cover Note No.:			(Comprehensive) Coverage: 28/04/2018 - 27/04/2019		
Vehicle Re	ehicle Reg. No. (Insured): GBE9210B			108	Policy No. (Claimant):			27/			
Repairer:						Evener					
	0.548600		Ga Mot	or (HQ) Blk 32 Si	n Ming Drive	, #01-331, 5757	06 Sin Mi	The state of the s			
Handling Ir	surer:		6594 25	nsurance (Singa 40]	pore) Pte. I	.td. (HQ) - Tel:	+65 6827	7888 [Handi	ed by El	aine Nou	Siau Mei
Adjuster:			LKK Au	to Consultants P	te Ltd (HO)	- Tel: 6356 356					oldu Mel -
Adj Asg. Re	odian (Insured):		QUEK SV	WEE HOCK (), N	RIC: S14565	15I. Tel: +650	2 [I m	m.Advice du	e 03/0	1/2019]	
uj Asy. Ke	marks:		LIABILIT	Y 100% ON OI AS	SIGN KENNI	TH KONG FROM	IKK CUN	TACT MDC TAN			
ASSOCIAT	ED MAIL RECE	IVED					ERR CON	INCI MKS IAN	Ø 64539	903	
here are n	o mail for this cas	ie.						View A	dit	Compose	Case Mail
E GENERAL PROPERTY	40.50.00.00.00.00.00.00.00										
1											
ALL ASSO	CIATED TASKS					No 1	2000000	STEP OF THE			
Due Date	Priority	Гуре	Task Gr	oup Subject	Manata	View All	Search		eate New	Task	Complete
lo results.				Subject	Handler	Assigned I	Ву	Completed On	Cr	eated On	Done?

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

: 13/12/2018

: 02/01/2019

: 3.00

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Elaine Ngu Siau Mei

Date:

04 Jan 2019

Accident Date

Assignment Date

Est. Duration of Repair

Preliminary Advice

Insured Vehicle No : GBE9210B

TP Vehicle No : FBA8732P

Make

: HONDA CB400

Date of Inspection : 03/01/2019

Inspection At

: GA MOTOR (HQ)

BLK 32 SIN MING DRIVE, #01-331

SINGAPORE 575706

Point of Impact / General Description of Damages The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,450.00
Revised Amount	:S\$	931.50
Check Items (Estimated)	:S\$	1,210.50
Total	:S\$	2,142.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

0	\ Th	e vehicle	is	economical/not	economical	for	repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 26/12/2018 12:52

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Driving Experience

Mobile Number

Contact Number EMail Address

Fax Number

Gender

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	26/12/2018 09:23
Date Of Accident	13/12/2018 11:00
Exact Location Of Accident	CHOA CHU KANG AVE 1
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	FBA8732P
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD FAISAL BIN ALI
NRIC No	S8915548G
Email Address	FAISAL.AMANINA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84488972
Alternative Phone No	OFFICE-84488972
Vehicle Particulars	
Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5064766119-04
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD FAISAL BIN ALI
NRIC No	S8915548G
Date Of Birth	05/05/1989
Occupation	OUTDOOR
Date Of Driving Pass	22/09/2009

9 YEARS AND 2 MONTHS


(LOCAL) +65-84488972

FAISAL.AMANINA@GMAIL.COM

OFFICE-84488972

MALE

Sketch Plan #2 Pg. 1







Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999 2 of 3 Report No. T/20181213/2157

CONTINUATION OF REPORT

Any Pedestrian Ir	volved; No	-372113114A33		ALDER OF THE PARTY OF		
No. of Pedestrian			Use of Pe		Crossi	ng: NA
Rider	· 经基础。 2014年2月	45 July 19	等。在198	湖 湖	374	
Name	MUHAMMAD FAISA		ID No.		S8915548G	
Related Vehicle	FBA8732P (Motorcycle)				ct No.	84488972
Hospital/Clinic	NG TENG FONG GENERAL HOSPIT			Class of Driving Licence & Expiry Date		Class: 2B,2A Date of Expiry: NIL
Date Treatment	13/12/2018	AND THE RESERVE	Date Dis	charge	13/12	/2018
No. of Days gran	ted Medical Leave	03		of Injury	Sligh	t
Driver	是在4000000000000000000000000000000000000		图的对抗规则			
Name	QUEK SWEE HOCK	(ID No),	S1456515I
Related Vehicle	GBE9210B (Van)			Contact No.		98773884
Hospital/Clinic	NIL			Class Drivin Licend Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Dis	charge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree	of Injury	NIL	

Brief Details.

On 13/12/2018 at about 1100hrs, I was riding my motorcycle (FBA8732P) at Keat Hong Mirage housing estate service road and was turning out to Choa Chu Kang Ave 1. Suddenly, a van (GBE9210B) which was driving behind me collided to the rear of my motorcycle. My motorcycle rear mudguard bend in, scratches to the rear light and box.

I felt pain to my right shoulder, back body and neck. I then seek treatment at Ng Teng Fong Hospital and was given 3 days MC.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Singapore NRIC
wner ID:	5548G
ehicle Details	
ehicle No.:	FBA8732P
ehicle to be Exported:	No
tended Deregistration Date:	04 Jan 2019
ehicle Make:	HONDA
ehicle Model:	CB400
rimary Colour:	Silver
lanufacturing Year:	2006
ngine No.:	NC23E3100212
hassis No.:	JH2NC39946M200193
laximum Power Output:	-
pen Market Value:	\$6,452.00
original Registration Date:	21 Sep 2006
irst Registration Date:	21 Sep 2006
ransfer Count:	1
ctual ARF Paid:	\$968.00
ntended PARF Rebate Details	
ARF Eligibility:	No
ARF Eligibility Expiry Date:	
ARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
OE Expiry Date:	20 Sep 2026
OE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,247.00
OE Rebate Amount:	\$4,817.00
otal Rebate Amount:	\$4,817.00

The information contained herein is correct as at 04 Jan 2019











Block 32, Sin Ming Drive, #01-331, Singapore 575706 TEL: 4539903, 4539904 FAX: 4539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories.

Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.

Date: 27-12-2018

Estimated repair list for the accident motorcycle Honda CB400 V-TEC Spec.3 Vehicle No. FBA8732P

		8
1 pc	Rear mudguard	\$285.00
1 pc	Tail light	Mg \$285.00 2
1 pc	Tail cover	CM \$420.00 -
2 pc	Rear signal	Mich \$150.00 -
1 pc	Rear sport Rim	14€ \$1350.00 X
1 pc	rear disc plate	\$450.00 X
1 pc	Rear Box	Mysan 12 \$270.00 # ?
1 pc	Rear carrier	Bur \$185.00 2
1 pc	Rear No. plate	520.00 1252
	Press rear frame	An \$350.00 x 100 € 1800
	Press swing arm	108 \$250.00 ton 1501
	Towing	\$50.00 301
	Labour	\$380.00 /20/
		a de
		(Mar.)

Total:

James de

\$4450.00

Not Notherhol 1/Smy 8 1550/2 Reinny After Paint 3days



LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case 1	Notified	Est Submitted	Adj Assigned	Adj Rpt	AdJ Su	bmitted	Ins Auth'ed	Status		
Main 1	13 Dec 2018			S\$1,550.00 Edit Estimater	S\$1,5 View	tradione revision	Repo		ling for Survey ort cel Case	
М	ain	Re	ference	Cla	im Details		Docume	nts	Show All	
CLAIM SUB	FOLDER DE	TAILS				[Creat	ed by insurer]			
Insured:	KHONG G	UAN BISCUIT FA	CTORY (S) PTI	ELTD, Co. Re	g. No.: -					
Main Claimant:	минамм	AD FAISAL BIN	ALI, ID: S891	5548G						
Vehicle Reg. No.:	FBA873	2P			Date of Loss	[146 M	2018 11:00 - :59 lonths and 22 Day	The second secon		
Claim Type:	TP / 579	977			Policy/Cove Note No.:		5497MKC(COMP) (ge: 28/04/2018 -		ve)	
Vehicle Reg. No. (Insured):	GBE9210B				Policy No. (Claimant):					
					Excess:	S\$750.				
Repairer:	Ga Motor	(HQ) Blk 32 Sin I	Ming Drive, #01-	-331, 575706 S	in Ming - Te	: 6453990)3			
Handling Insurer:							d by Elaine Ngu S			
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Handled by	KENNET	н ко м G] [Fin	al Rpt due	01/02/2019]	
Driver/Custo dian (Insured):	QUEK SWE	EE HOCK (), NRI	C: S1456515I,	Tel: +659877	3884					
Adj Asg. Remarks:	LIABILITY	100% ON OI ASS	IGN KENNETH K	ONG FROM LKK	CONTACT	1RS TAN @	64539903			
ASSOCIAT	ED MAIL RE	CEIVED						View All	Compose Case Mai	
There are no	mail for this	case.								
ALL ASSO	CIATED TAS	KS ⁻				View	All Search Tasks	Create Ne	w Task Complete	
Due Date	Priority	Type Task	Group Sub	ject Handl	er Assi	gned By	Completed (On Crea	ted On Done	

Claim Documents

*FBA8732P (579977) [GBE9210B]

MUHAMMAD FAISAL BIN ALI

Dec 13 2018 11:00AM [KHONG GUAN BISCUIT FACTORY (S) PTE LTD] **Ga Motor**

Upl	oad Documents Uplo	ad Photos Compose New Letter	view	View in Brow	1000
Ass	essment Reports		1 per	page ▼	€
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	26/12/18 15:40	Accident Statement From:SC - Reg. No: GBE9210B, Claimant: KHONG GUAN BISCUIT FACTORY (S) PTE LTD	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	-	Thumbnail	Print
1	04/01/19 13:52	Adjuster Immediate Advice	0	Load HTM	
Pho	tos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/02/19 10:48	General View	0	Load JPG	•
2	14/02/19 10:48	General View	0	Load JPG	•
3	14/02/19 10:48	General View	0	Load JPG	•
4	14/02/19 10:48	General View	0	Load JPG	•
5	14/02/19 10:48	General View	0	Load JPG	•
6	14/02/19 10:49	General View	0	Load JPG	•
7	14/02/19 10:49	General View	0	Load JPG	•
8	14/02/19 10:49	General View	0	Load JPG	•
9	14/02/19 10:49	General View	0	Load JPG	•
10	14/02/19 10:49	General View	0	Load JPG	•
11	14/02/19 10:49	General View	0	Load JPG	
12	14/02/19 10:49	General View	0	Load JPG	•
13	14/02/19 10:49	General View		Load JPG	•
14	14/02/19 10:49	General View	0	Load JPG	✓
15	14/02/19 10:49	General View	0	Load JPG	•
16	14/02/19 10:49	Odometer Reading	0	Load JPG	€
17	14/02/19 10:50	Reinspection Photo	0	Load JPG	V
18	14/02/19 10:50	Reinspection Photo	0	Load JPG	•
19	14/02/19 10:50	Reinspection Photo	0	Load JPG	•
20	14/02/19 10:50	Reinspection Photo	0	Load JPG	•
21	14/02/19 10:50	Reinspection Photo	1 Load		•
22	14/02/19 10:50	Reinspection Photo	0	1 Load JPG	
23	14/02/19 10:50	Reinspection Photo	0	Load JPG	2
24	14/02/19 10:50	Reinspection Photo	0	Load JPG	•
			1 nor	page ¥	
2.3	cumentation	MCVC Toursance (Cingagore) Bto 1+d (MO)	1 per	Thumbnail	-
No 1	Finalized On 26/12/18 15:40	MSIG Insurance (Singapore) Pte. Ltd. (HQ) GIA REPORT-FBA8732P From:SC - Reg. No: GBE9210B, Claimant: KHONG GUAN BISCUIT FACTORY (S) PTE LTD	0	Load PDF	
33	26/12/18 16:05	FAX PRI TO LAW FIRM AWAITING REPLY	0	Load PDF	
3	02/01/19 11:24	FAX REPLY FROM LAW FIRM AGREE KENNETH KONG FROM LKK	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19000070/KQBS2

Date:

15/02/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B28736497MKC(COMP)

Claimant Vehicle No:

FBA8732P

Insured Vehicle No:

GBE9210B

Claim No: 579977

Date of Loss:

13/12/2018

Nature of Claim:

TP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBA8732P

Make & Model:

HONDA CB400, 399cc Super Four 21/09/2006 (Man. Year: 2006)

Engine No: Chassis No: NC23E3100212

Reg. Date:

Metallic Blue

Odometer:

JH2NC39946M200193 120240 km

Colour: Engine Capacity:

399 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Yes

Engine Modification:

Pre-accident Condition:

Front Tyre Size:

120/60 ZR17

Rear Tyre Size:

160/60 ZR17 Pirelli 2 mm

Front Left Side: Front Right Side: Pirelli 2 mm Pirelli 0 mm Rear Left Side: Rear Right Side:

Pirelli 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,420.00	1,452.00	1,968.00	57.54
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,030.00	480.00	550.00	53.40
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,450.00	1,932.00	2,518.00	56.58
Арр	roved Total (Overridden) (S\$)		1,550.00		
	Nett Amount (S\$)	4,450.00	1,550.00	2,900.00	65.17

INSPECTION

Date of Assignment:

02/01/2019

Inspected At:

Ga Motor (HQ)

Date Inspected:

03/01/2019

Blk 32 Sin Ming Drive, #01-331

Singapore 575706

Estimated Period of Repair:

3.0 days

Adjuster: KENNETH KONG Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

(Last Synchronised: 15 Feb 2019) Part Source:

HONDA CB400 399cc Super Four (Model not available in database) Parts: N/A

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for FBA8732P)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR MUDGUARD	Cracked	285.00 F	*285,00 FL
1		*TAIL LIGHT	Mtg Cracked	290.00 F	*290.00 FL
1		*TAIL COVER	Cracked	420.00 F	*420.00 FL
2		*REAR SIGNAL	Mtg Cracked	150.00 F	*150.00 FL
1		*REAR SPORT RIM	Not Necessary	1,350.00 F	*- FL
1		*REAR DISC PLATE	Serviceable	450.00 F	*-FL
1		*REAR BOX	Mtg Cracked	270.00 F	*270.00 FL
1		*REAR CARRIER	Buckled	185.00 F	*185.00 FL
1		*REAR NO. PLATE	Bent	20,00 FS	*12.00 FS
anchise	part. S=SpcNett.	L=ListItemDisc.	100		
			Sub Total (S\$)	3,420.00	1,612.00
		- List Item Dis	scount on L Items 0.00/10.00% (S\$)	0.00	160.00
			Total Parts (S\$)	3,420.00	1,452.00
	1 1 2 1 1 1 1	1 1 1 1	1 *REAR MUDGUARD 1 *TAIL LIGHT 1 *TAIL COVER 2 *REAR SIGNAL 1 *REAR SPORT RIM 1 *REAR DISC PLATE 1 *REAR BOX 1 *REAR CARRIER 1 *REAR NO. PLATE 2 *REAR NO. PLATE 3 *REAR NO. PLATE 4 *REAR NO. PLATE 5 *REAR NO. PLATE 6 *REAR NO. PLATE	*REAR MUDGUARD Cracked *TAIL LIGHT Mtg Cracked *TAIL COVER Cracked *REAR SIGNAL Mtg Cracked *REAR SPORT RIM Not Necessary *REAR DISC PLATE Serviceable *REAR BOX Mtg Cracked *REAR BOX Mtg Cracked *REAR CARRIER Buckled *REAR NO. PLATE Bent *Conception of the part of the par	1 *REAR MUDGUARD Cracked 285.00 F 1 *TAIL LIGHT Mtg Cracked 290.00 F 1 *TAIL COVER Cracked 420.00 F 2 *REAR SIGNAL Mtg Cracked 150.00 F 1 *REAR SPORT RIM Not Necessary 1,350.00 F 1 *REAR DISC PLATE Serviceable 450.00 F 1 *REAR BOX Mtg Cracked 270.00 F 1 *REAR CARRIER Buckled 185.00 F 1 *REAR NO. PLATE Bent 20.00 FS anchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 3,420.00 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recom	mended	Labour
-------	--------	--------

ticulars	Lab.Type	Repairer's	Amount
tems			
ESS REAR FRAME.	New	350.00	180.00
ESS SWING ARM.	New	250.00	150.00
WING.	New	50.00	30.00
BOUR.	New	380.00	120.00
	Gross Labour Cost (S\$)	1,030.00	480.00
	tems ESS REAR FRAME. ESS SWING ARM. WING.	ESS REAR FRAME. ESS SWING ARM. WING. BOUR. New New	Stems New 350.00 ESS REAR FRAME. New 250.00 WING. New 50.00 BOUR. New 380.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.