

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

TPLCR

Xiao Tony

Quotation

DATE : 03.01.2019
 VEH NO : SFM3090E
 MODEL : Toyota Camry
 D O A : 28.12.2018
 YR REF : SLE8063Y

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SFM3090E (TOYOTA CAMRY)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Repair</i>	1	577.50 <i>+</i>
2	Front Bumper Clips <i>new</i>	1 set	30.00 <i>✓</i>
3	Front Bumper Side Holder - LH <i>new</i>	1	94.80 <i>+</i>
4	Front Fender - LH <i>Dented</i>	1	708.70 <i>✓</i>
5	Front Fender Inner Shield - LH <i>Debond</i>	1	190.80 <i>✓</i>
6	Front Fender Inner Shield Clips - LH <i>new</i>	1 set	30.00 <i>✓</i>
7	VVTi Logo <i>new</i>	1	41.10 <i>✓</i>
8	Front Lower Arm - LH <i>Bent</i>	1	404.00 <i>✓</i>
9	Front Shock Absorber - LH <i>Bent</i>	1	349.00 <i>✓</i>
10	Front Knuckle Arm - LH <i>Bent</i>	1	432.10 <i>✓</i>
11	Front Wheel Hub c/w Bearing - LH <i>new</i>	1	195.00 <i>✓</i>
12	Front Door - LH <i>Dented</i>	1	1,439.50 <i>✓</i>
13	Front Door Lock - LH <i>new</i>	1	632.50 <i>+</i>
14	Front Door Weatherstripe - LH <i>new</i>	1	271.80 <i>+</i>
15	Front Door Inner Trim Board - LH <i>new</i>	1	537.30 <i>+</i>
16	Front Door Inner Trim Board Clips - LH <i>new</i>	1 set	30.00 <i>✓</i>
17	Rocker Panel Outer Skirting <i>Debond</i>	1	565.70 <i>✓</i>
18	Rocker Panel Outer Skirting Chrome Moulding <i>at</i>	1	198.40 <i>✓</i>
19	Rocker Panel Outer Skirting Clips <i>new</i>	1 set	30.00 <i>✓</i>
20	Rear Door - LH <i>Dented</i>	1	1,293.50 <i>✓</i>
21	Rear Door Lock - LH <i>new</i>	1	632.30 <i>+</i>
22	Rear Door Weatherstripe - LH <i>new</i>	1	262.40 <i>+</i>
23	Rear Lower Arm - LH <i>?</i>	1	395.00 <i>+</i>
24	Rear Shock Absorber - LH <i>new</i>	1	324.00 <i>+</i>
25	Rear Knuckle Arm - LH <i>new</i>	1	454.00 <i>+</i>
26	Rear Wheel Hub c/w Bearing - LH	1	185.00 <i>+</i>
27	Rear Bumper <i>Repair</i>	1	655.20 <i>+</i>
28	Rear Bumper Clips <i>new</i>	1 set	30.00 <i>✓</i>

RE: ESTIMATE FOR ACCIDENT REPAIR SFM3090E (TOYOTA CAMRY)

29 Rear Bumper Side Holder - LH *Not new* 1 103.10 *X*
 5987.8
 4475.85 Less 25%
 \$ 8,357.03

S/NETT ITEMS

1 Front Wheel Rim - LH *ut* 850.00 *600*
 2 Front Tyre - LH *not new* 280.00 *X*
 3 Rear Wheel Rim - LH *ut* 850.00 *600*
 4 Rear Tyre - LH *Not new* 280.00 *X*

Total Parts \$ 10,617.03

LABOUR CHARGE

1 To knocking & pull out front & rear portion & renew above parts \$ 1,200.00 *800*
 2 To putty & spray up paint works \$ 1,800.00 *1300.*
 3 To check wiring \$ 100.00 *30*
 4 To remove reverse sensor \$ 100.00 *50.*
 5 To transfer front & rear door fittings \$ 300.00 *160.*
 6 To dismantle front & rear undercarriage \$ 750.00 *220.*
 8 To perform wheel alignment \$ 150.00 *80.*

Total Labour \$ 4,400.00

Grand Total \$ 15,017.03

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 8315.85
4/5: 6650.
06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: