

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0009/2019/JE
Date : 3-Jan-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lee Ming Shu
Address : 5 Fernvale Close
: #19-10
Singapore 797487
Telephone : HP +65 9023 8134
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SLC 3139 G**
Model Code : Audi A4 2.0 SEDAN TFSI
Model / Year : 25/5/2018
Engine No : CVK 057897
Chassis No : WAUZZZF43JA138605
Mileage : 6144 KM
Date In : 2-Jan-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Jan-19
Place of Accident : Junction of Finlayson Green & raffle Quay

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 3139 G.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 X <i>nn</i>
2	To remove and transfer RHS front door's multi-lock system and power window devices.	\$ 280.00 /
3	To dismantle front bumper, RHS front fender, RHS front door. Cut out and reweld RHS sill panel and RHS lower A Pillar. To Renew RHS front fender, RHS wing mirror assy and RHS front door. Re-orgnise crash management components. Reinstall all parts removed.	\$ 5,100.00 <i>2000</i> <i>2500</i>
4	To respray front bumper, <i>X</i> RHS front fender, <i>550 /</i> RHS wing mirror cover, <i>200</i> RHS front door, <i>150</i> RHS sill panel and <i>550</i> RHS lower A Pillar. <i>550</i>	\$ 3,800.00 <i>1950</i> <i>1800</i>
5	To renew RHS front rims and carry out wheel alignment.	S/N \$ 280.00 /
6	To carry out diagnostic check.	S/N \$ 192.00 /
TOTAL LABOUR CHARGES		: \$ 10,132.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 3139 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	Front fender - RH <i>Repair</i> X	\$ 700.00	
2	Front fender attachment parts X	\$ 48.00	
3	Front fender end plate - RH X	\$ 45.00	
4	Front fender bracket - RH X	\$ 32.00	
5	Front fender retaining bracket - RH X	\$ 45.00	
6	Front fender center bracket - RH X	\$ 29.00	
7	Front fender end support - RH X	\$ 107.00	
8	Front wheel housing liner - RH X	\$ 220.00	
9	Front wheel housing liner attachment parts X	\$ 82.00	
10	Front wheel arc spoiler trim-RH X	\$ 66.00	
11	Front fender end plate-RH X	\$ 33.00	
12	Front stone chip guard-RH <i>MC</i>	\$ 46.00	
13	Front fender ledge cover-RH X	\$ 28.00	
14	Front fender ledge top cover-RH X <i>MC</i>	\$ 21.00	
15	Front door-RH <i>MC</i>	\$ 2,152.00	
16	Front outer door seal-RH <i>MC</i>	\$ 185.00	
17	Bonding agent <i>MC</i>	\$ 43.00	
18	Cleaning solution <i>MC</i>	\$ 64.00	
19	Applicator <i>MC</i>	\$ 7.00	
20	Front door attachment parts-RH ?	\$ 488.00	
SUB - TOTAL SPARE PARTS		\$ 4,441.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 3139 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	Front door catch-RH ?	\$	96.00
22	Front door catch cover-RH ?	\$	13.00
23	Front window regulator without motor-RH ?	\$	250.00
24	Front exterior mirror mounting-RH BT	\$	824.00
25	Front mirror cap-RH MS	\$	220.00
26	Front mirror glass-RH ?	\$	1,553.00
27	Data plate for tyre pressure ML	\$	35.00
28	Data tag ?	\$	423.00
29	Sticker with pictogram for air bag ?	\$	23.00
30	Front door trim-RH X NN	\$	41.00
31	Front window Slot seal with trim strip chrome-RH Cut	\$	280.00
32	Front window trim strip guide-RH X NN	\$	235.00
33	Front sectional part -side member-RH Bnc.	\$	1,907.00
34	Front sill trim strip-RH ?	\$	109.00
35	Rubber valve 4	\$	13.00
36	Acrylic sealant ML	S/N \$	180.00
37	Cavity wax	S/N \$	140.00
38	Stone chip	S/N \$	180.00
39	Front rim-RH Cut		TBC
40	Sundries ?	\$	800.00
TOTAL SPARE PARTS		\$	11,763.00
TOTAL LABOUR CHARGES		\$	10,132.00
GRAND TOTAL		\$	21,895.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Eno Qi y.

Surveyed Date

:

Authorised Date

:

8 Days.

Excess Cost

:

Liability

:

Remarks

:

before paint photos.

07/1/2019

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant