



SH 8159G

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,600.00
	Spray Painting Charge			\$ 1,400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Transfer of Door			\$ 120.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Remove/Refix Dashboard			\$ 450.00
	Remove/Refix Front Windscreen Glass			\$ 120.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
	Re-set Frt ABS System			\$ 200.00
	Re-set Frt Power Window System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code		2180.00	\$ 480.00
	TOTAL LABOUR			\$ 5,330.00
	ESTIMATE TOTAL			\$ 25,921.88
	03/01/2019 @ 1100hrs LKK Auto 1/Sum @ 12 days.  LKK Auto		Supp 17205.40 1110.40 18315.80 4514650/-	27,032.28
				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.