



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLE1912T
Date of Accident : 29 December 2018

Miss Cheng Sheau Ping

Date : 02 January 2019

Estimate To Repair SGH9274S - Toyota Corolla Altis 1.6
Chassis No : MR053ZEC107122860

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 499.00
02	2 ps	rear bumper side retainers @ \$28.00	\$ 56.00
03	1 pc	rear end panel	\$ 902.70
04	1 pc	rear end panel inner trim	\$ 98.10
05	6 ps	rear end panel inner trim clips @ \$4.30	\$ 25.80
			\$ 1,581.60
		Less 25 %	\$ 395.40
			\$ 1,186.20
		<u>SPECIAL NETT ITEMS</u>	
06	1 set	rear bumper reverse sensor	\$ 300.00
			\$ 300.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 80.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00
03		Putty and spray painting of the affected portion.	\$ 400.00
			\$ 1,080.00
		Total	\$ 2,566.20
			1386.25
			200
			1109.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Not Authorised
LKK
2/5 \$1100/-
3 days.
3/1/19
Theophile Atkinson

3/1 - confirmed with
marcus.