



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

D.O.A: 31 DECEMBER 2018

04 JANUARY 2019

OWNER: AW LI YING MERYL

REG NO.: SLS 3133 M

MAKE/MODEL: MERCEDES BENZ GLA 180

not authorized
lhu
~~2/5 @ 5000~~
Hdy.
 3/1/19 *John-Philip Atkinson*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
	<u>LIST ITEMS</u>	
1	Front headlamp -LH	\$ <i>CAR</i> 2,455.60
1	Front headlamp side garnish	\$ <i>11</i> 68.50 <i>X</i>
1	Front bumper <i>1415-32</i>	\$ <i>Del/Born</i> 1,655.30 ✓
1	Front bumper badge	\$ <i>REU</i> 58.50 ✓
1	Front bumper clip (1 set)	\$ <i>REU</i> 80.00 ✓
1	Front bumper side grille	\$ <i>17</i> 89.60 <i>X</i>
1	Front bumper side retainer	\$ <i>Best</i> 35.00 ✓
1	Front bumper side arch garnish	\$ <i>11</i> 180.90 <i>X</i>
1	Front bumper top seal	\$ <i>REU</i> 110.20 ✓
1	Front fender -LH <i>1020.25</i>	\$ <i>DD/REU</i> 1,050.00 ✓
1	Front fender inner shield	\$ <i>Torn</i> 241.60 ✓
1	Front fender inner shield clip (1 set)	\$ <i>REU</i> 90.00 ✓
1	Front fender wheel arch garnish	\$ <i>garnish</i> 285.00 ✓
1	Front door -LH	\$ <i>11</i> 2,235.00 <i>X</i>
1	Front door rubber	\$ <i>11</i> 295.00 <i>X</i>
1	Front wheel hub bearing	\$ <i>17</i> 587.80 <i>X</i>
1	Front shock absorber	\$ <i>17</i> 781.60 <i>X</i>
1	Front knuckle arm	\$ <i>11</i> 1,027.10 <i>X</i>
1	Front lower arm	\$ <i>11</i> 705.50 <i>X</i>
1	Front wheel rim	\$ <i>A</i> 1,850.00 <i>X</i>
		\$ 13,882.20
	Less 10%	\$ 1,388.22
		\$ 12,493.98

5791.49
102

5212.32

SPECIAL NETT ITEMS

1	Front tyre	\$ 11	450.00 X
		\$	450.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00 20
2	To remove and refit front undercarriage.	\$ 11	400.00 X
3	To conduct wheel alignment.	\$ 11	180.00 X
4	To remove, replace doors and damaged parts, transfer all fittings to new door.	\$ 11	180.00 X
5	To apply undercoating.	\$	150.00 30
6	Panel beating.	\$	1,600.00 400
7	To re-spray painting on the affected areas.	\$	1,500.00 600
8	To diagnose erase fault memory after repair.	\$	350.00 80
		\$	4,440.00

1130
6342.32

GRAND TOTAL : **\$ 17,383.98**

UKK Auto Consultants hence notify the Repairer of the following:

- To be resurveyed before/after spray painting
- To identify damaged part(s) during resurvey
- Parts requirements must be confirmed
- To be surveyed on a "Without Prejudice" basis
- No liability for damage(s) is allowed
- Supplemental parts(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: