

ATTN: Ler



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower, Singapore 068811 Attn: Motor Claims Contact No 63387288	Cust No/Name	/Mr Ang Swee Kok(Hong Ruiguo)
	Reg No/Reg Date	SJU667Y / 31/07/2017
	Date In/Mileage	02/01/2019/ 0
	Chassis No	KNAFX411MH5676369
	Engine No	G4FGGH654499
	Make/Model	KIA/FORTE K3 1.6 A EX BRQ
	Colour/Trim	ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F000008	Credit	03/01/2019/ 08:34	DS	218 / MarsLer	16355

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 WHEEL BALANCING PER WHEEL			11	50.00
S MIPNT88088 COMPUTERIZED WHEEL ALIGNMENT				180.00
S MIPNT88088 TO CHECK LIGHTNING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088 REVERSE SENSOR SET			11	280.00
S MIPNT88088 TO REPLACE REAR BUMPER, REAR BUMPER CENTER, ETC. STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS		600		1200.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS		600		1260.00
M KS 86611 A7 800 COVER - REAR BUMPER	1.00	688.00	0.00	688.00
M KS 86695 A7 800 COVER - REAR BUMPER,	1.00	347.00	0.00	347.00
M KS 86614 A7 001 RH, BRACKET - REAR BU	1.00	29.00	0.00	29.00
M KS 86613 A7 001 LH, BRACKET - REAR BU	1.00	29.00	0.00	29.00
M KS 92406 A7 500 RH REFLECTOR REFLEX	1.00	99.00	0.00	99.00
P KS 0G032 50 037A CLIP, BUMPER	10.00	2.00	0.00	20.00
M WRT900446 WHEEL DISC ASSY	1.00	1480.00	0.00	1480.00
Z NOTES ACCIDENT ON 28/12/2018 ALONG FIRST LINK AFTER WOODLANDS CHECKPOINT OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP# SGQ1542Z TP INS: AXA				

Estimate

not allowed 3 days
 take photo before party
 8/1/19
 74610000/

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Confirm & accepted by	Parts	2,692.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	3,050.00
	Others (Lub, etc)	0.00
	Sundry	0.00
	Total (w/o GST)	5,742.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.