

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

2-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6233 U

1 pc	Wheel cover	\$	116.00	/scr
1 pc	Front o/s fender	\$	384.00	xr
1 pc	Front o/s fender inner shield	\$	120.00	DEF
1 pc	o/s mirror Assy	\$	590.00	BR
		\$	1,210.00	
		Less 10%	\$	121.00
			\$	1,089.00
S/NETT				
1 pc	Front o/s fender innershield clips	\$	28.00	XNN
	Sundry	\$	50.00	NN
	To check and focus o/s head lamp lights	\$	30.00	xNN
	To do wheel alignment	\$	80.00	60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	450.00	180
	To putty and spray painting on front o/s fender, o/s mirror	\$	350.00	230
	To apply rustproofing on the repaired and replaced panels.	\$	80.00	40
		\$	2,157.00	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

NAZ LKY
16/1/19 1500
LIS
2 DAYS
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____