

ASS. REC. BY:

REF

CS/CTI19000135/ Utd3 72

Special Instruction:

Surveyor
Menmen

Marius

ASSIGNMENT (Office)

From (Person):

Chong Jern Gen

of

CIF

Date/Time:

3/1/19 @ 3.20pm

Estimated Cost:

Bill to:

OD (T) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 9481A

Insured:

SKJ 7181G

at Workshop n/s:

Focus Auto

Tel:

68869097

of

1 Kaki Bukit Ave 6 # 02-48/50

Policy No:

DMPCSN3029 0718011

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 30/12/2018

CA / REV / REP. / REV 24 HRS

up

04/01/2018

H.O.D. Endorsement:

Date/Time:

3.20pm @ 3/1/19

Person Contacted:

Ms. Sin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 9481A - X

SKJ 7181G - X

REF: CTI

ASSIGNMENT

From:

Date:

04/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLM 9481A

at Workshop n/s

Focus Auto

of

1kaki Bukit Ave 6 #02-48/50

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lump Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

lup

LTA 48676
Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM 9481A

Yr Regn:

4.17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Mazda 3

C.C. 1496

Colour:

Gray

A/C: Insured / Std / NI / NA

Sp. Reading:

134877

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A8H0149858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/60216

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

roadstone

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/12/18

D.O.I.

4/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 2/5.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/1/19

Carved 4/5 \$2500 with air way

(Red: 1603.20, 39%)

RECEIVED 08 JAN 2019

Date/Time, File Pass to?



Prel. Report

1) 8/1 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

) TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

2500)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Dec 2018		03 Jan 2019 15:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	AIK CHUAN CONSTRUCTION PTE LTD, Co. Reg. No.: 198202522W		
Main Claimant:	ONESTO LEASING PTE LTD, Co. Reg. No.: 201814843R		
Vehicle Reg. No.:	SLM9481A	Date of Loss:	30/12/2018 20:00 - :59 [20 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	DMPCSN30290718011 (Comprehensive) Coverage: 02/05/2018 - 01/05/2019
Vehicle Reg. No. (Insured):	SKJ7181G	Policy No. (Claimant):	5103229513
		Excess:	S\$0.00
Repairer:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay, 417883 Kaki Bukit - Tel: 68869097		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/01/2019]		
Driver/Custodian (Insured):	LIM KWANG HENG (55 / Male), NRIC: S1581702Z		
Adj Asg. Remarks:	To conduct pre repair inspection		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Our Ref: 18/18/19/VC05/021278 RE: ACCIDENT INVOLVING SLN 6623 Y & GBC 2828 B ON 29/12/2018 ALONG PIE TOWARDS TUAS AT ABOUT 1900 HOUR

From: ONG LI LI (llong@lonpac.com)

To: focus.autopteltd@yahoo.com.sg; assignments@lkkauto.com; admin-d@lkkauto.com

Cc: mt_claim@lonpac.com

Date: Wednesday, 2 January 2019 12:13 PM +08

Without Prejudice

Dear Ms Sin

Thank you for your reply.

Dear Catherine/Nivitha

Please arrange Marcus Chua to conduct TP survey.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Focus Auto [mailto:focus.autopteltd@yahoo.com.sg]

Sent: Wednesday, 2 January, 2019 12:08 PM

To: ONG LI LI

Cc: MT_Claim_SG

Subject: Re: ACCIDENT INVOLVING SLN 6623 Y & GBC 2828 B ON 29/12/2018 ALONG PIE TOWARDS TUAS AT ABOUT 1900 HOUR

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:201004495R RCB NO:201004495R

*Not Allowed
4/1/19
Take M. Alford
1/5 \$2500/2
Haley.*

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 6389 6111

FAX: 6222 1033

ATTN: Motor Claim Department

Estimate No: EST0000781

Date: 02 Jan 2019

Policy No: 5103229513

Veh Reg No: SLM9481A

Make/Model: MAZDA 3 SEDAN 1.5 AT
EU6

Chassis No: JM6BN22A8H0149858

Engine No: P520441482

Reg. Date: 18-04-2017

Your Ref No: SLM9481A

Claim Type: Third Party

Accident Date: 30-12-2018

TP Veh Reg No: SKJ7181G

Estimate Repair Cost for Vehicle No :SLM9481A

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
MAZDA 3				
List Price				
1 Rear Bumper	950.0000	1 PC	950.00	—
2 Rear Bumper Side Retainer <i>ols</i>	48.0000	1 PC	48.00	—
3 Rear Bumper Reinforcement	486.0000	1 PC	486.00	X
4 Rear Bumper Reflector RH	52.0000	1 PC	52.00	—
5 Rear Bumper Towing Cover	48.0000	1 PC	48.00	—
6 Rear Bumper Lower Clipse	5.5000	2 PC	11.00	X
7 Rear End Panel <i>458</i>	659.0000	1 PC	659.00	—
8 Rear Tail Lamp RH	750.0000	1 PC	750.00	—
			3,004.00	
		Less 20%	600.80	2,403.20
Labour				
9 Panel Beating	850.0000	1 PC	850.00	600
10 Check Wiring	60.0000	1 PC	60.00	20
11 Rust Proofing	60.0000	1 PC	60.00	50
12 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	50
13 To Spray Painting	650.0000	1 PC	650.00	600
			1,700.00	1,700.00
		Total	S\$ 4,103.20	

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED AND THREE AND CENTS TWENTY ONLY

The Repairer of the following:

- To resurvey & resurvey spray painting
- To survey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

For FOCUS AUTO PTE LTD

Focus Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Auto Bay

#02-50 Singapore 417883

Tel: 66349695

AUTHORISED SIGNATURE

P-2303

202

1842-4

31174

2528

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

4843R

Vehicle Details

Vehicle No.:

SLM9481A

Vehicle to be Exported:

No

Intended Deregistration Date:

31 Dec 2018

Vehicle Make:

MAZDA

Vehicle Model:

MAZDA3 SEDAN 1.5 AT EU6

Primary Colour:

Grey

Manufacturing Year:

2017

Engine No.:

P520441482

Chassis No.:

JM6BN22A8H0149858

Maximum Power Output:

88.0 kW (118 bhp)

Open Market Value:

\$14,476.00

Original Registration Date:

18 Apr 2017

First Registration Date:

18 Apr 2017

Transfer Count:

1

Actual ARF Paid:

\$9,476.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

17 Apr 2027

PARF Rebate Amount:

\$7,107.00

Intended COE Rebate Details

COE Expiry Date:

17 Apr 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,101.00

COE Rebate Amount:

\$41,569.00

Total Rebate Amount:

\$48,676.00

The information contained herein is correct as at 31 Dec 2018

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19000135/UTD3N2

Date: 08/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30290718011	
Claimant Vehicle No :	SLM9481A	Insured Vehicle No :	SKJ7181G	
Date of Loss:	30/12/2018	Nature of Claim:	TP	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM9481A	Engine No:	P520441482
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0149858
Reg. Date:	18/04/2017 (Man. Year: 2017)	Odometer:	134977 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,403.20	1,842.40	560.80	23.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,320.00	380.00	22.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,103.20	3,162.40	940.80	22.93
Approved Total (Overridden) (\$\$)		2,500.00		
(\$\$)	4,103.20	2,500.00	1,603.20	39.07
+ GST 7.00/7.00% (\$\$)	287.22	175.00	112.22	39.07
Nett Amount (\$\$)	4,390.42	2,675.00	1,715.42	39.07

INSPECTION

Date of Assignment:	03/01/2019	
Date Inspected:	04/01/2019	Inspected At: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts: 143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM9481A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	950.00 FL	*950.00 FL
2	1		*REAR BUMPER SIDE RETAINER O/S	Bent	48.00 FL	*48.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	486.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR RH	Cracked	52.00 FL	*52.00 FL
5	1		*REAR BUMPER TOWING CVER	Torn	48.00 FL	*48.00 FL
6	2		*REAR BUMPER LOWER CLIPSE	Not Necessary	11.00 FL	*- FL
7	1		*REAR END PANEL	Dented	659.00 FL	*455.00 FL
8	1		*REAR TAIL LAMP RH	Cracked	750.00 FL	*750.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,004.00	2,303.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	600.80	460.60
Total Parts (\$\$)	2,403.20	1,842.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	850.00	600.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	50.00
4	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
5	TO SPRAY PAINTING	New	650.00	600.00
Gross Labour Cost (S\$)			1,700.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >