

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5812E**AAD1812-251***Not Authorized
61 Sup @ 1500/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5812E

VF1ABL15AUC281417

RENAULT

LATITUDE

30.12.2018

AIG

6/3/2015

PART		LIST	
1	FENDER PANEL REAR RH	\$	<i>17</i> 3,299.13 X
1	FENDER PANEL INNER TRIM REAR	\$	<i>12</i> 671.45 X
1	WHEELARCH REAR RH	\$	<i>12</i> 543.47 X
1	ROCKER PANEL INNER GARNISH RH	\$	<i>12</i> 466.51 X
1	ROCKER PANEL INNER RH	\$	<i>17</i> 1,024.79 X
1	ROCKER PANEL CENTER RH	\$	<i>17</i> 990.25 X
1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
1	BUMPER LOWER REAR	\$	<i>12</i> 768.84 X
1	BUMPER BRACKET CTR REAR	\$	<i>12</i> 113.47 X
1	BUMPER BRACKET SIDE RH REAR	\$	<i>12</i> 135.97 X
1	BUMPER RETAINER RH REAR	\$	<i>12</i> 44.99 X
		\$	9,167.33
10%		\$	916.73
		\$	8,250.60

Specical Nett

1SET	PARKING AID	\$	<i>12</i> 700.00 X
1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 ✓
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 X

TOTAL \$ 947.00

Trans-cab Auto Services Pte Ltd**AAD1812-251**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5812E

TOTAL PARTS	\$	9,197.60
--------------------	-----------	-----------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	300/
Putty and spray painting of the affected portion.	\$	4,200.00	440/
To rust-proofing of the affected areas.	\$	170.00	nn X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	80/
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	10/
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	380.00	nn X

TOTAL	\$	10,570.00
--------------	-----------	------------------

Over All Total	\$	19,767.60
-----------------------	-----------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

LUMP SUM (REPAIR DAY)**15 DAYS****2 days**