



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Siaw Kah Swee (Xiao Jiarui) Blk 168A Punggol East #07-379 Singapore 821168 Contact No	Cust No/Name	LCV04802/Mr Siaw Kah Swee (Xiao Jiarui)
	Reg No/Reg Date	SLW6973P / 28/02/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MJ5764183
	Engine No	G4FGHH694172
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV04802	CRDVCH	02/01/2019/ 13:24		465 / Tay Jian Ye	41966			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								825 1650.00
TO RENEW REAR BUMPER, AIR DAM REPAIR END PANEL								✓ 60.00
E PNT88000								✓ 1260.00
TO TRANSFER REAR PARKING SENSOR TO NEW PART								✓ 30.00
E PNT98000								✓ 200.00
PAINT WORK SPRAY REAR BUMPER AND AIR DAM, LH REAR BENDER								80.00
A 54900099								✓ 20.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
TO APPLY ANTI CORROSION								
M SUNDRY								
SUNDRIES								
M NEW K3 METAL STREAM MST					1.00	1177.00	00.00	de 1177.00
M BRACKET-RR BUMPER SIDE MTG,LH					1.00	29.00	00.00	re 29.00
M BRACKET-RR BUMPER SIDE MTG,RH					1.00	29.00	00.00	x 29.00
M STAY-RR BUMPER LH					1.00	120.00	00.00	? 120.00
M BEAM-RR BUMPER					1.00	318.00	00.00	? 318.00
M BRACKET-RR BEAM LWR MTG					2.00	5.00	00.00	? 10.00
M BRACKET-RR BEAM LWR,CTR					1.00	5.00	00.00	? 5.00
M COVER-RR BUMPER					1.00	688.00	00.00	de 688.00
M COVER-RR BUMPER,CTR					1.00	347.00	00.00	? 347.00
M ULTRASONIC SENSOR ASSY-P.A.S					1.00	177.00	00.00	re 177.00
SURVEYOR NAME: <u>Tan Jian 97495745</u>								
SURVEYOR SIGNATURE: <u>[Signature]</u>								
DATE: <u>14/1/19 P 1640 WP</u>								
REMARKS: <u>Resury before paint</u>								
<u>@3-4 days</u>								

Estimate

Confirm & accepted, hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

No alteration/modification(s) is allowed

Supplementary item(s) must be resurveyed and

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts and labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheques. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Nett 6,200.00
7% GST on 6200.00 434.00
Total Payable 6,634.00