

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0008/2019/GW
Date : 3-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no: SHC 5187 B

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Jun HanSung
Address : 967 Bukit Timah Road
#05-13
Singapore 589663
Telephone : (HP) 84945624
Type of Claim : Third Party Claims
Policy No. : 1800060456
Vehicle No : **S 9917 CD**
Model Code : Audi A4 Sedan 2.0 TFSI
Model / Year : Jun-18
Engine No : CVK 061090
Chassis No : WAUZZZF43JA163696
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Jan-19
Place of Accident : Lower Delta Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle S 9917 CD

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 500
3	To respray rear bumper.	\$ 800.00 550
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 2,252.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. S 9917 CD

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
1	REAR BUMPER / DL	\$	2,015.00
2	REAR BUMPER FIXING PARTS X NN	\$	66.00
3	REAR BUMPER SECURING PLATE ?	4 \$	60.00
4	REAR BUMPER SEALING PLATE ?	4 \$	10.00
5	REAR BUMPER SECURING STRIP ?	\$	203.00
6	REAR BUMPER SPOILER ?	\$	227.00
7	REAR LIGHT REFLECTOR LIGHT-LH/RH X NN 2	2 \$	76.00
8	REAR BUMPER CARRIER ?	\$	819.00
9	REAR BUMPER SEAL AK ?	2 \$	25.00
10	REAR BUMPER GUIDE SECTION-LH X	\$	40.00
11	REAR BUMPER GUIDE SECTION-RH X	\$	41.00
12	REAR BUMPER UPPER GUIDE SECTION-RH/LH X NN	2 \$	40.00
13	REAR SENSOR / DM	2 \$	462.00
14	REAR SENSOR SEAL RING / NL	4 \$	12.00
15	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS CHARGES		\$	4,396.00
TOTAL LABOUR CHARGES		\$	2,252.00
GRAND TOTAL		\$	6,648.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Gene Qian

08/1/19

before print photos.

3 Days.

Please Note

: This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant