

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1465/2018/GW
Date : 28-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

7 days exclude 1 Sunday - ok

2 Feb - jb

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Megan Lee Cheow Eng
Address : 31 Mount Sinai Rise
#19-07
Singapore 276953
Telephone : HP +65 96619698
Type of Claim : Own Damage Claims
Policy No. : 1800079813
Vehicle No : **SCZ 7728 G**
Model Code : Audi A4 Sedan 2.0 TFSI S-tronic
Model / Year : Jul-18
Engine No : CVX 063922
Chassis No : WAUZZZF43JA187996
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Dec-18
Place of Accident : ICON @ Pasir Pangjang

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCZ 7228 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$	360.00	
2	To remove and transfer rhs rear door's multi-lock system and power window devices.	S/N \$	280.00	\$ 280.00
3	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims. Lugagge compartment trims. Dislodge roof liner and disengage curtain air bag etc.	S/N \$	1,400.00	\$ 1,400.00
4	To remove and renew rhs 1/4 glass and rear windscreen for fender renewal.	S/N \$	600.00	
5	To dislodge and reinstall rear wire harness for tail lights, fuse units, battery manager, fuse and relay trays, and electrical components.	S/N \$	1,400.00	
SUB = TOTAL LABOUR CHARGES		:	<u>\$ 4,040.00</u>	<u>\$ 1,680.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCZ 7228 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
	<i>c/f</i>		1680
6	To dismantle rear bumper, rear lid and rhs rear door. Cut out and reweld rhs rear fender. Renew rhs rear door. Reorganise crash management components. Reinstall all parts removed.	\$ 5,400.00	\$ 2,000.00
7	To respray rhs rear door, door handle, rhs rear fender, rhs sill panel, door entrances, roof channel, drain channel and end panelling. To carry out joint works and stone chip treatment.	\$ 4,100.00	\$ 1,750.00
8	To renew rhs rear rim and carry out wheel alignment.	\$ 280.00	
9	To carry out diagnostic check.	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 14,012.00	\$ 5,622.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCZ 7228 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	REAR DOOR-RH	\$ 1,928.00	\$ 1,542.40
2	REAR DOOR OUTER SEAL-RH	\$ 176.00	\$ 140.40
3	BONDING AGENT	\$ 43.00	
4	CLEANING SOLUTION	\$ 64.00	
5	APPLICATOR	\$ 7.00	
6	REAR DOOR SEALING STRIP-RH	\$ 14.00	
7	REAR DOOR ATTACHMENT PARTS-RH	\$ 488.00	
8	REAR DOOR CATCH-RH	\$ 105.00	\$ 84.00
9	REAR DOOR CATCH COVER-RH	\$ 12.00	
10	REAR DOOR HANDLE TRIM PLATE-RH	\$ 22.00	
11	REAR DOOR HANDLE HOUSING-RH	\$ 7.00	
12	REAR DOOR HANDLE EXTERIOR-RH	\$ 33.00	
13	REAR DOOR MOUNTING BAR-RH	\$ 143.00	
14	REAR SIDE PANEL-RH	\$ 2,347.00	\$ 1,525.60
15	REAR WINDOW	\$ 1,014.00	
16	REAR WINDOW PRIMER	2 \$ 37.00	
17	REAR SIDE WINDOW-RH	\$ 541.00	
18	REAR SIDE WINDOW TRIM STRIPS CHROME-RH	\$ 426.00	
19	REAR ALUMINIUM-RH	\$ 645.00	
20	RUBBER VALVE	4 \$ 12.00	
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,064.00	\$ 3,292.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SCZ 7228 S**

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remark	
		<i>c/f</i>	\$	3,292.40
21	REAR WHEEL HOUSING LINER-RH	\$ 215.00		
22	REAR WHEEL HOUSING LINER ATTACHMENT PARTS-RH	\$ 78.00		
23	ACRYLIC SEALANT	\$ 180.00	\$ 180.00	
24	CAVITY WAX	\$ 140.00	\$ 140.00	
25	STONE CHIP	\$ 180.00	\$ 180.00	
26	METAL FILLER POWDER	\$ 280.00	\$ 280.00	
27	SUNDRIES	\$ 800.00	\$ 3.20	
TOTAL SPARE PARTS CHARGES		\$ 9,937.00	\$ 4,075.60	
TOTAL LABOUR CHARGES		\$ 14,012.00	\$ 5,622.00	
GRAND TOTAL		\$ 23,949.00	\$ 9,697.60	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 March 2019 9:59 AM
To: 'Boo seng yak'; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SCZ7728G - OD AIG - SURVEYED 3 JAN 19

Dear Mr Boo,

Confirm repair cost of \$9,697.60 before excess \$500 and GST @ 7 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, 2 February 2019 4:44 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SCZ7728G - OD AIG - SURVEYED 3 JAN 19

Hi Adrian and all,

Revised estimate attached.

Please confirm repair cost of \$9697.60 @ 7 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SCZ 7228 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1465/2019/MAS

28 March 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SCZ 7228 S, Audi A4 Sedan 2.0 TFSI

With reference to the above-mentioned vehicle, no. **SCZ 7228 G**, claimant, **Ms. Megan Lee Cheow Eng**, please find the related document per attached.

1. A copy of the Original invoice no. 85013590 – S\$9,841.43
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SCZ 7228 S

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SCZ7228S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1465/2018/TF
22 January 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF43JA187996
Vehicle Regn No. : **SCZ7228S**
Vehicle Mileage : 6297KM
Vehicle Owner : Mr. Megan Lee Cheow Eng
Certificate No : 1800079813
Own Damage Excess : S\$ 535.00 (inclusive of 7% GST)
Accident Date : 27/12/2018
Place : ICON @ Pasir Panjang
Repair Cost : \$ 9,841.43
WIP No. : 37611
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 22/1/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2019		03 Jan 2019 16:21 Edit Adj Rpt	S\$9,697.60 Edit Estimates	S\$9,697.60 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MEGAN LEE CHEOW ENG, ID: S1640744E, Tel: +6596619698		
Vehicle Reg. No.:	SCZ7228S	Date of Loss:	27/12/2018 09:00 - :59 [5 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 0202154477SG	Policy/Cover Note No.:	1800079813 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/01/2019]		
Driver/Custodian:	NICOLE OON SIEW SIEN (29 / Female), NRIC: S8929981J, Tel: +6596619698 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (04/01/2019): Alert - Adj Mandate Approved (S\$10853.00) - SCZ7228S - Claim Handler: Mohd Zaway...
- AIG_SG (04/01/2019): SCZ7228S / OD / 27/12/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SCZ7228S (0202154477SG)**
OD
Dec 27 2018 9:45AM
[MEGAN LEE CHEOW ENG]
Premium Automobiles Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser ▼
------------------	---------------	--------------------	--------------	--------------	------	-------------------

Assessment Reports				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/01/19 09:41	Adjuster Immediate Advice	 Load HTM		

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/01/19 08:26	General View	 Load JPG	☒	
2	04/01/19 08:26	General View	 Load JPG	☒	
3	04/01/19 08:26	General View	 Load JPG	☒	
4	04/01/19 08:26	General View	 Load JPG	☒	
5	04/01/19 08:26	General View	 Load JPG	☒	
6	04/01/19 08:26	General View	 Load JPG	☒	
7	04/01/19 08:26	General View	 Load JPG	☒	
8	04/01/19 08:26	General View	 Load JPG	☒	
9	04/01/19 08:26	General View	 Load JPG	☒	
10	04/01/19 08:26	General View	 Load JPG	☒	
11	04/01/19 08:26	General View	 Load JPG	☒	
12	04/01/19 08:26	General View	 Load JPG	☒	
13	04/01/19 08:26	General View	 Load JPG	☒	
14	04/01/19 08:26	General View	 Load JPG	☒	
15	04/01/19 08:26	General View	 Load JPG	☒	
16	04/01/19 08:26	General View	 Load JPG	☒	
17	04/01/19 08:26	General View	 Load JPG	☒	

Documentation				1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/01/19 08:48	Singapore Accident Statement	 Load PDF		
2	04/01/19 08:48	Certificate of Insurance	 Load PDF		
3	04/01/19 08:48	Insured's Driving License	 Load PDF		
4	04/01/19 08:48	Driving Licence	 Load PDF		
5	04/01/19 08:48	MARK ESTIMATE	 Load PDF		
6	27/05/19 10:26	DISCHARGE VOUCHER	 Load PDF		
7	27/05/19 10:29	WORKSHOP INVOICE	 Load PDF		

Linked Accident Report Documents

					View	View in Browser ▼
--	--	--	--	--	------	-------------------

Assessment Reports				1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	28/12/18 12:57	Accident Statement	 Load HTM		

Assessment Reports			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
Photos/Images			3 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/12/18 12:53	Accident Photo	 Load JPG	✓
2	28/12/18 12:53	Accident Photo	 Load JPG	✓
3	28/12/18 12:53	Accident Photo	 Load JPG	✓
4	28/12/18 12:53	Accident Photo	 Load JPG	✓
5	28/12/18 12:53	Accident Photo	 Load JPG	✓
6	28/12/18 12:53	Accident Photo	 Load JPG	✓
7	28/12/18 12:53	Accident Photo	 Load JPG	✓
8	28/12/18 12:53	Accident Photo	 Load JPG	✓
9	28/12/18 12:53	Accident Photo	 Load JPG	✓
10	28/12/18 12:53	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/12/18 12:50	Sketch Plan	 Load JPG	✓
2	28/12/18 12:50	Sketch Plan #2	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19000145/AVBS2

Date: 27/05/2019

REFERENCE

Insured/Claimant: MEGAN LEE CHEOW ENG

Policy No: 1800079813

Date of Loss: 27/12/2018

Nature of Claim: OD

Claim No: 0202154477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCZ7228S

Make & Model: AUDI A4, 2.0 (A)

Reg. Date: 16/07/2018 (Man. Year: 2018)

Colour: Black

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$160,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: CVK063922

Chassis No: WAUZZZF43JA187996

Odometer: 5716 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16

Front Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size:

205/60R16

Rear Left Side:

Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,937.00	4,075.60	5,861.40	58.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,012.00	5,622.00	8,390.00	59.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,949.00	9,697.60	14,251.40	59.51
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	23,449.00	9,197.60	14,251.40	60.78
+ GST 7.00/7.00% (S\$)	1,641.43	643.83	997.60	60.78
Nett Amount (S\$)	25,090.43	9,841.43	15,249.00	60.78

INSPECTION

Date of Assignment: 03/01/2019

Date Inspected: 03/01/2019

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RH	Dented	1,928.00 FS	*1,542.40 FS
2	1		*REAR DOOR OUTER SEAL - RH	Necessary	176.00 FS	*140.40 FS
3	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
6	1		*REAR DOOR SEALING STRIP - RH	Not Necessary	14.00 FS	*- FS
7	1		*REAR DOOR ATTACHMENT PARTS - RH	Not Necessary	488.00 FS	*- FS
8	1		*REAR DOOR CATCH - RH	Damaged	105.00 FS	*84.00 FS
9	1		*REAR DOOR CATCH COVER - RH	Not Necessary	12.00 FS	*- FS
10	1		*REAR DOOR HANDLE TRIM PLATE - RH	Not Necessary	22.00 FS	*- FS
11	1		*REAR DOOR HANDLE HOUSING - RH	Not Necessary	7.00 FS	*- FS
12	1		*REAR DOOR HANDLE EXTERIOR - RH	Repair	33.00 FS	*- FS
13	1		*REAR DOOR MOUNTING BAR - RH	Not Necessary	143.00 FS	*- FS
14	1		*REAR SIDE PANEL - RH	Dented	2,347.00 FS	*1,525.60 FS
15	1		*REAR WINDOW	Not Necessary	1,014.00 FS	*- FS
16	2		*REAR WINDOW PRIMER	Not Necessary	37.00 FS	*- FS
17	1		*REAR SIDE WINDOW - RH	Not Necessary	541.00 FS	*- FS
18	1		*REAR SIDE WINDOW TRIM STRIPS CHROME - RH	Not Necessary	426.00 FS	*- FS
19	1		*REAR ALUMINIUM - RH	Not Necessary	645.00 FS	*- FS
20	4		*RUBBER VALVE	Not Necessary	12.00 FS	*- FS
21	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	215.00 FS	*- FS
22	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS - RH	Not Necessary	78.00 FS	*- FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
25	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
26	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
27	1		*SUNDRIES	Necessary	800.00 FS	*3.20 FS
					Total Parts (\$\$)	9,937.00 4,075.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	New	280.00	280.00
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS. LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG ETC.	New	1,400.00	1,400.00
4	TO REMOVE AND RENEW RHS 1/4 GLASS AND REAR WINDSCREEN FOR FENDER RENEWAL.	New	600.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, FUSE UNITS, BATTERY MANAGER, FUSE AND RELAY TRAYS, AND ELECTRICAL COMPONENTS.	New	1,400.00	0.00
6	TO DISMANTLE REAR BUMPER, REAR LID AND RHS REAR DOOR. CUT OUT AND REWELD RHS REAR FENDER. RENEW RHS REAR DOOR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	5,400.00	2,000.00
7	TO RESPRAY RHS REAR DOOR, DOOR HANDLE, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCE, ROOF CHANNEL, DRAIN CHANNEL AND END PANELLING. TO CARRY OUT JOINT WORKS AND STONE SHIP TREATMENT.	New	4,100.00	1,750.00
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			14,012.00	5,622.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >