

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1465/2018/GW
Date : 28-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Megan Lee Cheow Eng
Address : 31 Mount Sinai Rise
#19-07
Singapore 276953
Telephone : HP +65 96619698
Type of Claim : Own Damage Claims
Policy No. : 1800079813
Vehicle No : **SCZ 7728 G**
Model Code : Audi A4 Sedan 2.0 TFSI S-tronic
Model / Year : Jul-18
Engine No : CVX 063922
Chassis No : WAUZZZF43JA187996
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Dec-18
Place of Accident : ICON @ Pasir Pangjang

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCZ 7228 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N	\$ 360.00	X
2	To remove and transfer rhs rear door's multi-lock system and power window devices.	S/N	\$ 280.00	✓
3	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims. Lugage compartment trims. Dislodge roof liner and disengage curtain air bag etc.	S/N	\$ 1,400.00	✓
4	To remove and renew rhs 1/4 glass and rear windscreen for fender renewal.	S/N	\$ 600.00	X
5	To dislodge and reinstall rear wire harness for tail lights, fuse units, battery manager, fuse and relay trays, and electrical components.	S/N	\$ 1,400.00	X
SUB = TOTAL LABOUR CHARGES		:	\$ 4,040.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCZ 7228 G

S/n	Nature of Jobs	Estimated Charges
6	To dismantle rear bumper, rear lid and rhs rear door. Cut out and reweld rhs rear fender. Renew rhs rear door. Reorganise crash management components. Reinstall all parts removed.	\$ 5,400.00 2000
7	To respray rhs rear door, door handle, rhs rear fender, rhs sill panel, door entrances, roof channel, drain channel and end panelling. To carry out joint works and stone chip treatment.	1750 550x3=1650 Hackle = 100. \$ 4,100.00
8	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00 X
9	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 14,012.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCZ 7228 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	REAR DOOR-RH <i>Dented</i>	\$ 1,928.00	✓
2	REAR DOOR OUTER SEAL-RH <i>ne</i>	\$ 176.00	✓
3	BONDING AGENT <i>?</i>	\$ 43.00	?
4	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
5	APPLICATOR <i>?</i>	\$ 7.00	?
6	REAR DOOR SEALING STRIP-RH <i>ne n</i>	\$ 14.00	✓
7	REAR DOOR ATTACHMENT PARTS-RH <i>?</i>	\$ 488.00	?
8	REAR DOOR CATCH-RH <i>ne n</i>	\$ 105.00	✓
9	REAR DOOR CATCH COVER-RH <i>ne n</i>	\$ 12.00	✓
10	REAR DOOR HANDLE TRIM PLATE-RH <i>?</i>	\$ 22.00	+
11	REAR DOOR HANDLE HOUSING-RH <i>ne n</i>	\$ 7.00	+
12	REAR DOOR HANDLE EXTERIOR-RH <i>Regis</i>	\$ 33.00	✓
13	REAR DOOR MOUNTING BAR-RH <i>ne n</i>	\$ 143.00	✓
14	REAR SIDE PANEL-RH <i>Dented</i>	\$ 2,347.00	✓
15	REAR WINDOW <i>?</i>	\$ 1,014.00	+
16	REAR WINDOW PRIMER <i>ne n</i>	2 \$ 37.00	+
17	REAR SIDE WINDOW-RH	\$ 541.00	+
18	REAR SIDE WINDOW TRIM STRIPS CHROME-RH <i>NT</i>	\$ 426.00	✓
19	REAR ALUMINIUM-RH <i>Not ne</i>	\$ 645.00	+
20	RUBBER VALVE <i>Not ne</i>	4 \$ 12.00	+
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,064.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCZ 7228 S

S/N	Parts Description	<u>Damaged Pa</u>	
		<u>S/Nett</u>	
21	REAR WHEEL HOUSING LINER-RH <i>re new</i>	\$	215.00 ✓
22	REAR WHEEL HOUSING LINER ATTACHMENT PARTS-RH <i>re new</i>	\$	78.00 +,
23	ACRYLIC SEALANT	S/N \$	180.00 ✓
24	CAVITY WAX	S/N \$	140.00 ✓
25	STONE CHIP	S/N \$	180.00 ✓
26	METAL FILLER POWDER	S/N \$	280.00 ✓
27	SUNDRIES ?	\$	800.00 ?
TOTAL SPARE PARTS CHARGES		\$	9,937.00
TOTAL LABOUR CHARGES		\$	14,012.00
GRAND TOTAL		\$	23,949.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 03/01/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OP Rgn.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant