

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TEE SUYIN
73 STILL ROAD
S 423982

TP Sompoo
Xiao Chen

Date :09.01.2019
Vehicle no :SKD 8312 X
Make/Model :VOLKSWAGEN BEETLE
Accident date :02.01.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bonnet <i>Dented</i>	1	\$ 1397 ✓
2	Front bonnet hinges @ \$148.50 <i>see n</i>	2	\$ 297 x
3	Front bonnet lock <i>Dented</i>	1	\$ 165 ✓
4	Front bonnet lock bracket <i>see n</i>	1	\$ 27.5 x
5	Frontbonnet inner rubber <i>see n</i>	1	\$ 88 x
6	Front bonnet emblem <i>crushed</i>	1	\$ 99 ✓
7	Front bonnet cable <i>see n</i>	1	\$ 132 x
8	Front bumper <i>del</i>	1	\$ 1980 1198
9	Front bumper side holder @ \$33.00 <i>see n</i>	2	\$ 66 ✓
10	Front bonnet shock absorber <i>see n</i>	1	\$ 94.6 x
11	Front support panel top garnish <i>see n</i>	1	\$ 155 x
12	Front support panel top garnish clips <i>see n</i>	1	\$ 80 x
Total			\$ 4581.1

Special Nett Items

1	Front number plate <i>Best</i>	1	\$ 50 <i>30</i>
2	Front number plate holder <i>del</i>	1	\$ 50 <i>30</i>
Total			\$ 100

Labour Costs

1	Remove, replace & repair consistent to the accident	\$ 1400 <i>400</i>
2	Respray painting	\$ 1200 <i>500</i>
3	Tuff kote	\$ 100 x
Total		\$ 2700

Grand Total \$ 7381.1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 3738.75
h/s: 3K.
O.A. Dany.

3K.
Seng