

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1455/2018/GW
Date : 26-Dec-18

Vehicle not IN Our Workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Gong XiaoZhen
Address : 87 Yishun Avenue 1
#16-01
Singapore 769133
Telephone : HP +65 96659708
Type of Claim : Own Damage Claims
Policy No. : 1800151451
Vehicle No : **SDR 5388 G**
Model Code : A3 Sedan 1.4 TFSI
Model / Year : Dec-18
Engine No : CZE 846873
Chassis No : WAUZZZ8V6K1008521
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Dec-18
Place of Accident : Junction Of Jalan Sungai Chat To main Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDR 5388 G

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓
2	To dislodge and reinstall rear wire harness for tailights, battery manager, fuse and relays, electrical and audio components.	S/N \$ 480.00 ?
3	To dismantle and renew rear bumper. Cut out and reweld end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 3,000.00 500
4	To respray rear bumper and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 1,500.00 550
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 5,452.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 5388 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Dehnd</i>	\$ 1,697.00 ✓	
2	REAR BUMPER STICKY PAD <i>Ne n</i>	4 TBC X	
3	REAR BUMPER FIXING PARTS <i>Ne n</i>	\$ 166.00 X	
4	REAR BUMPER UPPER GUIDE SECTION-RH ?	\$ 14.00 ?	
5	REAR ADPATER WHEEL HOSUING LINER-RH <i>Ne n</i>	\$ 32.00 X	
6	REAR BUMPER LOCKING MECHANISM <i>Ne n</i>	\$ 25.00 X	
7	REAR BUMPER SPOILER <i>ht</i>	\$ 206.00 ✓	
8	REAR LIGHT REFLECTOR-RH ?	\$ 35.00 ?	
9	REAR BUMPER SIDE REINFORCEMENT ?	\$ 501.00 ?	
10	REAR BUMPER BRACKET-LH <i>Ne n</i>	\$ 23.00 X	
11	REAR BUMPER BRACKET-RH <i>Ne n</i>	\$ 24.00 X	
12	REAR BUMPER GUIDE SECTION-RH ?	\$ 57.00 ?	
14	REAR SENSOR ?	2 \$ 421.00 ?	
15	REAR SENSOR SEAL RING ?	4 \$ 14.00 ?	
16	LED TAILLIGHT-RH <i>Ne n</i>	\$ 730.00 X	
17	LED TAILLIGHT TRIM-RH <i>Ne n</i>	\$ 26.00 X	
18	REAR CROSS PANEL ?	\$ 317.00 ?	
19	REAR REINFORCEMENT CROSS PANEL ?	TBC ?	
20	ACRYLIC SEALANT ?	S/N \$ 180.00 ?	
SUB - TOTAL SPARE PARTS		\$ 4,468.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 5388 G

		<u>Damage Pa</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	
21	CAVITY WAX	S/N \$	140.00
22	STONE CHIP	S/N \$	180.00
23	SUNDRIES	\$	800.00
TOTAL SPARE PARTS		:	\$ 5,588.00
TOTAL LABOUR CHARGES		:	\$ 5,452.00
GRAND TOTAL		:	\$ 11,040.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 03/01/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : All authorised, 03 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant