

ASS. REC. BY:

REF:

CS/III19000155/Utd3m2

Special Instruction:

Surveyor
Meinen

Markus

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time: 3/1/19 @ 4:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 5461D

Insured:

at Workshop m/s

Hup Motor

Tel:

67840039

of

Blk 9004 Tampines St-93 #01-120

Policy No:

Claim No:

Sum Insured:

Excess:

TBA

600

Make of Veh:

(Client's Record)

D.O.A.

02/01/2019

4/01/2019

H.O.D. Endorsement:

CA / (REV) / REP. / REV 24 HRS

Date/Time:

4:10pm @ 3/1/19

Person Contacted:

David

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 5461D-X

CS/ III 19000155/Utd3

REF: III

Insurance: Mercus

ASSIGNMENT

From

Date: 04/01/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLN 5461D

at Workshop m/s

Hup Motor

of B1k 9004, Tampines St. 93 # 01-120

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

600

(Client's Record)

Make of Veh:

after 10:30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

666

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

1.3%

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLN 5461D

Yn Regn

S. 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mazda 3 SP

C.C.

1496

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

21790

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22APH0147208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

2/1/19

D.O.I.

4/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt, O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

47453997 bys soli.

07/01/19 @ 11:15 a.m. mandate approved by meoradio via merimer

07/01/19 @ 13:17 p.m. revert authorize repair to David (repur) via email.

2/1/19 confirmed Fine/ by \$8987.68 with David

(Ref: 4932.64, 3570)

RECEIVED 08 JAN 2019

Date/Time, File Pass to?

07/01/19

Date/Time, File Return to?

☐

Preli. Report

☐

Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

350

S + RS \$

10

Photos

Others

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL

360

Report Format:

Lump Sum / I.B.I. (\$)

2931.68

REF: III

ASSIGNMENT

From: Date: 04/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SLN 5461D

at Workshop m/s

of Blk 9004, Tampines St 93 # 01-120

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

9600/-

(Client's Record)

Make of Veh:

after 10:30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

666.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / (REV) / REP. / 24 HRS

2847A

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

57453997 hrs sale.

07/01/19 @ 11:15 am. mandate approval by Muenchi.

07/01/19 @ 13:17 pm. revert authorise repair to David (operator) via email.

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 S + RS \$

Photos

Others

TOTAL

Veh No: SLN 5461D Yr Regn: 5.17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer or CA/

Make:

Mazda 3 SP

C.C.

1456

Colour:

Red

A/C

Insured / Std / NI / NA

Sp. Reading

21790

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22APH0147208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

2/1/19

D.O.I.

4/1/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fnt, O/S Rr.

Title U/C / Chassis frame / Body Structure affected due to collision.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 3 January 2019 4:10 PM
To: David Ang; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: C Meenachi - III
Subject: RE: RE : OD CLAIMS FOR CLIENT'S VEHICLE : SLN 5461 D, UNDER POLICY NO : M496664, DOA : 02/01/19, ALONG OPEN CAR PARK OF BLK 533 PASIR RIS DR, 1
Attachments: SLN 5461 D.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLN5461D and let us have your report urgently.

This claim will be handled by Ms Meena.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: David Ang [mailto:hupmotor@gmail.com]
Sent: 03 January, 2019 1:53 PM
To: Motor Claim - III <motorclaim@iii.com.sg>; C Meenachi - III <Meenachi@iii.com.sg>
Subject: RE : OD CLAIMS FOR CLIENT'S VEHICLE : SLN 5461 D, UNDER POLICY NO : M496664, DOA : 02/01/19, ALONG OPEN CAR PARK OF BLK 533 PASIR RIS DR, 1

Dear Meena, **URGENT**

Attach our estimate bill, Client's GIA report, Police Report (Hit & Run) Owner I/C, D/L, insurance certificate & log card for your reference & attention, Kindly assign your panel surveyor (LKK or LBS) to survey client's damaged vehicle, as owner need his car urgently for transportation. Please revert & confirm for OD claims survey assignment,

Best Regards
David Ang
Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655
Mailing Address :
Hup Motor Trading & Service
Blk 9004 Tampines St 93
#01-120
Singapore 528838



Virus-free. www.avg.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



6303 6303

Wide selection of Inchcape Certified Pre-owned LEXUS & TOYOTA

Christmas Sale

Free Tyre & Service Credits up to \$3,000

Interest Rate 2.28%

Extended Warranty 1yr



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coc Renewal Honda Stream 1.8A



2.88%P.A Lowest Interest@Gv
Cars Financing \$2000
Downpayment Monthly From
\$638
GV Credit Pte Ltd StarAd



AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Back (1 2) Next

Sort by Date Posted 20 results/page

31 vehicles

Mazda 3

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mazda 3		Any	Any	2017	Any	Any	Any	Available
	Mazda 3	Mazda 3 HB 1.5A Deluxe	\$71,900	\$7,390 /yr	12-Oct-2017	1,496 cc	24,000 km	Hatchback	Available
Well Maintained Mazda 3 Hatchback For Sale! Single Owner Unit! Almost New And In Flawless Condition! Car Still Under Warranty! Religiously Maintained By Fussy Owner! Paintwork In Pristine Condition! A...									
Prem Roy Motoring									
Posted: 03-Jan-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	Mazda 3 1.5A	\$66,500	\$7,210 /yr	19-Jul-2017	1,496 cc	16,117 km	Sedan	Available
Upfront \$2300, Monthly \$1076 Only. Insurance Can Be Paid By Giro x 12 Months (No Credit Card Required).									
Allmotoring.sg									
Posted: 02-Jan-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	Mazda 3 1.5A	\$65,000	\$7,220 /yr	09-May-2017	1,496 cc	23,200 km	Sedan	Available
Insurance By Debit Or Credit Card. Can Use For Grab, Cheaper Than To Rent A Car. Low Mileage And Under Agent Warranty Up To 100k Mileage Or 3yrs. Call Us For Test Drive Now!									
Allmotoring.sg									
Posted: 02-Jan-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	Mazda 3 1.5A	\$65,000	\$7,220 /yr	09-May-2017	1,496 cc	21,000 km	Sedan	Available
Year-end Clearance Sale!\$0 Down. 100% Loan Amount And 100% Accident Free. No Guarantor Needed, High Tradein, Overloan Up To \$4000.Call Now.									
Posted: 02-Jan-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazdaspeed Head Rest Pillow (Blue) Mazdaspeed Head Rest Pillow (Blue) More info about this product								
	Mazda 3	Mazda 3 1.5A Sunroof	\$62,555	\$7,080 /yr	22-Feb-2017	1,496 cc		Sedan	Available
New Year Carnival Sale Offer!Enjoy 2.28% Loan Interest! Best Deal With The Finance With Guaranteed 100% Loan Approval. 1 Owner Only! Free Servicing, Free Polishing. Highest Trade In For Your Used Car....									
Cars Inn Credit Pte Ltd									
Posted: 02-Jan-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	Mazda 3 1.5A Sunroof	\$70,500	\$7,280 /yr	29-Dec-2017	1,496 cc	10,000 km	Sedan	Available
Very Low Mileage. Used To Ferry Kids. Selling Due To Upgrade. First Owner. Still Under Warranty By Eurokars. Parking Sheltered 24 Hours. 100% Accident Free. Stock Condition. Good As New. Sincere Selle...									
Posted: 01-Jan-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
Compare	Mazda 3	Mazda 3 1.5A	\$68,000	\$7,380 /yr	19-Jul-2017	1,496 cc	17,000 km	Sedan	Available

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 7 January 2019 1:17 PM
To: hupmotor@gmail.com
Cc: SUR
Subject: SLN 5461D OD (III)

Dear David,

As instructed by our client, please proceed to repair the insured vehicle **SLN 5461D** (Excess \$ 600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLN5461D (MC20192000)**

OD

Jan 2 2019 8:00AM

[JOHANA BIN ABDUL RAHMAN]

Hup Motor Trading & Service

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 07/01/2019 11:15 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9415.68) - SLN5461D - Claim Handler: C. Meenachi

Approved:9415.68:EXCESS \$600.00

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2847A

Vehicle Details

Vehicle No.: SLN5461D
Vehicle to be Exported: No
Intended Deregistration Date: 04 Jan 2019
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour: Red
Manufacturing Year: 2017
Engine No.: P520435690
Chassis No.: JM6BN22A8H0147208
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$19,608.00
Original Registration Date: 08 May 2017
First Registration Date: 08 May 2017
Transfer Count: 0
Actual ARF Paid: \$14,608.00 7304

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 May 2027
PARF Rebate Amount: \$10,956.00

Intended COE Rebate Details

COE Expiry Date: 07 May 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$51,600.00
COE Rebate Amount: \$43,041.00
Total Rebate Amount: \$53,997.00

The information contained herein is correct as at 04 Jan 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2847A

Vehicle Details

Vehicle No.: SLN5461D

Vehicle to be Exported: No

Intended Deregistration Date: 04 Jan 2019

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Red

Manufacturing Year: 2017

Engine No.: P520435690

Chassis No.: JM6BN22A8H0147208

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$19,608.00

Original Registration Date: 08 May 2017

First Registration Date: 08 May 2017

Transfer Count: 0

Actual ARF Paid: \$14,608.00 7304

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 May 2027

PARF Rebate Amount: \$10,956.00

Intended COE Rebate Details

COE Expiry Date: 07 May 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$51,600.00

COE Rebate Amount: \$43,041.00

Total Rebate Amount: \$53,997.00

The information contained herein is correct as at 04 Jan 2019

OK

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 2935/01/19

Your Ref:

Date: 3rd JAN 2019

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

P/P # 8981-68

Not Adjudicated
4/1/19
The M. Atty Gen.
6 Lg.
Express \$600

Name Of Insured : Johana Bin Abdul Rahman
Date Of Accident : 02/01/19 (08:50hrs)
Policy Number : M496664

Estimate Cost of repair to MAZDA 3 SP (A) Saloon - SLN 5461 D

1 pc front o/s head lamp assy (HID)		scr/cn	\$ 3,598.60	✓
10 pcs front bonnet insulator clips	@ \$ 4.00	11	40.00	X
1 pc front bumper		cu7	825.50	✓
8 pcs front bumper clips	@ \$ 4.00	re	32.00	✓
1 pc front bumper o/s side retainer		del	22.70	✓
2 pcs front bumper o/s side bracket clips	@ \$ 5.00	per	10.00	✓
1 pc front o/s fender		20/34	333.90	✓
1 pc front o/s fender inner shield		per	129.00	✓
6 pcs front o/s fender inner shield clips	@ \$ 4.00	re	24.00	✓
1 pc front o/s sport rim		cu7	1,100.90	5005.W
1 pc front o/s door		27/34	1,143.20	✓
1 set front o/s door frame sticker		re	65.00	✓
2 pcs front o/s door top & low hinge	@ \$ 48.10	scr	96.20	X
16 pcs front o/s door inner trim board clips	@ \$ 6.80	11	108.80	X
1 pc front o/s door glass regulator		11	119.40	X
1 pc front o/s door side mirror		1	632.80	X
1 pc rear o/s door		2	999.40	X
1 set rear o/s door frame sticker		11	65.00	X
16 pcs rear o/s door inner trim board clips	@ \$ 6.80	11	108.80	X
1 pc rear o/s fender		1	1,175.00	X
8 pcs rear o/s fender inner garnish clips	@ \$ 4.00	11	32.00	X
1 pc rear bumper		cu7	1,074.80	✓
8 pcs rear bumper clips	@ \$ 4.00	re	32.00	✓
1 pc rear bumper o/s side retainer		re	36.10	✓
2 pcs rear bumper o/s side bracket clips	@ \$ 5.00	re	10.00	✓
			\$ 11,815.10	
	Less 20%		\$ 2,363.02	
			\$ 9,452.08	

To wiring check up & adjust headlight alignment. 40.00 20

To check & adjust front wheel alignment & balancing. 120.00 80

To remove & refix front & rear o/s door inner trim board, glass, regulator, motor, inner lock, handle, moulding, weatherstrip, hinge checker, channel & necessary parts into new door. 280.00 80

\$ 9,892.08

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 2935/01/19

Your Ref:

Date: 3rd JAN 2019

M/S INDIA INTERNATIONAL INSURANCE PTE. LTD.,

Balance B/F.... \$ 9,892.08

To remove & refix rear cushion seat, carpet, floor mat, garnish,
rear o/s fender inner garnish, channel run & necessary parts, to
enable repair rear o/s fender & necessary parts.

150.00 *so*

Labour charge to remove & cut out damaged parts, to jack, straighten
& knocking out front bonnet, rear o/s fender & necessary parts, to
weld, renew & align above parts.

1,800.00 *so*

To putty & respray painting (Pearl Candy Colour) on all affected
accident parts.

2,000.00 *1480*

\$ 13,842.08

=====

Dollars :Thirteen Thousand Eight Hundred Forty Two And Cents Eight Only.

HUP MOTOR TRADING & SERVICE



4. All Consultants hence notify:
- The repairer without delay;
 - The repairer after surveying;
 - The surveyor's party during survey;
 - Parts prices are subject to confirmation;
 - Two party survey is on a "Without Prejudice" basis;
 - The repairer must be notified;
 - Supplementary survey must be resurveyed and is subject to its approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7427-1
202

P-5941.68

S.W 500.00

Chen - 2540.80

8981.68

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 2935/01/19

Your Ref: _____

Date: 4th JAN 2019



The Claim's Manager

Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE. LTD.

64, Cecil Street, #05-00, IOB Bldg.

Singapore 049711

Name Of Insured : Johana Bin Abdul Rahman

Date Of Accident : 02/01/19 (08:50hrs)

Policy Number : M496664

SUPPLEMENTARY Bill for MAZDA 3 SP (A) saloon - SLN 5461 D

1 pc front bumper o/s fog lamp garnish (with chrome moulding) \$ 90.30

Less 20% \$ 18.06

Balance : \$ 72.24

=====

Dollars : Seventy Two And Cents Twenty Four Only.

HUP MOTOR TRADING & SERVICE

.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 2935/01/19

Your Ref:

Date: 3rd JAN 2019

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #C5-00, IOB Bldg.
Singapore 049711

Name Of Insured : Johana Bin Abdul Rahman
Date Of Accident : 02/01/19 (08:50hrs)
Policy Number : M496664

*Not Affected
4/1/19
The M. Officer
6 dy.
EXUSS?*

Estimate Cost of repair to MAZDA 3 SP (A) Saloon - SLN 5461 D

1 pc front o/s head lamp assy (HID)	SCR/CN	\$ 3,598.60	✓
10 pcs front bonnet insulator clips	@ \$ 4.00	11 40.00	X
1 pc front bumper	CUT	825.50	✓
8 pcs front bumper clips	@ \$ 4.00	NR 32.00	✓
1 pc front bumper o/s side retainer	Set	22.70	✓
2 pcs front bumper o/s side bracket clips	@ \$ 5.00	Per 10.00	✓
1 pc front o/s fender	20/Set	333.90	✓
1 pc front o/s fender inner shield	TR 1	129.00	✓
6 pcs front o/s fender inner shield clips	@ \$ 4.00	NR 24.00	✓
1 pc front o/s sport rim	CUT	1,100.90	5005.n
1 pc front o/s door	20/Set	1,143.20	✓
1 set front o/s door frame sticker	NR	65.00	✓
2 pcs front o/s door top & low hinge	@ \$ 48.10	Set 96.20	X
16 pcs front o/s door inner trim board clips	@ \$ 6.80	11 108.80	X
1 pc front o/s door glass regulator		11 119.40	X
1 pc front o/s door side mirror		632.80	?
1 pc rear o/s door	R	999.40	X
1 set rear o/s door frame sticker	11	65.00	X
16 pcs rear o/s door inner trim board clips	@ \$ 6.80	11 108.80	X
1 pc rear o/s fender		1,175.00	X
8 pcs rear o/s fender inner garnish clips	@ \$ 4.00	11 32.00	X
1 pc rear bumper	CUT	1,074.80	✓
8 pcs rear bumper clips	@ \$ 4.00	NR 32.00	✓
1 pc rear bumper o/s side retainer		NR 36.10	✓
2 pcs rear bumper o/s side bracket clips	@ \$ 5.00	NR 10.00	✓
		\$ 11,815.10	
	Less 20%	\$ 2,363.02	
		\$ 9,452.08	

To wiring check up & adjust headlight alignment. 40.00 20

To check & adjust front wheel alignment & balancing. 120.00 80

To remove & refix front & rear o/s door inner trim board, glass, regulator, motor, inner lock, handle, moulding, weatherstrip, hinge checker, channel & necessary parts into new door. 280.00 80

\$ 9,892.08

Balance C/F.....

合 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

116 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 2935/01/19

Your Ref:

Date: 3rd JAN 2019

M/S INDIA INTERNATIONAL INSURANCE PTE. LTD.,

Balance B/F.... \$ 9,892.08


To remove & refix rear cushion seat, carpet, floor mat, garnish,
rear o/s fender inner garnish, channel run & necessary parts, to
enable repair rear o/s fender & necessary parts.

150.00 *SO*

Labour charge to remove & cut out damaged parts, to jack, straighten
& knocking out front bonnet, rear o/s fender & necessary parts, to
weld, renew & align above parts.

1,800.00 *SO*

To putty & respray painting (Pearl Candy Colour) on all affected
accident parts.

2,000.00 *1480*\$ 13,842.08
=====Dollars : **Thirteen** Thousand Eight Hundred Forty Two And Cents Eight Only.**HUP MOTOR TRADING & SERVICE**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III19000155/UTD3N2

Date: 08/01/2019

REFERENCE

Insured/Claimant: JOHANA BIN ABDUL RAHMAN
Date of Loss: 02/01/2019

Policy No: M496664
Nature of Claim: OD Claim No: MC20192000

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN5461D	Engine No:	P520435690
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Chassis No:	JM6BN22A8H0147208
Reg. Date:	08/05/2017 (Man. Year: 2017)	Odometer:	21790 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,524.32	6,441.68	3,082.64	32.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	2,540.00	1,850.00	42.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,914.32	8,981.68	4,932.64	35.45
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	13,314.32	8,381.68	4,932.64	37.05
+ GST 7.00/7.00% (\$\$)	932.00	586.72	345.28	37.05
Nett Amount (\$\$)	14,246.32	8,968.40	5,277.92	37.05

INSPECTION

Date of Assignment: 03/01/2019

Date Inspected: 04/01/2019 Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN5461D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S HEAD LAMP ASSY (HID)	Scratched/Cracked	3,598.60 FL	*3,598.60 FL
2	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	40.00 FL	*- FL
3	1		*FRONT BUMPER	Cut	825.50 FL	*825.50 FL
4	8		*FRONT BUMPER CLIPS	Necessary	32.00 FL	*32.00 FL
5	1		*FRONT BUMPER O/S SIDE RETAINER	Bent	22.70 FL	*22.70 FL
6	2		*FRONT BUMPER O/S SIDE BRACKET CLIPS	Necessary	10.00 FL	*10.00 FL
7	1		*FRONT O/S FENDER	Dented/Bent	333.90 FL	*333.90 FL
8	1		*FRONT O/S FENDER INNER SHIELD	Torn	129.00 FL	*129.00 FL
9	6		*FRONT O/S FENDER INNER SHIELD CLIPS	Necessary	24.00 FL	*24.00 FL
10	1		*FRONT O/S DOOR	Dented/Bent	1,143.20 FL	*1,143.20 FL
11	1		*SET FRONT O/S DOOR FRAME STICKER	Necessary	65.00 FL	*65.00 FL
12	2		*FRONT O/S DOOR TOP & LOW HINGE	Serviceable	96.20 FL	*- FL
13	16		*FRONT O/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	108.80 FL	*- FL
14	1		*FRONT O/S DOOR GLASS REGULATOR	Not Necessary	119.40 FL	*- FL
15	1		*FRONT O/S DOOR SIDE MIRROR	Repair	632.80 FL	*- FL
16	1		*REAR O/S DOOR	Repair	999.40 FL	*- FL
17	1		*SET REAR O/S DOOR FRAME STICKER	Not Necessary	65.00 FL	*- FL
18	16		*REAR O/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	108.80 FL	*- FL
19	1		*REAR O/S FENDER	Repair	1,175.00 FL	*- FL
20	8		*REAR O/S FENDER INNER GARNISH CLIPS	Not Necessary	32.00 FL	*- FL
21	1		*REAR BUMPER	Cut	1,074.80 FL	*1,074.80 FL
22	8		*REAR BUMPER CLIPS	Necessary	32.00 FL	*32.00 FL
23	1		*REAR BUMPER O/S SIDE RETAINER	Necessary	36.10 FL	*36.10 FL
24	2		*REAR BUMPER O/S SIDE BRACKET CLIPS	Necessary	10.00 FL	*10.00 FL
25	1		*FRONT O/S SPORT RIM	Cut	880.72 FS	*500.00 FS
26	1		*FRONT BUMPER O/S FOG LAMP GARNISH (WITH CHROME MOULDING)	Grazed	90.30 FL	*90.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,685.22	7,927.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,160.90	1,485.42
Total Parts (\$\$)	9,524.32	6,441.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	40.00	20.00
2	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	120.00	80.00
3	TO REMOVE & REFIX FRONT & REAR O/S DOOR INNER TRIM BOARD, GLASS, REGULATOR, MOTOR, INNER LOCK, HANDLE, MOULDING, WEATHERSTRIP, HINGE CHECKER, CHANNEL & NECESSARY PARTS INTO NEW DOOR	New	280.00	80.00
4	TO REMOVE & REFIX REAR CUSHION SEAT, CARPET, FLOOR MAT, GARNISH, REAR O/S FENDER INNER GARNISH, CHANNEL RUN & NECESSARY PARTS, TO ENABLE REPAIR REAR O/S FENDER & NECESSARY PARTS	New	150.00	80.00
5	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT BONNET, REAR O/S FENDER & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,800.00	800.00
6	TO PUTTY & RESPRAY PAINTING (PEARL CANDY COLOUR) ON ALL AFFECTED ACCIDENT PARTS	New	2,000.00	1,480.00
Gross Labour Cost (S\$)			4,390.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >