



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 03.01.2019

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2703B HONDA FREED 1.5G (2010)

To Supply

- | | | | |
|---------|--------------------------------------|----|--------|
| 1) 1pc | Right side mirror assy. <i>scr ✓</i> | \$ | 564.20 |
| 2) 1pc | Front right door glass <i>repair</i> | \$ | 455.00 |

Sub total Parts	\$	1,019.20
Less: 20% discount	\$	(203.84)
	\$	815.36

To Supply S.Nett Parts

- | | | | |
|---------|--|----|--------|
| 1) 1pc | Right front door advertisement sticker <i>na ✓</i> | \$ | 180.00 |
|---------|--|----|--------|

Sub total S.Nett Parts	\$	180.00
------------------------	----	--------

L/charges

- | | | |
|---|----|-----------------------|
| 1) To remove right side mirror. Knock & repair front right door. Replace the above parts. | \$ | 400.00 250 |
| 2) To putty, respray painting right front door & right side mirror outer cover. To polish. | \$ | 400.00 300 |

Rasul

Hp 90010068

3 days

4/5

04/01/19 @ 0900

Resurvey after repair

Sub total L/charges	\$	800.00
Estimated Grand Total	\$	1,795.36