

15/02/2010

INS. CASE OWNER:

Gerald

CC 6 / LPC1900

0175, U+6352

LKK:

IDAC:

Surveyor:

murcus

DOI:

ASSIGNMENT

7/1/19

Date / Time:

Pohkin

7/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKH 1571P

Name of Insured:

WHEEN CHAN LING

Insured Tel No.:

HP:

94589914

Excess Sec II :SS

D.O.A:

7/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

818VP150M371

TAYOTA

LTE TMS PARK AVE S.

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLC 7249X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan
Lim

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/1/19
VX

SLC 7249X - X

SKH 1571P - X

File review BOLA 27

KIV LOD

File pass for type monitor report

Need after repair photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

4/1/2019

Sent By:

LSP

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

8,000.00

(5

days) Reduction:

46.31

%

Email

Call

FINAL SETTLEMENT

Date/Time:

8/4/2019

Confirm with

Johnson Chan

Email

Call

Final Liability:

%

60

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

(w/1655)

SS

8,560.00

Loss of Rental (LOR):

SS

1,155.60

(6

days) X \$180.00

+7% GST

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4450.00

Total:

SS

9,715.60

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

9,715.60

Name 1:

Tan Lim Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

(08/11/13) wef

ASS. REC. BY: MARCUS

REF:

LPC/**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC7249Xat Workshop n/s Tan Lian

of _____

Insured: SLH 1571P

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 50

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes- or NoCA / REV / REP. / 24 HRS LTA 39124

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC7249X Yr Regn: 12,06Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA/Make: Toyota Alphard c.c. 2362Colour: Gold A/C: Insured / Std / NI / NASp.Reading: 15-25.8 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ANH10 0150253Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 31/12/18 D.O.I. 3/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31-7-2026 7yrs 7m. rep 76.3/1/19 confirmed L/S \$8000 with MR Tan.(Red: \$6,901.61 / 46.31%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC6/LPC19000175/Ufb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 03-01-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKH 1571P	Veh. Inspected	SLC 7249X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/12/2018	Inspection Date	03/01/2019	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/LPC19000175/Ufb3

Date: 04.01.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLC7249X

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 03.01.2019 at the premises of M/s Tan Lim Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	14,901.61
Revised Estimate Amount	: S\$	8,000.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Lonpac Insured's Veh No : SKH1571P
Date of Accident : 31 December 2018

Miss Tan Bee Chin (Chen Meizhen)

Date : 03 January 2019

Estimate To Repair SLC7249X - Toyota Alphard 2.4 A
Chassis No : ANH100150253

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid	\$ 1,967.56
02	1 pc	tailgate lid centre logo badge	\$ 85.00
03	1 pc	tailgate lid Alphard badge	\$ 75.00
04	2 ps	tailgate lid reflectors @ \$285.00	\$ 570.00
05	1 pc	tailgate lid weatherstrip	\$ 375.00
06	2 ps	tailgate lid side catch @ \$98.00	\$ 196.00
07	1 pc	tailgate lid inner trimboard	\$ 429.80
08	2 ps	tailgate lid rubber stoppers @ \$16.80	\$ 33.60
09	1 pc	tailgate lid lock top	\$ 435.80
10	1 pc	tailgate lid lock latch bottom	\$ 55.60
11	1 pc	rear bumper	\$ 1,785.00
12	2 ps	rear bumper tow cover @ \$35.00	\$ 70.00
13	2 ps	rear bumper side retainers @ \$78.00	\$ 156.00
14	4 ps	rear bumper parking sensor @ \$485.00	\$ 1,940.00
15	1 pc	rear bumper parking sensor wire harness	\$ 394.65
16	2 ps	rear bumper side holders @ \$58.00	\$ 116.00
17	2 ps	rear bumper reflectors @ \$65.00	\$ 130.00
18	2 ps	rear bumper lower cover @ \$245.00	\$ 490.00
19	8 ps	rear bumper clips @ \$4.30	\$ 34.40
20	2 ps	rear lamps @ \$348.00	\$ 696.00
21	1 pc	rear lamp apron garnish	\$ 248.00
22	1 pc	rear end panel outer	\$ 625.00
23	1 pc	rear end panel inner	\$ 599.80
24	1 pc	rear end panel inner top garnish	\$ 225.00
25	1 pc	spare tyre carriage holder	\$ 224.60
26	1 pc	rear exhaust pipe	\$ 855.80
27	2 ps	rear licence plate lamp @ \$85.00	\$ 170.00
28	1 pc	rear licence plate garnish	\$ 197.00
29	1 pc	rear licence plate chrome garnish top	\$ 212.40
30	1 pc	rear licence plate chrome garnish bottom	\$ 269.80
31	2 ps	reverse lamp @ \$303.00	\$ 606.00
Less 25 %			\$ 14,268.81
			\$ 3,567.20
			\$ 10,701.61
<u>SPECIAL NETT ITEMS</u>			
32	1 pc	reverse CCTV camera	\$ 600.00
33	1 set	rear windscreen sealant	\$ 120.00
34	1 pc	rear windscreen inner sponge seal	\$ 70.00

Not Attached
3/1/19
4/5 #8000/2/1/1/1
Sdy.
The photo attached

Lik-MurLOS

03/01/19 0930h

9564.36
7173.27

450
40
30



51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 03 January 2019

S/No	Quantity	Description	Amount
35	1 pc	<u>SPECIAL NETT ITEMS</u> rear licence plate	\$ 17 70.00 \$ 860.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To remove and refit rear windscreen glass.	\$ 180.00
02		To reinstall of rear bumper parking sensor.	\$ 250.00
03		To check electrical lighting concerned.	\$ 60.00
04		To rust-proofing of the affected areas.	\$ 120.00
05		To drop rear exhaust box and renew the same.	\$ 120.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
07		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,280.00
09		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 3,340.00
		Total	\$ 14,901.61

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 7 January 2019 9:03 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving SKH1571P (OI : LPC - TBA) AND SLC7249X (TP : LKK REF - CC6/LPC19000175/Ufb3) on 31.12.2018
Attachments: 07012019085940.pdf

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Friday, 4 January, 2019 5:31 PM
To: GERALD POH WEE BIN; ericwoo; ONG LI LI
Cc: MT_Claim_SG; Admin A; Poh Kin (LKKAUTO)
Subject: Direct Settlement - Accident Involving SKH1571P (OI : LPC - TBA) AND SLC7249X (TP : LKK REF - CC6/LPC19000175/Ufb3) on 31.12.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLC 7249X at M/s Tan Lim Motor Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeit@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 11 April 2019 10:44 AM
To: Johnson Chua
Cc: 'Wei Shong'; Admin A
Subject: RE: Final Reminder - TLM Ref: TP003012019; ; Accident involving SLC7249X (TLM) & SKH1571P (Lonpac) on 31.12.2018
Attachments: DV SLC 7249X.pdf
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC6/LPC19000175/Ufb3
Your Ref: TP003012019

Dear Johnson,

We refer to the above matter.

We confirmed settlement as below:-

1. Cost of Repair (w/GST)	S\$ 8,560.00
2. Loss of Rental (\$180.00 x 6 days)+7% gst	<u>S\$ 1,155.60</u>
	<u>S\$ 9,715.60</u>

Please duly sign the **DV** attached and return to us (**LKK**) for payment processing.

We need **original copy DV**.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Poh Kin (LKKAuto)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>
Sent: Tuesday, 9 April 2019 12:27 PM
To: Poh Kin (LKKAuto)
Cc: 'Wei Shong'; Admin A
Subject: Final Reminder - TLM Ref: TP003012019; ; Accident involving SLC7249X (TLM) & SKH1571P (Lonpac) on 31.12.2018

Importance: High

Categories: clear

Dear Poh Kin,

We refer to our tele-conversation on 08.04.2019.

As spoken, we confirmed our settlement at **\$9,715.60** (all-in).

Hence, please forward the Discharge Voucher to us as soon as possible.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte L
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L. Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]
Sent: Monday, 8 April 2019 4:19 PM
To: Johnson Chua <johnson.chua@tlmotor.com.sg>
Cc: 'Wei Shong' <wei.shong@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: Final Reminder - TLM Ref: TP003012019; ; Accident involving SLC7249X (TLM) & SKH1571P (Lonpac) on 31.12.2018
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC6/LPC19000175/Ufb3
Your Ref: TP003012019

Dear Johnson,

We refer to the above matter and our tele conversation.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 8 April 2019 4:19 PM
To: Johnson Chua
Cc: 'Wei Shong'; Admin A
Subject: RE: Final Reminder - TLM Ref: TP003012019; ; Accident involving SLC7249X (TLM) & SKH1571P (Lonpac) on 31.12.2018

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC6/LPC19000175/Ufb3
Your Ref: TP003012019

Dear Johnson,

We refer to the above matter and our tele conversation.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to revise offer settlement as below:-

1. Cost of Repair (w/GST)	S\$ 8,560.00
2. Loss of Rental (\$170.00 x 6 days)+7% gst	S\$ 1,091.40
	S\$ 9,651.40

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 8 April 2019 4:10 PM
To: Poh Kin (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: RE-SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKH 1571P (OI) AND SLC 7249X (TP) ON 31-12-2018; LKK ref : CC6/LPC19000175/Ufb3; Lonpac ref: TBA [External Confidential]

Lonpac External - Confidential

Dear Poh Kin,

Kindly proceed as proposed.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]
Sent: Tuesday, 2 April, 2019 5:59 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A
Subject: RE-SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKH 1571P (OI) AND SLC 7249X (TP) ON 31-12-2018; LKK ref : CC6/LPC19000175/Ufb3; Lonpac ref: TBA [External Confidential]
Importance: High

Without Prejudice

Our Ref: CC6/LPC19000175/Ufb3

Your Ref: TBA

Dear Gerald,

We refer to the above matter and your mandate approval on 01.03.2019.

We hereby re-seek mandate as TP M/S Tan Lim Motor Pte Ltd counter proposal for loss of rental for \$180.00 per day, given a point of view that rental vehicle is MPV vehicle and 2400 cc.

Summary to offer to third party repairer, Tan Lim Motor Pte Ltd is as follows: -

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 2 April 2019 5:59 PM
To: 'GERALD POH WEE BIN'
Cc: MT_Claim_SG; Admin A
Subject: RE-SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKH 1571P (OI) AND SLC 7249X (TP) ON 31-12-2018; LKK ref : CC6/LPC19000175/Ufb3; Lonpac ref: TBA [External Confidential]
Attachments: LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK Survey photo.pdf; TP LOD_ SLC 7249X.PDF
Importance: High

Without Prejudice

Our Ref: CC6/LPC19000175/Ufb3

Your Ref: TBA

Dear Gerald, 18/18/18/LP05/021283

We refer to the above matter and your mandate approval on 01.03.2019.

We hereby re-seek mandate as TP M/S Tan Lim Motor Pte Ltd counter proposal for loss of rental for **\$180.00** per day, given a point of view that rental vehicle is MPV vehicle and 2400 cc.

Summary to offer to third party repairer, Tan Lim Motor Pte Ltd is as follows: -

	Claimed Amount	Our Revised	TP counter proposal
1. Cost of Repair (w/GST)	\$ 15,944.72 (\$14,901.61 + 7%gst)	\$ 8,560.00 (\$8,000.00 + 7% gst)	\$ 8,560.00 (\$8,000.00 + 7% gst)
2. Loss of Rental	\$ 1,412.40 (\$220.00 x 6 days)+ 7% gst	\$ 963.00 (\$150.00 x 6 days)+7%gst	\$ 1,155.60 (\$150.00 x 6 days)+7%gst
Total	\$ 17,357.12	\$ 9,523.00	\$ 9,715.60

Total amount of claim (Liability 100%)

\$9,715.60

****05** days recommendation for repair + Weekend = 6 days

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Poh Kin (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 1 March 2019 8:28 AM
To: Poh Kin (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKH 1571P (OI) AND SLC 7249X (TP) ON 31-12-2018; LKK ref : CC6/LPC19000175/Ufb3; Lonpac ref: TBA [External Confidential]

Categories: clear

Lonpac External - Confidential

Dear Poh Kin,

Kindly proceed as proposed.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]

Sent: Saturday, 23 February, 2019 11:16 AM

To: GERALD POH WEE BIN

Cc: MT_Claim_SG; Admin A

Subject: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKH 1571P (OI) AND SLC 7249X (TP) ON 31-12-2018; LKK ref : CC6/LPC19000175/Ufb3; Lonpac ref: TBA

Importance: High

Without Prejudice

Our Ref: CC6/LPC19000175/Ufb3

Your Ref: TBA

Dear Gerald,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKH 1571P (OI) AND SLC 7249X (TP) ALONG CTE ON 31/12/2018

We refer to the above matter.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Saturday, 23 February 2019 11:16 AM
To: 'GERALD POH WEE BIN'
Cc: 'MT_Claim_SG'; Admin A
Subject: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKH 1571P (OI) AND SLC 7249X (TP) ON 31-12-2018; LKK ref : CC6/LPC19000175/Ufb3; Lonpac ref: TBA
Attachments: LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK Survey photo.pdf; TP LOD_ SLC 7249X.pdf
Importance: High

Without Prejudice

Our Ref: CC6/LPC19000175/Ufb3
Your Ref: TBA

Dear Gerald,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKH 1571P (OI) AND SLC 7249X (TP) ALONG CTE ON 31/12/2018

We refer to the above matter.

Liability: The accident occurred when our Insured driver collided into rear of third party vehicle. Liability is down against our Insured.

Summary to offer to third party repairer, Tan Lim Motor Pte Ltd is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 15,944.72 (\$14,901.61 + 7%gst)	\$ 8,560.00 (\$8,000.00 + 7% gst)
2. Loss of Rental	\$ 1,412.40 (\$220.00 x 6 days)+ 7% gst	\$ 963.00 (\$150.00 x 6 days)+7%
Total	\$ 17,357.12	\$ 9,523.00

****05 days recommendation for repair + Weekend = 6 days**

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC6/LPC19000175/Ufb3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 29-04-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKH 1571P	Veh. Inspected	SLC 7249X	
Policy No.	Z18VP05020771	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/021283	Excess (\$)	0.00	
Assign From		Assign Date	03/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALPHARD (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	ANH100150253	Colour	GOLD	
Odometer	152598	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	MICHELIN	6 mm	
L/H Front Tyre	215/60R16	MICHELIN	6 mm	
R/H Rear Tyre	215/60R16	MICHELIN	6 mm	
L/H Rear Tyre	215/60R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2018	Inspection Date	03/01/2019	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 7249X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE LID	BADLY DENTED	1,967.56	1,967.56
1	TAILGATE LID CENTRE LOGO BADGE	NECESSARY	85.00	85.00
1	TAILGATE LID ALPHARD BADGE	NECESSARY	75.00	75.00
2	TAILGATE LID REFLECTORS @ \$285.00	CRACKED	570.00	570.00
1	TAILGATE LID WEATHERSTRIP	TWISTED	375.00	375.00
2	TAILGATE LID SIDE CATCH @ \$98.00	NOT NECESSARY	196.00	-
1	TAILGATE LID INNER TRIMBOARD	DEFORMED / CRACKED	429.80	429.80
2	TAILGATE LID RUBBER STOPPERS @ \$16.80	NOT NECESSARY	33.60	-
1	TAILGATE LID LOCK TOP	TWISTED / JAMMED	435.80	435.80
1	TAILGATE LID LOCK LATCH BOTTOM	NOT NECESSARY	55.60	-
1	REAR BUMPER	DISTORTED	1,785.00	1,785.00
2	REAR BUMPER TOW COVER @ \$35.00	NOT FITTED	70.00	-
2	REAR BUMPER SIDE RETAINERS @ \$78.00	BENT	156.00	156.00
4	REAR BUMPER PARKING SENSOR @ \$485.00	SHORTED 3PCS ONLY	1,940.00	1,455.00
1	REAR BUMPER PARKING SENSOR WIRE HARNESS	SERVICEABLE	394.65	-
2	REAR BUMPER SIDE HOLDERS @ \$58.00	NOT NECESSARY	116.00	-
2	REAR BUMPER REFLECTORS @ \$65.00	NOT NECESSARY	130.00	-
2	REAR BUMPER LOWER COVER @ \$245.00	DEFORMED / TWISTED	490.00	490.00
8	REAR BUMPER CLIPS @ \$4.30	NECESSARY	34.40	34.40
2	REAR LAMPS @ \$348.00	NOT NECESSARY	696.00	-
1	REAR LAMP APRON GARNISH	NO SUCH PARTS	248.00	-
1	REAR END PANEL OUTER	BADLY DENTED	625.00	625.00
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	599.80	-
1	REAR END PANEL INNER TOP GARNISH	TWISTED	225.00	225.00
1	SPARE TYRE CARRIAGE HOLDER	NOT NECESSARY	224.60	-
1	REAR EXHAUST PIPE	DENTED / CRACKED	855.80	855.80
2	REAR LICENCE PLATE LAMP @ \$85.00	NOT NECESSARY	170.00	-

Report Ref No. CC6/LPC19000175/Ufb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LICENCE PLATE GARNISH	NOT NECESSARY	197.00	-
1	REAR LICENCE PLATE CHROME GARNISH TOP	NOT NECESSARY	212.40	-
1	REAR LICENCE PLATE CHROME GARNISH BOTTOM	NOT NECESSARY	269.80	-
2	REVERSE LAMP @ \$303.00	NOT NECESSARY	606.00	-
	LESS 25% DISCOUNT		-3,567.20	-2,391.09
			10,701.61	7,173.27
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERRE CCTV CAMERA (SN)	SHORTED	600.00	450.00
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	70.00	30.00
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	70.00	-
			860.00	520.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		250.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	30.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	60.00
	TO DROP REAR EXHAUST BOX AND RENEW THE SAME.		120.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		180.00	80.00
	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATER SEEPAGE TEST.		150.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER.		1,280.00	880.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,000.00	980.00
			-	-
			-	-
			-	-
			3,340.00	2,320.00
GRAND TOTAL			14,901.61	10,013.27

Report Ref No. CC6/LPC19000175/Ufb3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,000.00
---	--	--	----------

Report Ref No. CC6/LPC19000175/Ufb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.