



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Lonpac Insured's Veh No : SKH1571P
Date of Accident : 31 December 2018

Miss Tan Bee Chin (Chen Meizhen)

Date : 03 January 2019

Estimate To Repair SLC7249X - Toyota Alphard 2.4 A
Chassis No : ANH100150253

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>Body</i>	\$ 1,967.56
02	1 pc	tailgate lid centre logo badge <i>rec</i>	\$ 85.00
03	1 pc	tailgate lid Alphard badge <i>rec</i>	\$ 75.00
04	2 ps	tailgate lid reflectors @ \$285.00 <i>cm</i>	\$ 570.00
05	1 pc	tailgate lid weatherstrip <i>twi</i>	\$ 375.00
06	2 ps	tailgate lid side catch @ \$98.00 <i>11</i>	\$ 196.00
07	1 pc	tailgate lid inner trimboard <i>Del/cu</i>	\$ 429.80
08	2 ps	tailgate lid rubber stoppers @ \$16.80 <i>11</i>	\$ 33.60
09	1 pc	tailgate lid lock top <i>twi/jm</i>	\$ 435.80
10	1 pc	tailgate lid lock latch bottom <i>11</i>	\$ 55.60
11	1 pc	rear bumper <i>D.S</i>	\$ 1,785.00
12	2 ps	rear bumper tow cover @ \$35.00 <i>PRF</i>	\$ 70.00
13	2 ps	rear bumper side retainers @ \$78.00 <i>Recd</i>	\$ 156.00
14	4 ps	rear bumper parking sensor @ \$485.00 <i>shhd</i>	\$ 1,940.00
15	1 pc	rear bumper parking sensor wire harness <i>src</i>	\$ 394.65
16	2 ps	rear bumper side holders @ \$58.00 <i>11</i>	\$ 116.00
17	2 ps	rear bumper reflectors @ \$65.00 <i>11</i>	\$ 130.00
18	2 ps	rear bumper lower cover @ \$245.00 <i>Del/tw</i>	\$ 490.00
19	8 ps	rear bumper clips @ \$4.30 <i>rec</i>	\$ 34.40
20	2 ps	rear lamps @ \$348.00 <i>11</i>	\$ 696.00
21	1 pc	rear lamp apron garnish <i>PRF</i>	\$ 248.00
22	1 pc	rear end panel outer <i>Body</i>	\$ 625.00
23	1 pc	rear end panel inner <i>2</i>	\$ 599.80
24	1 pc	rear end panel inner top garnish <i>twi</i>	\$ 225.00
25	1 pc	spare tyre carriage holder <i>11</i>	\$ 224.60
26	1 pc	rear exhaust pipe <i>10/cu</i>	\$ 855.80
27	2 ps	rear licence plate lamp @ \$85.00 <i>11</i>	\$ 170.00
28	1 pc	rear licence plate garnish <i>11</i>	\$ 197.00
29	1 pc	rear licence plate chrome garnish top <i>11</i>	\$ 212.40
30	1 pc	rear licence plate chrome garnish bottom <i>11</i>	\$ 269.80
31	2 ps	reverse lamp @ \$303.00 <i>11</i>	\$ 606.00
Less 25 %			\$ 14,268.81
			\$ 3,567.20
			\$ 10,701.61
<u>SPECIAL NETT ITEMS</u>			
32	1 pc	reverse CCTV camera <i>shhd</i>	\$ 600.00
33	1 set	rear windscreen sealant <i>rec</i>	\$ 120.00
34	1 pc	rear windscreen inner sponge seal <i>rec</i>	\$ 70.00

Not Attached
3/1/19
1/5 #8000/2/1/19
Sdy.
Take photo of the car

Lik - M/LUS
03/01/19 0930hr

9564.36
7173.27

450
40
30



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Lonpac Insured's Veh No : SKH1571P
Date of Accident : 31 December 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Tan Bee Chin (Chen Meizhen)

Date : 03 January 2019

Estimate To Repair SLC7249X - Toyota Alphard 2.4 A
Chassis No : ANH100150253

S/No	Quantity	Description	Amount
35	1 pc	<u>SPECIAL NETT ITEMS</u> rear licence plate	\$ 11 70.00 X \$ 860.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To remove and refit rear windscreen glass.	\$ 180.00 120
02		To reinstall of rear bumper parking sensor.	\$ 250.00 50
03		To check electrical lighting concerned.	\$ 60.00 30
04		To rust-proofing of the affected areas.	\$ 120.00 60
05		To drop rear exhaust box and renew the same.	\$ 120.00 60
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00 80
07		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00 60
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,280.00 880
09		Putty and spray painting of the affected portion.	\$ 1,000.00 980
			\$ 3,340.00
		Total	\$ 14,901.61

LKF Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9783.27