

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8053C

DATE 2/1/2019 14:46

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Licence Lamp Cover ✓			\$ 100.00
	Rear Bumper <i>X repair</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>X</i>			\$ 22.00
	SUB TOTAL			\$ 675.00
	LESS 20%			\$ 135.00
	DISCOUNTED TOTAL			\$ 540.00
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				\$ 250.00
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00 <i>200</i>
	Wiring Charge			\$ 30.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 80.00 <i>X</i>
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,600.00
<p><i>Kalish 16/11/19</i></p> <p><i>2/1/19 1600hrs.</i></p> <p><i>2 Days</i></p> <p><i>P/P</i></p> <p><i>After Repair p/h</i></p> <div data-bbox="820 1396 1388 1900" data-label="Text"> <p>LKK Auto Consultants hence notify the Insurer of the following:</p> <ul style="list-style-type: none"> • Insurer to be notified of any painting • Insurer to be notified of any damage • Parts prices are subject to confirmation • Third party survey is on a "without prejudice" basis • No illegal or unauthorised work • Supplier of parts is subject to insurance and is subject to approval from insurance company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				