

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9438U

DATE 2/1/2019 14:39

MAKE :

MODEL : HYUNDAI i40

LKK/Kahin

plyp

Lke

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover /			\$ 1,052.20
	Front Bumper Grille (RH) -			\$ 41.60
	Front Bumper Bracket Top (RH) x			\$ 22.40
	Front Bumper Bracket (RH) x			\$ 24.60
	SUB TOTAL			\$ 1,140.80
	LESS 20%			\$ 228.16
	DISCOUNTED TOTAL			\$ 912.64
	Front Number Plate x			\$ 25.00
				\$ 25.00
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 300.00 ²⁰⁰
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 1,637.64

Nett

Kahin (LKK)
2/1/19 1505h
2 days
PIP
Before part plh

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental charges must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.