

LKK

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9098J (CCPL)

DATE 12/29/2018 10:54

Alt

MAKE :

Chang

MODEL : HYUNDAI i40

LS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 544.50
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Headlamp (RH) ✕			\$ 1,388.00
	Front Fender (RH) ✓			\$ 566.30
	Front Fender Shield (RH) ✕			\$ 174.90
	Front Fender Retainer (RH) ✕			\$ 24.60
SUB TOTAL				\$ 2,729.90
LESS 20%				\$ 545.98
DISCOUNTED TOTAL				\$ 2,183.92
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
TOTAL				\$ 100.00
Labour Charge				
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
TOTAL LABOUR				\$ 1,080.00
ESTIMATE TOTAL				\$ 3,363.92

Nett

200

400

✕

20

Kali 10/11/19
2/1/19 1120L
2 days
4/5
After Repair p.k.

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.