



FALCON-AIR

NG BEOW LUAN
C/O FALCON AIR AUTO SERVICES PTE LTD
NO. 8 PANDAN LOOP

Attention : Motor Claim Department

Contact : 98259565

Estimate : ES003362

Date : 03/01/2019
Vehicle Num. : SFR3061M
Make/Model : TOYOTA CAMRY
Chassis/Eng# :
Accident Date : 31/12/2018
Claim No. :
Reference : TP CLAIM - NTUC vs EQ
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	FRONT GRILLE WITH LOGO <i>CRA</i> ✓		475.00
2.	1 PC	LH HEADLAMP <i>CRA</i> ✓		780.00
3.	1 PC	BRACE PANEL <i>PA</i> ✓		65.00
4.	1 PC	FRONT BUMPER <i>SCA</i> ✓		605.60
5.	1 PC	FRONT BUMPER TOP BEAM <i>PA</i> ✓		75.00
6.	1 PC	FRONT BUMPER REINFORCEMENT ?		465.00
7.	1 PC	FRONT BUMPER SPONGE <i>CRA</i> ✓		145.00
8.	2 PCS	FRONT BUMPER CHROME MOULDING LH/RH <i>new</i> ✓	70.00	140.00
9.	1 PC	FOG LAMP LH <i>CRA</i> ✓		420.00
10.	2 PCS	FRONT BUMPER SIDE RETAINER <i>new</i> / 1 pc LH	<u>55.00</u>	110.00
	<i>1 PC</i>			
List TotalS\$:				3,280.60
25.00% Discount S\$:				820.15
				<u>2,460.45</u>
SPECIAL NETT ITEMS :				
1.	1 PC	FRONT NUMBER PLATE <i>PA</i> ✓		45.00
2.	10 PCS	CLIPS <i>new</i> ✓	5.00	50.00
Special Nett Total S\$:				<u>95.00</u>
LABOUR :				
TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM				<i>20</i> <u>30.00</u>

CONTINUE / ...


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

NG BEOW LUAN
C/O FALCON AIR AUTO SERVICES PTE LTD
NO. 8 PANDAN LOOP

Attention : Motor Claim Department
Contact : 98259565

Estimate : ES003362

Date : 03/01/2019
Vehicle Num. : SFR3061M
Make/Model : TOYOTA CAMRY
Chassis/Eng# :
Accident Date : 31/12/2018
Claim No. :
Reference : TP CLAIM - NTUC vs EQ
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO REMOVE/REFIX AIRCON CONDENSOR, VACUUM AND REGAS
TO FACILITATE REPAIRS
TO REPAIR RADIATOR SUPPORT PANEL, BONNET, FRONT FENDER
CHASSIS, INCLUDING KNOCKING AND REPLACEMENT OF PARTS
SPRAY PAINTING

120.00 100

600.00 400

900.00 800.70

Labour Total S\$:

1,650.00

Repair
4p 9000 w68
4 days
4/1
03/01/19 @ 1415
Ready after repair

E. & O.E.

Total S\$: 4,205.45

[Signature]
for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg