



FALCON-AIR

NG BEOW LUAN
C/O FALCON AIR AUTO SERVICES PTE LTD
NO. 8 PANDAN LOOP

Attention : Motor Claim Department

Contact : 98259565

Page 1 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003362

Date : 03/01/2019
Vehicle Num. : SFR3061M
Make/Model : TOYOTA CAMRY
Chassis/Eng# :
Accident Date : 31/12/2018
Claim No. :
Reference : TP CLAIM - NTUC vs EQ
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	FRONT GRILLE WITH LOGO		475.00
2.	1 PC	LH HEADLAMP		780.00
3.	1 PC	BRACE PANEL		65.00
4.	1 PC	FRONT BUMPER		605.60
5.	1 PC	FRONT BUMPER TOP BEAM		75.00
6.	1 PC	FRONT BUMPER REINFORCEMENT		465.00
7.	1 PC	FRONT BUMPER SPONGE		145.00
8.	2 PCS	FRONT BUMPER CHROME MOULDING LH/RH	70.00	140.00
9.	1 PC	FOG LAMP LH		420.00
10.	2 PCS	FRONT BUMPER SIDE RETAINER	55.00	110.00
List TotalS\$:				3,280.60
25.00% Discount S\$:				820.15
				2,460.45
SPECIAL NETT ITEMS :				
1.	1 PC	FRONT NUMBER PLATE		45.00
2.	10 PCS	CLIPS	5.00	50.00
Special Nett Total S\$:				95.00
LABOUR :				
TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM				30.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

NG BEOW LUAN
C/O FALCON AIR AUTO SERVICES PTE LTD
NO. 8 PANDAN LOOP

Attention : Motor Claim Department

Contact : 98259565

Page 2 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003362

Date : 03/01/2019
Vehicle Num. : SFR3061M
Make/Model : TOYOTA CAMRY
Chassis/Eng# :
Accident Date : 31/12/2018
Claim No. :
Reference : TP CLAIM - NTUC vs EQ
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REMOVE/REFIX AIRCON CONDENSOR, VACUUM AND REGAS TO FACILITATE REPAIRS		120.00
		TO REPAIR RADIATOR SUPPORT PANEL, BONNET, FRONT FENDER CHASSIS, INCLUDING KNOCKING AND REPLACEMENT OF PARTS		600.00
		SPRAY PAINTING		900.00
		Labour Total S\$:		1,650.00

E. & O.E.

Total S\$: 4,205.45

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg