

Sheet1

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526

Email : chris_chanbebe@hotmail.com

02nd January 2019

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPAXA.

Poh Kin

JNISC2F242085942

Accident date: 28th December 2018

Estimated repair cost for vehicle no: GBG40Z NISSAN CABSTAR '17

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid <i>Dented.</i>		\$1,688.40
2	2	Rear boot lid side lock <i>RH Best</i>	\$183.20	\$366.40 <i>183.20</i>
3	1	Rear center lower crossmember <i>HP m</i>		\$650.00 <i>X</i>
4	1	Rear boot lid aluminium cover <i>HP m</i>		\$1,109.50 <i>X</i>
5	10	Rear boot lid aluminium cover devit <i>HP m</i>	\$5.00	\$50.00 <i>X</i>
Subtotal :-				\$3,864.30

S/n	Qty	Items/Nett	U/price	Amount
1	2	Rear boot lid top lock <i>new</i>	\$81.50	\$163.00 <i>X</i>
2	1	Rear End Panel <i>Dented</i>		\$858.00 <i>458</i>
3	2	Rear end panel Side Bracket <i>RH Best</i>	\$182.10	\$364.20 <i>182.10</i>
4	2	Rear Boot Lid Top Side Hinge <i>HP m</i>	\$183.20	\$366.40 <i>X</i>
5	2	Rear boot lid lower side hinge <i>RH Best</i>	\$201.30	\$402.60 <i>53</i>
6	2	Rear tail lamp <i>RH cruled</i>	\$215.00	\$430.00 <i>215</i>
7	2	Rear tail lamp panel <i>RH Best</i>	\$181.10	\$362.20 <i>181.10</i>
8	1	Rear number plate lamp <i>HP m</i>		\$54.00 <i>X</i>
9	1	Rear spare tire lock <i>HP m</i>		\$365.10 <i>X</i>
10				
11				
Subtotal :-				\$3,365.50

2960.80

2664.72

S/n	Qty	Items/S/Nett	U/price	Amount
1	1	Rear number plate <i>NRN</i>		\$50.00 <i>x</i>
2	1	Rear boot lid 70 km/h logo <i>NRN</i>		\$30.00 <i>x</i>
3	1	Rear boot lid lower nissan logo <i>NRN</i>		\$108.00 <i>x</i>
4	1	Rear boot lid lower cabstar logo <i>NRN</i>		\$78.30 <i>x</i>
Reverse Sensor Damaged <i>280 200</i>				Subtotal :- \$266.30

323

Labour charges

To Check Wiring System

Panel beating

Spray painting

~~\$80.00~~ 30

~~\$800.00~~ 500

~~\$800.00~~ 600

Subtotal :- \$1,680.00

Total:- \$9,176.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4217.72

4/5: 3350.

06 Days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 1231K

Vehicle Details

Vehicle No.: GBG40Z
Vehicle to be Exported: Yes
Intended Deregistration Date: 31 Dec 2018
Vehicle Make: NISSAN
Vehicle Model: CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: ZD30016425N
Chassis No.: JN1SC2F24Z0859442
Maximum Power Output: \$25,665.00
Open Market Value: 19 May 2017
Original Registration Date: 19 May 2017
First Registration Date: 0
Transfer Count: \$1,284.00
Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: \$0.00
PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date: 18 May 2027
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$26,029.00
COE Rebate Amount: \$20,823.00
Total Rebate Amount: \$20,823.00

The information contained herein is correct as at 31 Dec 2018

OK