

TO : ESTIMATE REPORT 1ST Quotation OWNER'S PARTICULARS NAME: CityCab PTE LTD (Fleet) ADDRESS: 383 SIN MING DRIVE SINGAPORE 575717 0	Date: Signature: Acknowledged by Reparer is subject to final approval from Insurance Company • Supplementary item(s) must be resurveyed and • No illegal modification(s) is allowed • Third party survey is on a "Without Prejudice" basis • Parts prices are subject to confirmation • To display damaged part(s) during resurvey • To resurvey before after spray painting the Reparer of the following: CONTACT: 65533880 LKK Auto Co. 64739522	FAX NO: 03/01/2019 9:30 JOB-NO: 50111267 Page 1 of 2
---	--	--

VEHICLE DETAILS

LICENSE NO: SHC7084B	TRANS: AUTO	CHASSIS: KMHLB41UMGU086866
MAKE / MODEL: HYUNDAI / i40		ENGINE: D4DFDU606554
OWNER'S INSURER: MS First Capital Insurance Limited		
JOB-CODE: TP	SA: Ding Auto User 1	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	800.00	0.00	800.00 300		Y	
2 R&R CONDENSOR AND RADIOTR .AND REFILL AIRCON GAS	1.00	120.00	0.00	120.00 X		Y	
3 R&R FRONT WHEEL RIM & TYRE	1.00	100.00	0.00	100.00 X		Y	
4 FRONT WHEEL BALANCING AND ALIGNMENT	1.00	120.00	0.00	120.00 60		Y	
5 SPRAY PAINTING ON FRONT BUMPER ,BONNET AND FRONT FENDER RHS	1.00	800.00	0.00	800.00 400		Y	
6 CHECK WIRING	1.00	80.00	0.00	80.00 30		Y	
7 RUSH PROOFING	1.00	80.00	0.00	80.00 40		Y	
TOTAL:		2,100.00	0.00	2,100.00			
MATERIALS							
1 FRONT BUMPER repair	1.00	599.68	119.94	479.74	L	Y	
2 FRONT BUMPER RETAINER RH X	1.00	42.32	8.46	33.86	L	Y	
3 FRONT FENDER RH repair	1.00	523.86	104.77	419.09	L	Y	
4 FRONT FENDER RH INNERSHIELD ?	1.00	175.00	35.00	140.00	L	Y	
5 HEAD LAMP RH ?	1.00	1,808.68	361.74	1,446.94	L	Y	
6 SUPPORT PANEL X	1.00	917.58	183.52	734.06	L	Y	
7 WHEEL CAP FRONT RH see	1.00	265.50	53.10	212.40	L	Y	
8 FRONT WHEEL BEARING RH X	1.00	362.50	72.50	290.00	L	Y	
9 FRONT LOWER ARM RH X	1.00	438.90	87.78	351.12	L	Y	
10 FRONT ABORBER RHS X	1.00	438.90	87.78	351.12	L	Y	
11 FRONT BUMPER CLIPS repair	1.00	35.00	0.00	35.00	S	Y	
12 FRONT FENDER RH INNER SHIELD CLIP repair	1.00	35.00	0.00	35.00	S	Y	
13 FRONT FENDER RH ADS STICKER repair	1.00	180.00	0.00	180.00 150	S	Y	
14 FRONT TYRE RH X	1.00	250.00	0.00	250.00	S	Y	
TOTAL:		6,072.92	1,114.59	4,958.33			
TOTAL PARTS & LABOUR :		8,172.92	1,114.59	7,058.33			

EXCESS/LOADING:\$ 0.00

No. Of Day: 3 days

RE-SURVEY BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 04 / 01 / 19 @

Rasul - Hp 90010068

P/P - Resurvey 64 paint