

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBE5215P (AIG)

Accident Date : 25-12-2018

Date : 02-01-2019

Our Ref : SGB8680R /CHAN

LEE QUEE LAM @ LEE KWAI LUM  
C/O ALAN'S UNITED AUTO PTE LTD  
BLK 7 SIN MING IND. EST. SECTOR C  
#01-76  
SINGAPORE 575642

*Not Notified*

*Runny After Rain*

*4 days*

## ESTIMATE REPAIR PRICE FOR VOLVO XC60 2.5 SGB8680R

1 PC	FRONT BUMPER FASCIA		\$1,116.00	7
1 PC	FRONT N/S BUMPER SIDE RETAINER		\$74.00	7
1 PC	FRONT N/S BUMPER LOWER PAD	in	\$267.00	X
1 PC	FRONT N/S FENDER	K	\$1,274.00	X
1 PC	FRONT N/S FENDER WHEEL ARCH GARNISH	in	\$187.00	X
10 PCS	FRONT N/S WHEEL ARCH GARNISH CLIP @ \$6.00	na	\$60.00	X
10 PCS	FRONT N/S FENDER INNER SHIELD CLIP \$3.50	na	\$35.00	X
1 PC	N/S HEADLAMP		\$954.00	7
1 PC	N/S MIRROR ASSY		\$1,807.00	7
			\$5,774.00	
		LESS 10%	\$577.40	
			<u>\$5,196.60</u>	
			\$5,196.60	

TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM

\$20.00 ✓

TO CHECK AND ADJUST WHEEL ALIGNMENT

\$65.00 601

TO PUTTY AND SPRAY REPLACED PARTS

\$700.00 5501

TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, ALIGN, REPAIR AND TO RENEW ABOVE PARTS

\$600.00 4001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# **ALAN'S UNITED AUTO PTE. LTD.**

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

**GST Reg. No.: 201113667N**

\$6,581.60

Singapore Dollars Six Thousand Five Hundred Eighty One And Cents Sixty Only