

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9998G**AAD1812-226***Not Notified*
1/2 up \$5600

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9998G

VF1ABL15AUC275221

RENAULT

LATITUDE

28.12.2018

CHINA TAIPING

30/10/2013

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>Br</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Dir</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 } X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61
14	1	RADIATOR GRILLE	\$	1,707.78 ?
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36 ? } XN
16	1	RADIATOR GRILLE FRAME	\$	1,353.75 ?
17	1	FRAME FULL SUPPORT PANEL	\$	615.90 ?
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>SL</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>Br</i> 1,184.43 ✓
23	1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 ✓
25	1	BONNET	\$	<i>R</i> 1,941.63 ✓
26	1	BONNET INSULATOR	\$	<i>SL</i> 405.73 X
27	1	BONNET STRUT LH	\$	<i>SL</i> 88.61 X
28	1	BONNET STRUT RH	\$	<i>SL</i> 88.61 X
29	1	BONNET HINGE LH	\$	<i>Dir</i> 348.31 ✓

Trans-cab Auto Services Pte Ltd**AAD1812-226**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9998G

30	1	BONNET HINGE RH	\$	348.31	X
31	1	BONNET LOCK	\$	305.48	X
32	1	BONNET CABLE	\$	119.19	X
33	1	BONNET CABLE COVER	\$	161.03	X
34	1	BONNET SEAL OUTER	\$	92.36	X
35	1	BONNET SEAL INNER	\$	157.28	X
36	1	FENDER PANEL FRT LH	\$	783.83	
37	1	WHEELARCH FRT LH	\$	278.84	
38	1	FENDER BRACKET LOWER LH	\$	15.79	
39	1	FENDER INSULATOR LH	\$	130.84	
40	1	FENDER PANEL INNER FRT LH	\$	1,693.77	
41	1	FENDER PANEL REINFORCEMENT FRT LH	\$	1,096.22	
42	1	WHEEL HOUSING PANEL FRT LH	\$	5,173.47	
43	1	TURBO DUCT	\$	1,027.80	
44	1	A/C HEATER VALVE	\$	484.50	
45	1	SUBFRAME OUTER FRT	\$	2,652.45	
46	1	SUBFRAME BRACKET OUTER LH	\$	92.36	
47	1	SUBFRAME BRACKET OUTER RH	\$	92.36	
48	1	ENGINE UNDERTRAY	\$	564.98	
49	1	A/C CONDENSER	\$	2,020.37	
50	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	
51	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	
52	1	A/C CONDENSER GARNISH LH	\$	58.81	
53	1	A/C CONDENSER GARNISH RH	\$	59.60	
54	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39	
55	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72	
74	1	A/C PIPE COMPRESSOR	\$	334.29	
75	1	A/C PIPE	\$	658.72	
76	1	A/C COMRPRESSOR	\$	2,684.61	
77	1	AIR COOLER	\$	792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	
80	1	TRANSMISSION COOLER	\$	1,219.30	
81	1	TRANSMISSION COOLER PAD	\$	17.96	
82	1	RADIATOR	\$	1,202.20	
83	2	RADIATOR STUD UPPER	\$	14.41	
84	2	RADIATOR BUSH UPPER	\$	50.12	
85	2	RADIATOR MTG LOWER	\$	55.85	

Trans-cab Auto Services Pte Ltd

AAD1812-226

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9998G

86	1	RADIATOR FAN COWLING	\$	820.54	} X
87	1	RADIATOR FAN MOTOR LH	\$	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46	
89	1	RADIATOR TANK	\$	324.62	
90	1	RADIATOR HOSE UPPER	\$	240.56	
91	1	RADIATOR HOSE LOWER	\$	491.18	
92	1	RADIATOR TANK HOSE	\$	61.18	

TOTAL	\$	45,305.01
10%	\$	4,530.50
	\$	40,774.51

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	} X
2	1SET	BUMPER CLIP FRT	\$	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	
7	1	TOW COVER FRT	\$	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
21	1	Windscreen moulding	\$	100.00	

TOTAL	\$	482.50
TOTAL PARTS	\$	41,257.01

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 4,000.00 6001

Towing Fees.

\$ 120.00 501

Trans-cab Auto Services Pte Ltd**AAD1812-226**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9998G

To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
Putty and spray painting of the affected portion.	\$	4,000.00 <i>800/</i>
To rust-proofing of the affected areas.	\$	170.00 <i>90/</i>
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To remove and refit air bag system and reset.	\$	nn 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>100/</i>
To replace, refix and top up coolant for radiator	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1812-226**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9998G

To vacuum, replace, refix and recharge Air
Intercooler

\$ 170.00 X

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 X

To Transfer Of Bonnet Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 X

To Transfer Of Door Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 X

TOTAL \$ 13,000.00**Over All Total \$ 54,257.01****Repair Days (Lump Sum)**~~20~~ days

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: