

Not withered
Resurvey B4paint 1-B1

6 days



ESTIMATE TO REPAIR

VEHICLE NO. : SJN 1030 P
MAKE : TOYOTA
MODEL : ESQUIRE 2.0XI A
YEAR : 2017
CHASSIS NO : ZRR800234592

SURVEYOR NAME :	
DATE OF SURVEY :	03 JAN 2019
TIME OF SURVEY :	1- 45pm

DATE : 31-Dec-18
DATE OF ACCIDENT : 29-Dec-18
THIRD PARTY REF : SJQ 7465 M / EQ INSURANCE

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ B1 664.00 ✓
2 pcs	Rear Bumper Bracket		\$ 107.00		\$ 214.00 ?
2 pcs	Rear Bumper Retainer		\$ 131.00		\$ 262.00 x
1 pc	Rear End Panel				\$ 918.00 ?
1 pc	Rear End Panel Garnish				\$ 258.00 ✓
1 pc	Rear Spare Tyre Top Cover				\$ 818.00 ✓
1 pc	Tailgate				\$ 1,685.00 ✓
1 pc	Tailgate Rubber				\$ 356.00 ?
1 pc	Tailgate Lock				\$ 498.00 ✓
1 pc	Tailgate Emblem				\$ 57.00 ✓
1 set	Rear Windscreen Moulding				\$ 160.00 ✓
					\$ 5,890.00
	Less 25%				\$ 1,472.50
					\$ 4,417.50
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00 ✓
1 set	Rear Bumper Sensor	S.Nett			\$ 300.00 ?
	To putty and spray painting				\$ 800.00 600
	To transfer tailgate fittings				\$ 80.00 600
	To remove and refix rear windscreen glass				\$ 120.00 ✓
	To anti-rust				\$ 80.00 600
	Labour Charges				\$ 750.00 600
TG/RA-					\$ 6,587.50
		Acknowledged by Repairer:			
		Signature:			
		Date:			

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd