



ESTIMATE TO REPAIR

VEHICLE NO. : SJN 1030 P
 MAKE : TOYOTA
 MODEL : ESQUIRE 2.0XI A
 YEAR : 2017
 CHASSIS NO : ZRR800234592

| |
|------------------|
| SURVEYOR NAME : |
| DATE OF SURVEY : |
| TIME OF SURVEY : |

DATE : 31-Dec-18
 DATE OF ACCIDENT : 29-Dec-18
 THIRD PARTY REF : SJQ 7465 M / EQ INSURANCE

| No. | Parts Description/ Labour | Type | Unit Price | Nett Item Amt | Amount |
|--------|---|--------|------------|---------------|-------------|
| 1 pc | Rear Bumper | | | | \$ 664.00 |
| 2 pcs | Rear Bumper Bracket | | \$ 107.00 | | \$ 214.00 |
| 2 pcs | Rear Bumper Retainer | | \$ 131.00 | | \$ 262.00 |
| 1 pc | Rear End Panel | | | | \$ 918.00 |
| 1 pc | Rear End Panel Garnish | | | | \$ 258.00 |
| 1 pc | Rear Spare Tyre Top Cover | | | | \$ 818.00 |
| 1 pc | Tailgate | | | | \$ 1,685.00 |
| 1 pc | Tailgate Rubber | | | | \$ 356.00 |
| 1 pc | Tailgate Lock | | | | \$ 498.00 |
| 1 pc | Tailgate Emblem | | | | \$ 57.00 |
| 1 set | Rear Windscreen Moulding | | | | \$ 160.00 |
| | | | | | \$ 5,890.00 |
| | Less 25% | | | | \$ 1,472.50 |
| | | | | | \$ 4,417.50 |
| 1 tube | Rear Windscreen Sealant | S.Nett | | | \$ 40.00 |
| 1 set | Rear Bumper Sensor | S.Nett | | | \$ 300.00 |
| | To putty and spray painting | | | | \$ 800.00 |
| | To transfer tailgate fittings | | | | \$ 80.00 |
| | To remove and refix rear windscreen glass | | | | \$ 120.00 |
| | To anti-rust | | | | \$ 80.00 |
| | Labour Charges | | | | \$ 750.00 |
| TG/RA- | | | | | \$ 6,587.50 |
| | | | | | |

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd