

Kp kf.

Not Authorized
 Running B4 paint 1-B1 @ 5553.50

6 days



ESTIMATE TO REPAIR

VEHICLE NO. : SJN 1030 P
 MAKE : TOYOTA
 MODEL : ESQUIRE 2.0XI A
 YEAR : 2017
 CHASSIS NO : ZRR800234592

SURVEYOR NAME :	
DATE OF SURVEY :	03 JAN 2019
TIME OF SURVEY :	1.45pm

DATE : 31-Dec-18
 DATE OF ACCIDENT : 29-Dec-18
 THIRD PARTY REF : SJQ 7465 M / EQ INSURANCE

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc ✓	Rear Bumper			\$ B1	664.00
2 pcs	Rear Bumper Bracket		\$ 107.00	R	214.00
3 pcs	Rear Bumper Retainer		\$ 131.00	Sen	262.00
1 pc	Rear End Panel			B1	918.00
1 pc ✓	Rear End Panel Garnish			B1	258.00
1 pc ✓	Rear Spare Tyre Top Cover			cmz	818.00
1 pc ✓	Tailgate			B1	1,685.00
1 pc	Tailgate Rubber			Sen	356.00
1 pc	Tailgate Lock			pd	498.00
1 pc	Tailgate Emblem			Sen	57.00
1 set ✓	Rear Windscreen Moulding			Sen	160.00
	Less 25%				5,890.00
					1,472.50
					4,417.50
1 tube	Rear Windscreen Sealant	S.Nett	Paint	\$5058.00	\$ Sen 40.00
1 set	Rear Bumper Sensor	S.Nett	-25%	\$1264.50	\$ shot 300.00
	To putty and spray painting			\$3793.50	\$ 800.00
	To transfer tailgate fittings		SH	\$340.00	\$ 80.00
	To remove and refix rear windscreen glass		labour	\$1500.00	\$ 120.00
	To anti-rust		ppp	\$5633.00	\$ 80.00
	Labour Charges		OG	days	\$ 750.00
TG/RA-					\$ 6,587.50