

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811

Accident date:31/12/18

Date:02/01/19

• office
Tanjun 97495749 / 62563561
-wp
3/1/19 @ 1030.
Returning after repair
sur@lkhauto.com
11 days

Estimate cost to repair vel:SKD 8968D (Mazda 323) claims under vel: SLJ 1658B.

1pcs rear inner side sponge

L \$ 165.10 cur

1pce rear windscreen outer rubber	\$ 77.00	ne
1pce rear windscreen inner tape form	45.00	ne
1pce rear windscreen inner sealant	120.00	ne
1pce rear windscreen sun x sticker	250.00	ne
2pcs rear fenders@\$1,232.90	2,456.80	LH-bt ✓, RH-Rx
2pcs rear wheel housing@\$1.547	3,094.00	Rx
2pcs rear fender trim cover@\$154.30	308.60	X
1pce rear spare tyer panel	524.70	Rx
1set rear spare tyer panel paddling	280.00	X an
1pce rear boot lid	852.65	bt ✓
2pcs rear boot lid hinges@\$145.30	290.60	Rx
1pce rear boot lid op lock	153.00	bt -
1pce rear boot lid lower lock	35.40	bt ✓
1pce rear boot lid rubber	129.30	? TN ✓
1pce rear boot lid emblem	74.40	ne
1pce rear boot lid skyactiv plate	63.60	ne
1pce rear boot lid mazda 3 plate	53.40	ne
2pcs rear boot lid reflector@\$915	1,830.00	X cut ✓
2pcs tail lamps@\$466.40	932.80	? cut ✓
2pcs tail lamp inner panel@\$377.80	755.60	RH-Rx
1pce rear bumper	1,074.80	cur ✓
2pcs rear bumper tow cover@\$18.20	36.40	mi ✓
4pcs rear bumper reverse sensor@\$180	720.00	3pc - rx ✓
2pcs rear bumper reflector@\$51	102.00	LH-X ⁿⁿ RH-cut ✓
1pce rear bumper reinforcement ~ photo	537.30	bt ✓
10pcs rear bumper inner clip@\$9.50	95.00	ne ✓
2pcs rear bumper side holder@\$38.10	76.20	ne ✓
2pcs rear bumper top clips@\$10	20.00	ne ✓

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

office

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811

Accident date:31/12/18

Date:02/01/19

Tan Jia 97495749 / 62563561
-wp
3/1/19 @ 1030.
Reserving after repair
sur@lkhauto.com
11 days

Estimate cost to repair vel:SKD 8968D (Mazda 323) claims under vel: SLJ 1658B.

1-pcs rear inner side sponge

\$ 165.10 cur

1pce rear windscreen outer rubber	\$ 77.00	new
1pce rear windscreen inner tape form	45.00	new
1pce rear windscreen inner sealant	120.00	new
1pce rear windscreen sun x sticker	250.00	new
2pcs rear fenders@\$1,232.90	2,456.80	LH-bt ✓, RH-RP
2pcs rear wheel housing@\$1.547	3,094.00	RP
2pcs rear fender trim cover@\$154.30	308.60	X
1pce rear spare tyer panel	524.70	RP
1set rear spare tyer panel paddling	280.00	X an
1pce rear boot lid	852.65	bt ✓
2pcs rear boot lid hinges@\$145.30	290.60	RP
1pce rear boot lid op lock	153.00	bt -
1pce rear boot lid lower lock	35.40	bt ✓
1pce rear boot lid rubber	129.30	? TNV
1pce rear boot lid emblem	74.40	new
1pce rear boot lid skyactiv plate	63.60	new
1pce rear boot lid mazda 3 plate	53.40	new
2pcs rear boot lid reflector@\$915	1,830.00	X cut ✓
2pcs tail lamps@\$466.40	932.80	? cut ✓
2pcs tail lamp inner panel@\$377.80	755.60	new - RP
1pce rear bumper	1,074.80	cur
2pcs rear bumper tow cover@\$18.20	36.40	new
4pcs rear bumper reverse sensor@\$180	720.00	3pc - new
2pcs rear bumper reflector@\$51	102.00	LH-X, RH - cut ✓
1pce rear bumper reinforcement - photo	537.30	bt ✓
10pcs rear bumper inner clip@\$9.50	95.00	new
2pcs rear bumper side holder@\$38.10	76.20	new
2pcs rear bumper top clips@\$10	20.00	new

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811

Accident date:31/12/18

Date:02/01/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate cost to repair vel:SKD 8968D (Mazda 323) claims under vel: SLJ 1658B.

Page 2		
1pce rear exhaust pipe - photo.	\$ 1,088.70	? SCR ✓
2pcs rear exhaust pipe rubber holder@\$33.30	66.60	? MNX
1pce rear exhaust pipe heat cover	87.00	? BT ✓
1pce rear panel	505.10	bt ✓
1pce rear panel lower lock cover garnish	158.00	? ✓ DR
1set rear shock absorber	614.00	x nn
	\$ 17,507.95	
Less 20%	3,501.59	
	\$ 14,006.36	
1pce rear number plate with cover	100.00	x nn
To remove/refit rear windscreen	140.00	120
To rustproof	200.00	100.
To dismantle/renew exhaust pipe	100.00	80.
To check wiring	50.00	30.
To computer reset	150.00	100.
To remove/refit rear interior to effect repair	100.00	60.
To dismantle/refit rear undercarriage	120.00	x nn
To remove/refit rear boot lid top spoiler	100.00	40.
To dismantle/renew reverse sensors	100.00	30.
To dismantle/renew rear exhaust pipe	100.00	nn x Repeated.
To dismantle/renew accident portion	2,000.00	1400
To spray paint	2,000.00	1200.
Total	\$ 19,266.36	1