

CH MOTOR REPAIRS AND SERVICES

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #05-19
Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

ROC No: 53030817K

Email: chmotorrank@gmail.com

M/s AXA Insurance Singapore Pte Ltd

No 8 Shenton Way #27-02 AXA Tower

S068811 Tel 63387288 Fax 68804838

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurer

DATE: 27.12.2018

CAR NO: SJX 1334 X

MAKE: Honda Fit

Acknowledged by Repairer

Signature:

Date:

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.

YOUR INSURED : SJR 5441 P

Pc	Pcs	Description	UNIT PRICE	AMOUNT	
1	pc	Tail gate <i>Dented</i>		\$771.50	✓
1	pc	Tailgate "FIT" emblem <i>ble NF</i>		\$25.20	✓
1	pc	Tailgate outer garnish <i>MM</i>		\$114.60	✓
1	pc	Tailgate upper lock <i>SLC</i>		\$186.20	✓
1	pc	Tailgate lock striker <i>SLC</i>		\$25.70	✓
1	pc	Tailgate "H" logo <i>ble NF</i>		\$23.10	✓
1	pc	Rear wind screen upper moulding <i>MC</i>		\$32.00	✓
1	pc	Rear wind screen lower moulding <i>MC</i>		\$42.00	✓
1	pc	Tail end panel <i>Dented</i>		\$276.50	✓
1	pc	Tail end panel inner lining <i>monthly reform</i>		\$60.80	✓
1	pc	Rear bumper face <i>distorted</i>		\$497.40	✓
10	pcs	Rear bumper clip <i>MC</i>	\$3.70	\$37.00	✓
2	pcs	Rear bumper side retainer <i>SLC</i>	\$12.70	\$25.40	✓
1	pc	Rear bumper tow cover <i>distorted</i>		\$22.00	✓
1	set	Reverse sensor set <i>Dem</i>		\$300.00	220✓
1	pc	Right Side tail lamp <i>crack MC</i>		\$206.20	✓
		To spray anti-rust coating on new and affected panels.		\$200.00	40✓
		Straightening, repairing and realigning onto rear left/right side mudguard, cutting rear end panel, dismantle & replace the above mentioned parts		\$1,000.00	600✓
		To spray painting on rear boot lid cover, rear end panel, rear bumper & rear left/right side mudguard.		\$1,200.00	600✓
		To apply silicon onto rear wind screen.		\$60.00	40✓
		To dismantle & refix rear wind screen.		\$160.00	120✓
				\$5,059.40	

List 20% discount.

[Signature]

CH MOTOR REPAIRS AND SERVICES

31/12/2018 @ 1000hrs

NA Annual

2/Small 4 days.

Photo after repair. *[Signature]* 2kk Auto