

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWERS
 SINGAPORE 189702

Registration No : SKQ3682S
 Chassis No : JHMGK5850FX201561
 Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)
 Owner's Name : CHANG TOU EN KENNETH
 Ins Policy No. :
 Date of Accident : 2/1/2019

Document No. : SQT19000035
 Date : 3. Jan 2019
 Customer No. : WZL009
 Svc Advisor : RUEBEN THOMAS
 Engine No : L15B31000129
 Date | Time : 3. Jan 2019 8:34:45 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHANG TOU EN KENNETH OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 02/01/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC INSURANCE BHD TP VEH: GBB8624M						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5B-Z50ZZ	TAILGATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE	1	78.90	25	59.17	4.14	63.31
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
34155-T5A-J01	LIGHT ASSYL.LID	1	81.70	25	61.27	4.29	65.56
34150-T5A-J01	LIGHT ASSYR.LID	1	81.70	25	61.27	4.29	65.56
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	25	167.92	11.75	179.67
33500-T5A-J02	TAILLIGHT ASSY.R.	1	223.90	25	167.92	11.75	179.67
66100-TAR-T10ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
04646-TAS-300ZZ	PANEL SETL.RR.OUTSIDE	1	570.50	25	427.87	29.95	457.82
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17	48.47
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.58
84521-T5A-901ZA	LID ASSYSPARE TIRE	1	189.80	25	142.35	9.96	152.31
84550-T5S-M10	BOX ASSYCARGO FLOOR	1	107.00	25	80.25	5.62	85.87
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	53.70	25	40.27	2.82	43.09



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702
Registration No : SKQ3682S
Chassis No : JHMGK5850FX201561
Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)
Owner's Name : CHANG TOU EN KENNETH
Ins Policy No. :
Date of Accident : 2/1/2019

Document No. : SQT19000035 Page 2
Date : 3. Jan 2019
Customer No. : WZL009
Svc Advisor : RUEBEN THOMAS
Engine No : L15B31000129
Date | Time : 3. Jan 2019 8:34:45 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84640-T5A-003ZA	LINING ASSYRR.PANEL <i>Repld</i>	1	60.80	25	✓ 45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL.TRUNK <i>Repld</i>	1	169.00	25	✓ 126.75	8.87	135.62
84601-TAR-Z02ZA	LINING ASSYR.TRUNK <i>Repld</i>	1	169.00	25	✓ 126.75	8.87	135.62
04715-T5B-000ZZ	FACERR.BUMPER <i>Repld</i>	1	502.50	25	✓ 376.87	26.38	403.25
71598-T5A-000	SPACERL.RR.BUMPER <i>2</i>	1	11.50	25	✓ 8.62	0.60	9.22
71593-T5A-000	SPACERR.RR.BUMPER <i>per</i>	1	11.50	25	✓ 8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	5	2.30	25	✓ 8.62	0.60	9.22
71507-T5A-000	GARNISHL.RR.BUMPER <i>at</i>	1	14.30	25	✓ 10.72	0.75	11.47
71502-T5A-000	GARNISHR.RR.BUMPER <i>new</i>	1	14.30	25	* 10.72	0.75	11.47
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>Repld</i>	1	320.00		✓ 320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>new</i>	1	45.00		+ 45.00	3.15	48.15
Sum Item					3347.81	234.32	3,582.13

BOSUN	SUNDRIES	1	50.00		<i>20</i> 50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		<i>80</i> 100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		✓ 130.00	9.10	139.10
BOJSE	BODY JOINT SEALANT.	1	100.00		<i>80</i> 100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		✓ 100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		<i>180</i> 250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		✓ 300.00	21.00	321.00
BOMISC1	RESET VEHICLE SMART ENTRY SYSTEM (N)	1	320.00		<i>280</i> 320.00	22.40	342.40
BOMISC1	REMOVE, INSTALL & ADJUST REAR VIEW CAMERA (N)	1	320.00		<i>280</i> 320.00	22.40	342.40
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00		<i>180</i> 350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		✓ 450.00	31.50	481.50
BOMISC1	PULL & ALIGN L REAR CHASSIS	1	600.00		<i>380</i> 600.00	42.00	642.00
BKRP21M	CUT OFF & RENEW RR PANEL, RR L FENDER. STRAIGHTEN	1	4500.00		<i>2520</i> 4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00		<i>2700</i> 2800.00	196.00	2996.00
Sum Labor					10370.00	725.90	11,095.90

Printed on 3/1/2019 11:18:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT19000035	Page	3
	100 BEACH ROAD	Date	: 3. Jan 2019		
	#19-00 SHAW TOWERS	Customer No.	: WZL009		
	SINGAPORE 189702	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SKQ3682S	Engine No	: L15B31000129		
Chassis No	: JHMGK5850FX201561	Date Time	: 3. Jan 2019 8:34:45 AM		
Model	: JAZZ 1.5VTIR CVT 15YM (EURO 4)	Surveyor Name	:		
Owner's Name	: CHANG TOU EN KENNETH	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 2/1/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	Adrian Lim						
Date & Time	04/01/19						
Excess							
Status	Not Authorised.						
Signature	[Signature]						
					Total Amount	13,717.81	960.22
					Total (Inclusive of GST)		14,678.03

Printed on 3/1/2019 11:18:43 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)