

ASS. REC. BY:

REF:

TM1/ CC3/TM19000204/KHbnz

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/1

File pass to Corning

LLP 89000 Cred. 17/12/18 (66%)

SHD 9717R - CC3/AXA 17016382/KUL652

SHH 8548A - X

DA: 31/12/2017

4/1 @ 1:33pm Email to Tokio estimate and GIA Report.

RECEIVED 02 APR 2019

Date/Time, File Pass to?

1) 1/4 Typist

Date/Time, File Return to?

2)

☐ : Prell. Report☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Fees:

Others:

TOTAL

250

10

260

Report Format:

Lump Sum / I.B.I. (\$

TP

90007

Kenneth Kong (LKKAUTO)

From: weichunkong <weichunkong@transcab.com.sg>
Sent: Thursday, 3 January, 2019 3:59 PM
To: 'Candy Kong'
Cc: Kenneth Kong (LKKAUTO)
Subject: RE: BOOK VALUE SHD9717R DOA 31.12.2018

Hi all,

SHD9717R Net book value is \$43,616.56

Thanks
Best regards

CK



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Candy Kong [<mailto:candy.kong@transcab.com.sg>]
Sent: Thursday, 3 January, 2019 2:14 PM
To: 'weichunkong' <weichunkong@transcab.com.sg>
Cc: 'Kenneth Kong (LKKAUTO)' <KennethKong@lkkauto.com>
Subject: BOOK VALUE SHD9717R DOA 31.12.2018

Hi ck

Pls provide book value.

Thks & Rdgs
Candy Kong
Claims Service Assistant



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 4 January 2019 1:33 PM
To: 'Motor Claims'
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 31/12/2018 , SHD 9717R (TP Vehicle), SLH 8548A (OI Vehicle)
Attachments: ESTIMATE OF SHD 9717R.pdf; GIA REPORT SHD 9717B.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9717R at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 3/1/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 11:02
Date Of Accident	31/12/2018 21:35
Exact Location Of Accident	SERANGOON NORTH AVENUE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9717R
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LIEW YOOT HOO
NRIC No	S2504419C
Date Of Birth	06/02/1952
Occupation	OUTDOOR
Date Of Driving Pass	02/08/1982
Driving Experience	36 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97366735
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 695 JURONG WEST CENTRAL 1 #02-33
Postcode	640695
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 31.12.2018 at about 2135 hours, I was travelling straight along Serangoon North Avenue 1 on the extreme left lane. Suddenly I felt an impact. Vehicle B (SLH8548A) hit on my taxi rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH8548A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM YIAK TIAM
NRIC/Passport Number	
Contact Number	98624495
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

A: SHD 9717R
B: SLH 8548A
Serangwan North Avenue 1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see the attach G/A report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD9717R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000751
Chassis No.:	VF1ABL15AUC276054
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	04 Dec 2013
First Registration Date:	04 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2021
PARF Rebate Amount:	\$8,748.00
Intended COE Rebate Details	
COE Expiry Date:	03 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$22,895.00
Total Rebate Amount:	\$31,643.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Jan 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9717R**AAD1901-009***Not Authorized
C1 Sing @ 9000h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9717R

VF1ABL15AUC276054

RENAULT

LATITUDE

31.12.2018

TOKIO

4/12/2013

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPER BRACKET SIDE RH REAR
- 5 1 BUMPER RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPER BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

- | | | | |
|----|---------------|----------|-------------------------|
| \$ | <i>Bu</i> | 1,108.46 | ✓ |
| \$ | <i>Not in</i> | 768.84 | ✓ |
| \$ | <i>DI</i> | 113.47 | ✓ |
| \$ | <i>Sn</i> | 135.97 | X |
| \$ | <i>Sn</i> | 44.99 | X |
| \$ | <i>Sn</i> | 43.61 | X |
| \$ | <i>DI</i> | 135.97 | ✓ |
| \$ | <i>Sn</i> | 44.99 | X |
| \$ | <i>Sn</i> | 43.61 | X |
| \$ | <i>Bz</i> | 777.52 | ✓ |
| \$ | <i>Bz</i> | 225.95 | ✓ |
| \$ | <i>R</i> | 225.95 | X |
| \$ | <i>Bz</i> | 2,872.68 | ✓ |
| \$ | <i>Sn</i> | 470.06 | X |
| \$ | <i>DI/IN</i> | 323.05 | <i>50% in 161.52 in</i> |
| \$ | <i>CM</i> | 493.35 | ✓ |
| \$ | <i>Sn</i> | 493.35 | X |
| \$ | <i>na</i> | 225.36 | ✓ |
| \$ | <i>na</i> | 225.36 | ✓ |
| \$ | <i>Sn</i> | 276.08 | } X |
| \$ | <i>Sn</i> | 276.08 | |
| \$ | <i>R</i> | 367.84 | |
| \$ | <i>R</i> | 367.84 | |
| \$ | <i>Sn</i> | 586.45 | |
| \$ | <i>Sn</i> | 168.13 | |
| \$ | <i>R</i> | 202.67 | |
| \$ | <i>R</i> | 74.40 | |
| \$ | <i>Sn</i> | 50.52 | |
| \$ | <i>Sn</i> | 221.81 | |

Trans-cab Auto Services Pte Ltd**AAD1901-009**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9717R

30	1 TAILLAMP LH	\$	CM 552.55	✓
31	1 TAILLAMP PANEL LH	\$	R 986.70	X
32	1 TAILLAMP RH	\$	Sn 552.55	X
33	1 TAILLAMP PANEL RH	\$	R 986.70	X
34	1 OUTER PANEL REAR (End Panel)	\$	B 1,471.77	✓
35	1 OUTER PANEL REAR (End Panel)TRIM	\$	nd 404.56	✓
36	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88	X
37	1 SPARE WHEEL PANEL TRIM	\$	Sn 612.21	X

TOTAL	\$	19,121.29
10%	\$	1,912.13
	\$	17,209.16

Specical Nett

1	1SET PARKING AID	\$	Short 700.00	Goosa
2	1SET REAR BUMPER CLIP	\$	na 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn 17.82	X
11	1SET BOOT FINISHER CLIP	\$	na 24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na 30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na 45.00	X
15	1 TAILLAMP CLIP RH	\$	na 5.00	X
16	1 TAILLAMP CLIP LH	\$	na 5.00	✓
17	2 REAR WINDSCREEN SELANT	\$	na 80.00	X
18	1 WINDSCREEN MOULDING	\$	na 100.00	X
19	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00	X

TOTAL	\$	1,384.02
--------------	-----------	-----------------

TOTAL PARTS	\$	18,593.18
--------------------	-----------	------------------

Trans-cab Auto Services Pte Ltd**AAD1901-009**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9717R**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	7001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

LKK Auto Consultants hereby certify that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 7,960.00**Over All Total \$ 26,553.18****(Lump Sum) Repair Days****10 Days****5 days**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19000204/KTBN2

Date: 04/04/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MV010873
Claimant Vehicle No :	SHD9717R	Insured Vehicle No :	SLH8548A
Date of Loss:	31/12/2018	Nature of Claim:	TP
		Claim No:	M1900025

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9717R	Engine No:	M9R8839C000751
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276054
Reg. Date:	04/12/2013 (Man. Year: 2013)	Odometer:	793257 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,593.18	9,429.78	9,163.40	49.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,960.00	1,820.00	6,140.00	77.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,553.18	11,249.78	15,303.40	57.63
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	26,553.18	9,000.00	17,553.18	66.11
+ GST 7.00/7.00% (S\$)	1,858.72	630.00	1,228.72	66.11
Nett Amount (S\$)	28,411.90	9,630.00	18,781.90	66.11

INSPECTION

Date of Assignment:	04/01/2019	
Date Inspected:	03/01/2019	Inspected At:
		Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9717R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CRT REAR	Distorted	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*-FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*-FL
7	1		*BUMPER BRACKET SIDE LH REAR	Distorted	135.97 FL	*135.97 FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*-FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*-FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*-FL
15	1		*BOOT REFLECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
16	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*-FL
17	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
18	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT STRUT LH	Serviceable	276.08 FL	*-FL
20	1		*BOOT STRUT RH	Serviceable	276.08 FL	*-FL
21	1		*BOOT HINGE LH	Repair	367.84 FL	*-FL
22	1		*BOOT HINGE RH	Repair	367.84 FL	*-FL
23	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*-FL
24	1		*BOOT SWITCH	Serviceable	168.13 FL	*-FL
25	1		*BOOT LOCK	Repair	202.67 FL	*-FL
26	1		*BOOT LOCK CATCH	Repair	74.40 FL	*-FL
27	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*-FL
28	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*-FL
29	1		*TAILLAMP LH	Cracked	552.55 FL	*552.55 FL
30	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*-FL
31	1		*TAILLAMP RH	Serviceable	552.55 FL	*-FL
32	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*-FL
33	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
34	1		*OUTER PANEL REAR (END PANEL) TRIM	Dented	404.56 FL	*404.56 FL
35	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*-FL
36	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*-FL
37	1		*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
38	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
39	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
40	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
41	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
42	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
44	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
45	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
46	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
47	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
48	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
49	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
50	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
51	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
52	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
53	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
54	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
55	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
56	1		*BOOT WEATHERSTRIP (50%)	Distorted/Dented	290.75 FS	*161.52 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,473.00	10,367.36
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,879.82	937.58
Total Parts (\$\$)	18,593.18	9,429.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	880.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	700.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			7,960.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >