



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMRC1890EC202147
License No: SDW1663L
Mileage: 112410
Engine No: K24W71001119

Document No: SVO19003125
Printed By: JACKNG
Order Date: 14. January 2019
Order Time: 11:43:19 AM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:NG KOK HWA OWNER INSURER:UOI ACC DATE:02/01/2019 SURVEYED BY: DATE: REF NO: TP INSURER:MS FIRST CAPITAL TP VEH:SHA 7858 X						
04711-T6A-900ZZ	FACE,FR.BUMPER	1	700.00	25	525.00	36.75	561.75
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.80	25	8.85	0.62	9.47
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.80	25	8.85	0.62	9.47
91505-TM8-003	CLIP,BUMPER	22	2.30	25	37.95	2.66	40.61
60260-T6A-300ZZ	FENDER COMPL.FR.	1	548.60	25	411.45	28.80	440.25
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J	1	915.00	25	686.25	48.04	734.29
51215-T6A-000	KNUCKLE COMPL.FR. A bt ✓	1	298.40	25	223.80	15.67	239.47
51360-T6A-J00	ARM ASSYL.FR.LOWER A bt ✓	1	636.30	25	477.22	33.41	510.63
44300-T6A-J51	BEARING ASSYFR.HUB A bt ✓	1	138.20	25	103.65	7.26	110.91
44600-T0B-A00	HUB ASSYFR. A bt ✓	1	187.20	25	140.40	9.83	150.23
51621-T6A-J01	ABSORBER UNITL.FR.SHOCK A bt ✓	1	318.70	25	239.02	16.73	255.75
51920-T6A-J01	TOP FR.MOUNTING A bt ✓	1	69.50	25	52.12	3.65	55.77
	SUM PARTS:				2,914.56	204.04	3,118.60
BOSUN	1610 SUNDRIES	1	50.00		50.00	3.50	53.50
BOJSE	1610 BODY JOINT SEALANT FOR LHS FRONT FENDER	1	120.00		120.00	8.40	128.40
BML011	1610 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	280.00		280.00	19.60	299.60
BOMISC1	0671 REMOVE & INSTALL FRONT VIEW CAMERA(N)	1	450.00		450.00	31.50	481.50
BKFE11R	0671 REMOVE & RENEW FR L FENDER.RENEW ALL DAMAGE ITEMS.	1	1,400.00		1,400.00	98.00	1,498.00
BP05R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	900.00		900.00	63.00	963.00
BOMISC1	0671 REMOVE & RENEW FRONT LHS ABSORBER & ALL DAMAGE	1	560.00		560.00	39.20	599.20
	SUM LABOUR:				3,760.00	263.20	4,023.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	SUM EXT SERVICE:				180.00	12.60	192.60
	TOTAL SGD				6,854.56	479.84	7,334.40
	Total Payable (SGD)						7,334.40