

Taylor

REF: NS/INC19000218/TI vber

INSURANCE

From: Date: 3/1/19

Estimated Cost

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SHB 609P

at Workshop no: SMRT woodlands Depot

Incurrd: SLE 2953D

Policy No: 5090188949-01 090518-080519

Claims No: MT/1026215-002

Sum Insured Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No


GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted: Vehicle: IN / OUT



Vehicle: SHB 609P. Reg No: 2014 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Prime Mover /

Truck / Trailer or

Make: Nyske Primus cc 1798

Colour: Maroon A/C Insured / Std / NI / NA

Sp. Reading: 629438. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: STDKN 364603749684

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/65R15
R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	3/1/19 @ 4:30 pm

Survey held at: SMRT WL

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
01/19/2013	SHB 609P - NS/TI/INC 22037 / T/vber SIC 2953D - x

01/19 LS \$ 900 confirmed by email (Ref: 1535.60, 637)

RECEIVED 2 2013

Date/Time, File Pass to? : Prel. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee: 160

Transportation

Site Insp (\$)

Interview (\$)

Tech. Inva (\$)

Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$) 900f

160

Hello, NAC_PAYA_UBI_800601

Change Language Change Password Log Out

My Desktop
Notice of Loss

Policy Query

Policy No.	<input type="text"/>	Date of Accident	02/01/2019 14:14
Vehicle No.(For Motor)	SLC2953D	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="checkbox"/>	5090188949-01		NGUYEN THI LIEN HUONG	S7279558Z	GPC	drive CLASSIC	SLC2953D	SLC2953D	09/05/2018	08/05/2019

Veron Chen (LKKAuto)

From: mtreg <mtreg@income.com.sg>
Sent: Tuesday, 22 January 2019 4:01 PM
To: Veron Chen (LKKAuto)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi,

Claim created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, January 22, 2019 2:38 PM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Please provide us the claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/1026215-002	SMRT TAXIS PTE LTD	SHB 609P	SLC 2953I

D.O.A	Time of Accident	Estimate	Tentative repair cost
2/1/2019	7:40	\$2,435.60	\$900.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHB609P
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1412102
Chassis No.:	JTDKN36U605749684
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	17 Sep 2014
First Registration Date:	17 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Sep 2022
PARF Rebate Amount:	\$6,066.00

Intended COE Rebate Details

COE Expiry Date:	16 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$23,397.00
Total Rebate Amount:	\$29,463.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Jan 2019

OK

Case Details

Case Reference Number : TAX/01/19/2013

Type of Repair : Accident Repair

Vehicle Registration Number : SHB609P

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-5173-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 01/01/2019 11:40 PM

Vehicle Age(In Months) : 52

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	de	Replace
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	AD	Replace
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	AD	Replace
One Time Key in	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	?	Check
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	?	Check
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	?	Check
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	AD	Replace
Total Spare Part Cost									1,019.70			Surveyor Total	858.03	
Lump Sum Discount (%)									20.00			Lump Sum Dis (%)	20	
Final Spare Part Cost									815.76			Final Sur Total	524.82	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		338.00	200.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
2	TO REPLACE SUNDRY PARTS	100.00	20	
3	TO WASH AND VACUUM	60.00	0	
Total:		280.00	50.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	815.76	524.82
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	280.00	50.00
Overall Total	1,991.76	974.82
Lump Sum Repair Option		✓
Lump Sum Total	2,000.00	950.00
Surveyor Approved Amount		950.00
No of Repair Days*	3	2
Remarks	-	Resurvey after repair
Surveyor Name		Taufikh

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature

Save Clear

Survey Date

03/01/2019



Handwritten notes:
 3/1/19
 Being after repair
 see 11kants um
 02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section A - Accident Details	
Registration Number	SHB609P
Case Reference Number	TAX01/19/2013
Registration Date	17/09/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHENG YEOW WAH
Type of Accident	Head to Rear
Accident Date and Time	02/01/2019 7:40 AM
Accident Reported Date and Time	02/01/2019 3:11 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099498
Special Instruction to ARC, if any	TP
Prepared Date and Time	02/01/2019 9:40 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Page 2 of 2

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$1,019.70	\$656.03
Total Other Cost	\$280.00	(\$156.03)
TOTAL COST	\$2,195.70	\$900.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Kim Ming Chin	Taufikh (LKK) / NTUC
ARC / Surveyor Sign Off Date	03/01/2019 5:52 PM	03/01/2019 5:48 PM
Signature		
Remarks	Resurvey after repair	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 15:33
Date Of Accident	02/01/2019 07:40
Exact Location Of Accident	SLIP ROAD FROM BKE TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB609P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
Driver	
Name of Driver	CHENG YEOW WAH
NRIC No	S7246840F
Date Of Birth	17/12/1972
Occupation	OUTDOOR
Date Of Driving Pass	27/08/1993
Driving Experience	25 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : THIRU
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD FROM BKE TOWARDS PIE WITH ONE PASSENGER (MALE INDIAN) ON BOARD AS I WAS LOOKING OUT FOR THE ONCOMING TRAFFIC. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SLC2953D HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLC2953D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LIM CHEN CHIN
 NRIC/Passport Number S1773488A
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Handwritten Signature]
02/11/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten Signature]
2/11/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 49 Woodlands Industrial Park #4, Singapore 757708
 FAX Number : 63445582
 Estimator Telephone Number : 64562629
 Accident Reporting Number : 06552672

Date Generated : 18/01/2019
 User ID : hmlmlegchv

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1901-0309	Invoice Number	
Quotation Date	14.01.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	\$376.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$206.03)
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$280.00	(\$156.03)

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47905	BUMPER REAR	1.00	\$458.80	25.00	\$343.95	Replace	Replace	de
		52161-16010	BUMPER CLIPS	10.00	\$1.61	16.10	\$12.08	Replace	Replace	nc
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	nc
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X nn
		52018-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X nn
		52015-47050	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X nn
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	nc
Total					\$1,185.11		\$666.03			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

656.03
 + 200.00
 + 250.00

 1106.03
 - 202

 0904.83

4/5 \$900/-
 2535.60

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 22 January 2019 2:31 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Taufikh (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB609P

Dear Poh Suan,

WITHOUT PREJUDICE

Confirmed Lump Sum \$900 @ 2 working days.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 22 January 2019 10:40 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB609P

Hi Taufikh,

Attached herewith the repair estimate of SHB 609P having Case No: TAX/01/19/2013.

There is no change to the approved amount of \$900 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Sent: Monday, 21 January 2019 11:08 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC19000218/T1vbe2
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 23-01-2019
		Code: INC4



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 2953D	Veh. Inspected	SHB 609P
Policy No.	5090188949-01	Coverage (\$)	0.00
Claim No.	MT/1026215-002	Excess (\$)	0.00
Assign From		Assign Date	03/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U605749684	Colour	MAROON
Odometer	629438	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/01/2019	Inspection Date	03/01/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 609P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	DEFORMED	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	NOT WORKING	180.00	180.00
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
			1,259.60	656.03
LABOUR				
PANEL BEATING & BODY WORK.			338.00	200.00
SPRAY PAINT.			558.00	200.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM.			120.00	30.00
TO REPLACE SUNDRY PARTS.			100.00	20.00
TO WASH AND VACUUM.		NOT NECESSARY	60.00	-
			1,176.00	450.00
GRAND TOTAL			2,435.60	1,106.03

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			900.00
---	--	--	---------------

Report Ref No. NS/INC19000218/T1vbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.