

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 15 Jan 2019

Preliminary Advice

Insured Vehicle No	: SLB2797T		
TP Vehicle No	: SH9483M	Accident Date	: 03/01/2019
Make	: HYUNDAI I40	Assignment Date	: 04/01/2019
Date of Inspection	: 07/01/2019	Est. Duration of Repair	: 7 days
Inspection At	: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front & front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,497.88
Revised Amount	:S\$	5,460.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,460.88
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.