

SERVICE ESTIMATE

73986 - C00001
 Ms Ho Ho Colette
 50 Holland Road
 #04-09

SL: SERVICE SALES - PC

Singapore 258853

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Ms Ho Colette

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 03/01/2019
 WIP No. . : 46166
 Veh.In/Out:
 *Tel.No. . : Mobile: 98255879
 Reg.No. . : SKJ6469J
 Reg.date . : 26/04/2013
 Mileage .. : 0
 Chassis No: YV1CZ2457D1662504

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, FRT LH FENDER, HEADLAMP, FRT BUMPER GRILLE, WIDENER, LHF WHEELARCH, REPAIR BONNET, ETC	0	3200.00	0		3,200.00	S
-----	---	---	---------	---	--	----------	---

800	TO PUTTY SPRAYPAINT ON FRT BUMPER, FRT LH FENDER, BONNET, ETC	0	2800.00	0		2,800.00	S
-----	---	---	---------	---	--	----------	---

280	TO FOCUS HEADLAMP	0	150.00	0		150.00	S ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S ✓

BUMPER COVER FRT XC9	1.0 EA	1698.00			1,698.00	S de✓
BUMPER FOAM FRT XC90	1.0 EA	216.90			216.90	S ?
BUMPER REINFORCEMENT	1.0 EA	325.70			325.70	S ?
BUMPER MOULDING LHF	1.0 EA	347.50			347.50	S de✓
BUMPER GRILLE LHF XC	1.0 EA	54.30			54.30	S mis✓

Tanpin 97495749
 WP
 22/11/19 2/130
 04 days
 Resurvey before paint.
 840 R 1kkauto.com

**LKK Auto Consultants hence notify
 the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4930 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

73986 - C00001
 Ms Ho Ho Colette
 50 Holland Road
 #04-09

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 03/01/2019

WIP No. : 46166

Veh.In/Out:

*Tel.No. : Mobile: 98255879

Reg.No. : SKJ6469J

Reg.date. : 26/04/2013

Mileage : 0

Chassis No: YV1CZ2457D1662504

Singapore 258853

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Ms Ho Colette

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BUMPER BRACKET LHF X	1.0 EA	88.70			88.70 S	new ✓
	BUMPER BRACKET RH F X	1.0 EA	88.70			88.70 S	x
	FENDER WINDENER FRT	1.0 EA	142.90			142.90 S	de ✓
	FENDER FRT LH XC90 -	1.0 EA	1456.70			1,456.70 S	bt ✓
	FENDER BRACKET FRT L	1.0 EA	138.10			138.10 S	new ✓
	WHEELARCH LHF XC90	1.0 EA	198.30			198.30 S	cut ✓
	WHEELARCH PLASTIC NU	10.0 EA	6.10			61.00 S	new ✓
	FRAME PANEL FRT XC90	1.0 EA	1585.90			1,585.90 S	?
	BUMPER RAIL (BEAM) F	1.0 EA	1390.60			1,390.60 S	?
	BLIND RIVET 4.0*21 P	10.0 EA	3.00			30.00 S	na ✓
	BUMPER CLIP 8x8,5	10.0 EA	5.40			54.00 S	new ✓
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40 S	?
	V009437654/*D* VOLVO	2.0 EA	40.50			81.00 S	?
	D AUTO TRANS OIL 4	1.0 EA	232.70			232.70 S	?

Gross Total. 14,874.40

Labour Total 6,600.00
 Parts Total 8,274.40
 Package Total 0.00

Net..... 14,874.40
 GST @ 7.0% 1,041.21
 Total..... 15,915.60
 Paid..... 0.00
 Please Pay.. 15,915.60

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated